Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

CIZ	
Θ	

Form C-103 Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

OIL CONSERVATION DIVISION

2040 Pacheco St. Santa Fe, NM 87505

WELL API NO.			
30-015-32281			
Indicate Type of Lease			
	STATE X	FEE;	
State Oil & Gas Lease N	0		

1000 Rio Brazos Rd., A	ztec, NM 87410				VB - 0520	Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			Lanca Nama ar	Unit Agreement Nam	•		
(DO NOT USE TH	OIFFERENT RESERVOIR. U	JSE "APPLICATION R SUCH PROPOSA				Unit Agreement Nam 4 State	e
Type of Well: OIL WELL X	GAS	OTHER	ALS.)				
₂Name of Operator Poqo Pro	oducing Company	, 			₃Well No.		<u></u> .
3Address of Operate	or				₃Pool name or W		
P. O. Bo	ox 10340, Midland	<u>, TX 79702-</u>	<u> 7340 </u>		<u> Sand Dun</u>	<u>es Delaware</u>	South
₄Well Location Unit Letter	0 <u>660</u> Feet Fro			nd1980	Feet From 1	_{The} East	Line
Section	4 Tov	vnship 24S	Range	31E	NMPM	Eddy	County
		₁₀Elevation (Show w 3414 'GR	hether DF, RKB, RT,	GR, etc.)			
11	Check Appropri	ate Box to Ind	icate Nature o	f Notice, Rep	port, or Othe	er Data	

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	7 1	PLUG AND ABANDON		REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILLING OPNS.	X	PLUG AND ANBANDONMENT
PULL OR ALTER CASING	f i			CASING TEST AND CEMENT JOB		
OTHER:				OTHER:		

12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spud & Set Surface Csg - MIRU TMBR/Sharp #23. Spud well @ 18:00 hrs 05/29/02. Drld 14-3/4" hole to 615'. TD reached @ 09:30 hrs 05/30/02. Ran 13 jts 10-3/4" 32.75# J-55 ST&C csg. TPGS @ 615'. BJ cmt'd w/ 425 sks 65:35 POZ "C" @ 12.8 ppg followed by 150 sks CI "C" + 2% CaCl2 @ 14.8 ppg. Circ 200 sks to surface. Plug down @ 15:00 hrs 05/30/02. WOC 30 hrs. Make cut-off. Weld on WH. NU BOP's & test to 1000# ok.

Intermediate Csg - Drld 9-7/8" hole to 4212'. TD reached @ 09:00 hrs 06/04/02. Ran 95 jts 7-5/8" 26.40# J-55 LT&C & ST&C csg. Cmt'd w/ 750 sks 65:35 POZ @ 12.4 ppg followed by 150 sks CL 'C" + 1% CaCl2 @ 14.8 ppg. Circ 177 sks to surface. WOC 40 hrs. Make cut-off. Install WH. NU BOP & test.

TD & Production Csg - Drld 6-3/4" hole to 8300. TD reached @ 23:30 hrs 06/11/02. Logged well w/ Baker Atlas. Ran 194 jts 4-1/2" 11.60# L-80 & J-55 LT&C csg. BJ cmt'd the 1st stage w/ 475 sks Cl "H" + .3% FL52 + .3% CD32 + .15% SMS + .1% R3 @ 15.7 ppg. Plug down @ 14:00 hrs 06/13/02. Circ 100 sks to surface. Cmt'd 2^{nd} stage w/ 440 sks Cl "C" + .15% FL52 + .75% CD32 @ 14.09 ppg. Plug down @ 19:45 hrs 06/13/02. CBL ran 06/22/02. TOC @ 4850'.

I hereby certify that the information above is true and complete to the best of my known	vledge and belief.	
	TITLE Sr. Operation Tech	DATE 07/08/02
TYPE OR PRINT NAME Cathy Tomberlin	(915)685-8100	TELEPHONE NO.
(This space for State Use)		
APPROVED BY	тпте	DATE
CONDITIONS OF APPROVAL, IF ANY:		