

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other ☐
2. NAME OF OPERATOR
Estoril Producing Corporation
3. ADDRESS OF OPERATOR
11th Floor, Vaughn Bldg., Midland, TX 79701
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FNL & 660' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☒
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☐


5. LEASE
NM 33659
6. IF INDIAN, ALLOTTEE OR **RECEIVED**
7. UNIT AGREEMENT NAME
NOV 12 1982
8. FARM OR LEASE NAME
Hoffman Federal O.C.D.
9. WELL NO.
2
10. FIELD OR WILDCAT NAME
Wildcat-Abo
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 11, T4S, R23E
12. COUNTY OR PARISH
Chaves
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Abandon location.

no drilling or dirt work was done.



OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWEIL, NEW MEXICO

*Post ID-2
11-12-82
Aband. loc.*

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *Pat Richardson* TITLE Production Clerk DATE 8-6-82

(This space for Federal or State office use)

APPROVED BY (Orig. Sgd.) GEORGE H. STEWART DATE _____
CONDITIONS OF APPROVAL, IF ANY: