

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 7708
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-79

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

FEB 26 1979

O.C.C.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name
Clark Land & Development Company

9. Well No.

1

10. Field and Pool, or Wildcat

Wildcat

11. Elevation (Show whether DF, RT, GR, etc.)

2949.5 GR

12. County

Kddy

13. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☒

CHANGE PLANS ☐

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Casing hole 10 3/4" - 306 - Circ.

7" - 1596 to be plugged.

Well to be plugged for abandonment as follows:

25 sacks at total depth, 3620

25 sacks 2500-2600 to cover top La Mar @ 2620

25 sacks 1750 to 1850 to isolate Salt section 1890 to 2430

35 sacks 1525 to 1625 to cover sulphur water seep at 1576

40 sacks 250 to 350 across casing shoe at 306

10 sacks at surface with regulation marker

Mud between all plugs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Norma H. H.* TITLE **Agent** DATE **2/24/79**

APPROVED BY *W. A. Gussitt* TITLE **SUPERVISOR, DISTRICT II** DATE **FEB 27 1979**

CONDITIONS OF APPROVAL, IF ANY: