# EXHIBIT #1

# MINIMUM BLOWOUT PREVENTL ... ¿QUIREMENTS

# 3,000 ps! Working Pressure

3 MWP

#### STACK REQUIREMENTS

•.

No.	Nem		Min. LD.	Min. Nominal
1	Flowline			
2	Fill up line		1	2*
3	Drilling nipple		1	
4	Annular preventer			
5	Two single or one dual hydraulically operated rams			
64	Drilling spool with 2° min. Id 3° min choke line outlets	Il line and		
<b>6</b> b	2" min. kill line and 3" min. choke line outlets in ram. (Alternate to 6a above.)			
7	Valve	Gale D Plug D	3-1/8*	
8	Gate valve—power operated		3-1/8"	
9	Line to choke manifold			3.
10	Valves	Gale D Plug D	2-1/16*	
11	Check valve		2-1/16*	
12	Casing head			
13	Valve	Gate D Plug D	1-13/16*	
14	Pressure gauge with needle	valve		
15	Kill line to rig mud pump mer	niloid	i i	2*



OPTIONAL					
16	Flanged valve	1-13/16*			

## CONTRACTOR'S OPTION TO FURNISH:

- 1.All equipment and connections above bradenhead or casinghead. Working pressure of preventers to be 3,000 psl, minimum.
- 2.Automatic accumulator (20 gallon, minimum) capable of closing BOP in 30 seconds or less and, holding them closed against full rated working pressure.
- 3.BOP controls, to be located near drillers position.
- 4.Kelly equipped with Kelly cock.
- 5.Inside blowout prevventer or its equivalent on derrick floor at all times with proper threads to fit pipe being used.
- 6.Kelly saver-sub equipped with rubber casing protector at all times.
- 7.Plug type blowout preventer tester.
- S.Extra set pipe rams to fit drill pipe in use on location at all times.
- 9. Type RX ring gaskets in place of Type R.

## MEC TO FURNISH:

- 1.Bradenhead or casinghead and side valves.
- 2.Wear bushing, il required.

## **GENERAL NOTES:**

- 1. Deviations from this drawing may be made only with the express permission of MEC's Drilling Manager.
- 2. All connections, valves, fittings, piping, etc., subject to well or pump pressure must be flanged (suitable clamp connections acceptable) and have minimum working pressure equal to rated working pressure of preventers up through chore. Valves must be full opening and suitable for high pressure mud service.
- 3. Controls to be of standard design and each marked, showing opening and closing position.
- 4. Chokes will be positioned so as not to hamper or delay changing of choke beens. Repisceable parts for edjustable choke, other been sizes, retainers, and choke wrenches to be conveniently located for immediate use.
- All values to be equipped with handwheels or handles ready for immediate use.
- 6. Choke lines must be suitably enchored.

- 7.Handwheels and extensions to be connected and ready for use.
- Valves adjecent to drilling spool to be kept open. Use outside valves except for emergency.
- All seamless steel central piping (3000 pel working pressure) to have flexible joints to avaid stress. Hoses will be permitted.
- 18. Casinghead connections shall not be used except in case of emergency.
- 11.Do not use kill line for routine fill-up operations.