

- d. Logs to be run: Halliburton CNL/LDT/DLL/MSFL/GR/CAL/BHC, FMI below 7" Logs to be run in vertical hole only
- 8. The expected bottom-hole pressure and any anticipated abnormal pressures, temperatures or potential hazards that are expected to be encountered, such as lost circulation zones and hydrogen sulfide. The operator's plans for mitigating such hazards shall be discussed. Should the potential to encounter hydrogen sulfide exist, the mitigation procedures shall comply with the provisions of Onshore Oil and Gas Order No. 6.

Potential for abnormal pressure exists from the top of the Wolfcamp to TD. Bottom hole pressures at TD is estimated at 7200 psi. Bottom hole temperature 170 F. There is no anticipated Hydrogen Sulfide in this known drilling area. .

- 9. Any other facets of the proposed operation which the operator wishes for BLM to consider in reviewing the application.

Anticipated time expected to do this work is 61 days. (Horizontal Well)