

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO. 30-045-08680 08681
5. Indicate Type of Lease STATE FEE ☒
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name: Lobato Gas Com A
1. Type of Well: Oil Well ☐ Gas Well ☒ Other		
2. Name of Operator BP America Production Company Attn: Mary Corley	8. Well No. 1	
3. Address of Operator P.O. Box 3092 Houston, TX 77253	9. Pool name or Wildcat Blanco Mesaverde	
4. Well Location Unit Letter <u>K</u> <u>1750</u> feet from the <u>South</u> line and <u>1550</u> feet from the <u>West</u> line Section <u>03</u> Township <u>29N</u> Range <u>09W</u> NMPM <u>San Juan</u> County		
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 5651'		

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: <u>PayAdd</u> ☒	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: <u>Pay add</u> ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

01/14/2003 MIRU workover rig. NDWH. NU BOPs. TIH & tag fill @ 4633'. TOH w/2-3/8" production TBG. TIH w/bit & scraper & clean CSG to PBD. TIH w/ 5" CIBP & set CIBP @ 4462'. Load hole with 2% KCL. RU & ran GR log. RU & Menefee formation w/2JSPF, .470 inch diameter, 15 shots / 30 holes: 4132', 4179', 4186', 4206', 4213', 4254', 4263', 4288', 4294', 4336', 4342', 4281', 4295', 4422', 4430'. RU & frac w/90,153# 16/30 Brady Sand, 70 Quality Foam & N2. RU Flowback frac thru 1/4" choke for 12 hrs. Upsized to 1/2" choke & flowed back 24 hrs. Release PKR & TOH. TIH & tag fill @ 4350'. Circ hole clean to top of CIBP set @ 4462'. TIH & encountered tight spot @ 2201'. TOH. TIH w/ mill & milled heavy scale down to 2220'. TOH. TIH w/ 5" CIBP & set @ 3786'. Loaded hole w/2% KcL WTR & pressure tested CSG to 550#. Test Ok. Tih & encountered hard scale. Mill scale from 2220' to 3725'. Circ hole clean. TOH. TIH & tag CIBP @ 3786 & mill out. TIH to top of CIBP set @ 4462' & mill out CIBP. Circ hole clean to PBD @ 4680'. PU above TOL & flow back well thru 3.4" choke for 12 hrs. TIH & tag 3' fill. Circ clean to PBD. PU above perfs & flowed well thru 3/4" choke for 12 hrs. TIH & tag 0 fill. TOH. TIH w/2-3/8" production TBG & land A 4477'. ND BOP's. NUWH. Pull TBG plug.
01/31/2003 RDMO workover rig. Return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>Mary Corley</u>	TITLE <u>Sr. Regulatory Analyst</u>	DATE <u>02/05/2003</u>
Type or print name <u>Mary Corley</u>	Telephone No. <u>281-366-4491</u>	
(This space for State use)		
APPROVED BY <u>[Signature]</u>	TITLE <u>DEPUTY OIL & GAS INSPECTOR, DIST. 43</u>	DATE <u>FEB 10 2003</u>
Conditions of approval, if any:		