

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised May 08, 2003

WELL API NO. 30-045-22900	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. E-70-45	
7. Lease Name or Unit Agreement Name San Juan 32-9 Unit	
8. Well Number 43A	
9. OGRID Number 14538	
10. Pool name or Wildcat Blanco Mesaverde	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	
2. Name of Operator Burlington Resources Oil & Gas Company LP	
3. Address of Operator PO Box 4289, Farmington, NM 87499	
4. Well Location Unit Letter <u>D</u> : 1150 feet from the <u>North</u> line and 1055 feet from the <u>West</u> line Section <u>02</u> Township <u>31N</u> Range <u>10W</u> NMPM San Juan County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input checked="" type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Burlington Resources performed workover operations on the subject well as per the attached operation summary.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tammy Wimsatt TITLE Regulatory Specialist DATE 4/7/2004

Type or print name Tammy Wimsatt

Telephone No. (505) 326-9700

(This space for State use)

APPROVED BY Chad L TITLE DEPUTY OIL & GAS INSPECTOR, DIST. 00 DATE APR - 9 2004
Conditions of approval, if any:

BURLINGTON
 RESOURCES

 San Juan Division - Intranet Well Information System
 (DIMS)

Wednesday, April 7, 20

--Logon--	--By Date--	--By Well--	--By AFE--	--By Rig--
--Printouts--	--Production Notes--	--Accountability--	--Safety--	
	--Other--	API Units		

[Export to Excel](#)

 Operations Detail Report for: SAN JUAN 32-9 UNIT #43A
 LOE WORK

[Entire Well / All Events](#)
[Time Breakdown Summary](#)

DAY	FROM	TO	HRS	DEPTH (ft)	PHASE	CODES	OPERATION
1 (LWK)	02/06/2004 10:00	12:00	2.00		OBJECT	MIMO a	ROAD UNIT AND CREW TO LOCATION
1 (LWK)	02/06/2004 12:00	14:30	2.50		OBJECT	MIMO a	MOVE IN AND RIG UP RIG & EQUIP, HAD TO REMOVE BERM FROM AROUND PUMPJACK IN ORDER TO RIG UP
1 (LWK)	02/06/2004 14:30	16:00	1.50		OBJECT	RURD a	RIG DN HORSES HEAD, UNSEAT PUMP, PULL 1 ROD & PREP TO HOT OIL RODS & TBG IN THE MORNING
2 (LWK)	02/07/2004 06:00	07:30	1.50		OBJECT	SRIG a	CREW TRAVEL, SER RIG, WARM UP EQUIP
2 (LWK)	02/07/2004 07:30	08:30	1.00		OBJECT	HOTO a	LOAD HOT OIL UNIT 40 BBLS 2% KCL, PRE HEAT WATER, ATTEMPT TO HOT OIL TBG, COULD NOT PUMP DN TBG
2 (LWK)	02/07/2004 08:30	09:30	1.00		OBJECT	HOTO a	RIG UP H O UNIT, PUMP 20 BBLS 2% KCL DN CASING
2 (LWK)	02/07/2004 09:30	10:30	1.00		OBJECT	HOTO a	HOOK BACK UP TO TBG, START WORKING RODS WHILE TRYING TO PUMP DN TBG, COULD NOT GET ANY FLUID DN TBG
2 (LWK)	02/07/2004 10:30	12:00	1.50		OBJECT	TRIP a	POH W/RODS & PUMP, PULL OUT SLOW TO KEEP FROM SWABBING OIL OUT OF TBG, GOT OUT OF HOLE WITH ALL EQUIP INCLUDING SAND SCREEN, RODS COVERED W/HEAVY PARRIFIN
2 (LWK)	02/07/2004 12:00	12:30	0.50		OBJECT	HOTO a	HOT OIL TBG W/20 BBLS WATER
2 (LWK)	02/07/2004 12:30	13:45	1.25		OBJECT	NUND a	CHANGE OVER STUDS FOR 2000# WH, NDWH, NUBOP & FUNCTION TEST
2 (LWK)	02/07/2004 13:45	14:30	0.75		OBJECT	PULD a	X-OVER TOOLS TO PULL TBG, RIG UP FLOOR & TONGS, PU 2 JTS 2 3/8 TBG & TAG UP @ 5508,

							PBTD @ 5556'
2 (LWK)	02/07/2004 14:30	15:30	1.00		OBJECT	PRES a	N FLUSH TBG W/10BBLS WATER, DROP SV, LOAD TBG & PRESSURE TEST WITH RIG PUMP TO 1200 PSI, HELD GOOD FOR 5 MIN, RIH W/SANDLINE, RETRIEVE SV
2 (LWK)	02/07/2004 15:30	17:45	2.25		OBJECT	TRIP a	N POH & TALLY TBG, SHUT WELL IN, SDFWE, CALLED IN FOR BAILER FOR MONDAY, 02/09/04
3 (LWK)	02/09/2004 06:30	07:30	1.00		OBJECT	SRIG a	N CREW TRAVEL
3 (LWK)	02/09/2004 07:30	08:30	1.00		OBJECT	SRIG a	N WARM UP EQUIP, SER RIG, HSM, START WELL BLOWING TO PIT
3 (LWK)	02/09/2004 08:30	10:30	2.00		OBJECT	TRIP a	N M UP BAILER RIH TO TOP OF FILL @ 5508, WELL UNLOADED UP THE TBG 1 STAND IN AND COVERED RIG FLOOR AND GROUND AROUND WELLHEAD W/PARRIFIN
3 (LWK)	02/09/2004 10:30	11:30	1.00		OBJECT	COUT a	N C/OUT W/BAILER FROM 5508 TO 5528' BAILER QUIT WORKING, PUMPED 15 BBLS WATER DOWN BACKSIDE WHILE WORKING BAILER COULD NOT MAKE ANY MORE HOLE.
3 (LWK)	02/09/2004 11:30	13:00	1.50		OBJECT	TRIP a	N POH W/TBG & BAILER
3 (LWK)	02/09/2004 13:00	13:30	0.50		OBJECT	COUT a	N CLEAN SAND OUT OF FLAPPER VALVE AND TBG, RECOVERED 1STAND OF CLEAN FRAC SAND & 1/2 STAND SAND & WATER MIXED
3 (LWK)	02/09/2004 13:30	15:00	1.50		OBJECT	TRIP a	N RIH W/TBG & BAILER TO TOP OF SAND @ 5528
3 (LWK)	02/09/2004 15:00	15:15	0.25		OBJECT	COUT a	N C/OUT SAND TO PBTD @ 5550, QUIT MAKING HOLE. LEFT WITH 6' OF FILL IN HOLE, SHOULD BE CLEAN SAND.
3 (LWK)	02/09/2004 15:15	16:15	1.00		OBJECT	TRIP a	N POH W/TBG & BAILER
3 (LWK)	02/09/2004 16:15	16:30	0.25		OBJECT	PULD a	N PU & BREAK DOWN BTM ASSM CHECK FOR PARRIFIN, START IN HOLE W/BTM ASSM.
3 (LWK)	02/09/2004 16:30	17:30	1.00		OBJECT	TRIP a	N RIH W/TBG 15 STANDS, SWI, SDFN
4 (LWK)	02/10/2004 06:30	07:30	1.00		OBJECT	SRIG a	N CREW TRAVEL
4 (LWK)	02/10/2004 07:30	08:30	1.00		OBJECT	RRSR a	N RIG WOULD NOT START DUE TO COLD WEATHER, WORK ON AIR LINES
4 (LWK)	02/10/2004 08:30	09:00	0.50		OBJECT	BLOW a	N START WELL BLOWING DOWN WHILE WORKING ON RIG
4 (LWK)	02/10/2004 09:00	10:00	1.00		OBJECT	KILL a	N THAW RIG PUMP OUT & KILL WELL W/20 BBLS 2% KCL
4 (LWK)	02/10/2004 10:00	11:00	1.00		OBJECT	TRIP a	N TIH W/PROD TBG, LAND TBG ON HANGER @ 5505'
4 (LWK)	02/10/2004 11:00	11:30	0.50		OBJECT	NUND a	N NDBOP, NUWH, INSTALL DIP TUBE & SAND SCREEN ON NEW PUMP
4	02/10/2004	13:00	1.50		OBJECT	TRIP	N X-OVER TO RUN RODS, RIH W/RODS & PUMP

(LWK)	11:30					a	
4 (LWK)	02/10/2004 13:00	14:30	1.50		OBJECT	PRES a	N INSTALL NEW POLISH ROD, POLISH ROD LINER AND BIG STUFF STUFFING BOX, SEAT PUMP, LOAD TBG, PRES TEST TBG TO 600 PSI WITH ROD PUMP, HELD GOOD
4 (LWK)	02/10/2004 14:30	16:30	2.00		OBJECT	RURD a	N RIG DOWN RIG & EQUIP, PREP TO MOVE TO PAGE 101 R, CLEAN UP OIL SPILL AROUND WELLHEAD AND LAY SOAKER PADS DOWN.

[Global Intranet](#) | [Comments and Feedback](#) | [Legal Notice](#) | [Privacy Statement](#)