Form	31	60-5	
(Augu			

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 200

Do

Lease Serial No.

SUNDRI NUTICES AND REPORTS ON WELLS	Y NWSFU/09ZOA
not use this form for proposals to drill or to re-enter an	/
ndoned well. Use form 3160-3 (APD) for such proposals.	6. If Indian, Allottee or T
navnou men. Ose ronn v rov-s (AFD) fot such proposais.	EACTEDNIALAN/A

abandoned well. Use form 3160-3 (APD) for such proposals.  SUBMIT IN TRIPLICATE - Other instructions on reverse side.				If Indian, Allottee or Tribe Name     EASTERN NAVAJO     If Unit or CA/Agreement, Name and/or No.     NMNM78391C	
. Type of Well			8. Well Name and N	0.	
☐ Oil Well ☐ Gas Well ☐ Ot	her		GCU 163		
2. Name of Operator Contact: CHERRY HLAVA BP AMERICA PRODUCTION CO E-Mail: hlavacl@bp.com		9. API Well No. 30-045-07795	9. API Well No. 30-045-07795-00-S1		
a. Address P. O. BOX 3092 HOUSTON, TX 77253		3b. Phone No. (include are) cod Ph: 281.366.4081 Fx: 281.366.0760	10. Field and Pool, of BASIN DAKO	or Exploratory TA	
Location of Well (Footage, Sec., 7	T., R., M., or Survey Description	1)	11. County or Parish	n, and State	
Sec 26 T29N R13W SWSE 0 36.69241 N Lat, 108.17123 V		MAR 2	SAN JUAN CO	OUNTY, NM	
12. CHECK APP	ROPRIATE BOX(ES) TO	O INDICATE NATURE OF	NOTICE, REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION		TYPE O	TYPE OF ACTION		
— Notice of Intent	☐ Acidize	Deepen	Production (Start/Resume)	☐ Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	☐ Well Integrity	
Subsequent Report	Casing Repair	☐ New Construction	Recomplete	Other	
Final Abandonment Notice	Change Plans	Plug and Abandon	☐ Temporarily Abandon	<b>.</b>	
	Convert to Injection	Plug Back	☐ Water Disposal		
On 1/20/03 BP America requerements on 1/20/03 BP Am	/28/03 bmitted to report hole in c	asing and repair of that hole	•		
For technical questions pleas		•			
4. Thereby certify that the foregoing is	Thus and correct				
	Electronic Submission # For BP AMERICA	H9578 verified by the BLM We A PRODUCTION CO, sent to the Decessing by Steve Mason on 0	e Farmington		
Name (Printed/Typed) CHERRY			DRIZED REPRESENTATIVE	_	
Signature (Electronic S	Submission)	Date 03/14/2	2003		
	THIS SPACE FO	OR FEDERAL OR STATE	OFFICE USE		
APPROVED By ACCEPT	ED		N MASON EUM ENGINEER	Date 03/19/2003	
nditions of approval, if any, are attache tify that the applicant holds legal or eq ich would entitle the applicant to cond	uitable title to those rights in the	not warrant or e subject lease Office Farming	gton	***	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office Farmington

## Casing Leak Repair Gallegos Canyon Unit 163 01/31/2003

2/25/03 TIH & SET RBP @6100'. PRESS TST TO 1000#. HELD PRESSURE. RU & PMPd DN BACKSIDE & CSG LEAKED OFF TO 350# IN 30 SECONDS. ISOLATED HOLE IN CSG 3780' - 3810'. TOH w/TBG & SET PKR. EST RATE INTO HOLE PMPd 2 BPM @1100#. RU & DUMP 1 SX SAND ON RBP. SDFN.

MUDDY ROADS - STANDBY

3/4/03 RU CEMENTERS. TRY TO PMP INTO HOLE, COULD NOT BREAK DN. TOH w/PKR. TIH OPEN ENDED. SPOT 3 bbls CMT. TOH 11 STANDS, REVERSE OUT. PRESSURE UP ON SQZ. SECURE WELL.

3/5/03 CSG 800 PSI BLED DN PSI. TOH w/TBG TIH w/BIT. TAG CMT@3710'. RU PWR SWIVEL & RU & DRILL OUT CMT FROM 3710' TO 3858'. RD. TST CSG TO 500 PSI. BLED DN 170 PSI IN 3 MINS. RELEASE PSI & TST CSG TO 300 POSI, BLED DN SAME. TOH w/BIT.

3/6/03 TIH w/PKR. FOUND HOLE @3808. TRY TO BREAK DN, WOULD NOT BREAK DN. TOH w/PKR. TIH OPEN-ENDED TO SPOT CMT. SPOT 3 bbls CMT. REVERSE CIRC TBG CLEAN. PSI UP & TRY TO SQZ CMT IN TO HOLE. SHUT IN PSI 1300. RD CEMENTERS. SECURE WELL.

3/7/03 TIH & TAG CMT @3582'. CIRC OUT 10' GREEN CMT. PUH & CIRC CLEAN. WOC. DRILL OUT CMT FROM 3592' - 3706'. CMT STILL GREEN. SDF WEEK-END.

**3/10/03** DRILL OUT CMT 3706' - 3843'. TIH TO 3900'. TST CSG TO 540 PSI, HELD 10 MINS. GOOD. TOH w/BIT. C/O SND TO TOP OF **RBP @6100'** w/WTR.

3/11/03 TIH & UNSET RBP. TOH w/RBP. C/O FILL TO BPTD @6290'.

3/12/03 TIH & LAND TBG @ 6231'.

TRYING TO GET DAKOTA GOING AGAIN BEFORE PLUGBACK