


State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

<p>1. Type of Well GAS</p> <p>2. Name of Operator BURLINGTON RESOURCES OIL & GAS COMPANY LP</p> <p>3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700</p> <p>4. Location of Well, Footage, Sec., T, R, M 1500' FNL, 990' FWL, Sec. 11, T-30-N, R-11-W, NMPM, San Juan County</p>	<p>API # (assigned by OCD) 30-045-09726</p> <p>5. Lease Number Fee</p> <p>6. State Oil&Gas Lease #</p> <p>7. Lease Name/Unit Name Current</p> <p>8. Well No. 1</p> <p>9. Pool Name or Wildcat Aztec Pictured Cliffs</p> <p>10. Elevation:</p>
--	---



Type of Submission	Type of Action
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input checked="" type="checkbox"/> Other - Deepen
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Conversion to Injection

13. Describe Proposed or Completed Operations

It is intended to restimulate the Pictured Cliffs formation in the subject well as follows:

Move in, rig up. Pull tubing. Deepen the well to approximately 200 feet below the top of the Pictured Cliffs. Run production casing. Cement to surface. Fracture stimulate the Pictured Cliffs formation. Return the well to production.

SIGNATURE *Peggy Case* (KM5) Regulatory Supervisor _____ March 12, 2003 _____

no
(This space for State Use)

Approved by *[Signature]* Title _____ Date MAR 18 2003

DEPUTY OIL & GAS INSPECTOR, DIST. #1