

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator

**BURLINGTON
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

800' FNL, 2460' FEL, Sec. 7, T-32-N, R-6-W, NMPM, San Juan County

API # (assigned by OCD)
30-045-29628

5. Lease Number
Fee

6. State Oil & Gas Lease #

7. Lease Name/Unit Name

Allison Unit

8. Well No.
61

9. Pool Name or Wildcat
Basin DK/Blanco MV

10. Elevation:

Type of Submission

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment

Type of Action

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other -

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

Burlington Resources completed workover operations as per the attached daily summary.



SIGNATURE

Francesca Bond

Regulatory Specialist April 6, 2004

FSB

(This space for State Use)

Approved by

Chad H. [Signature]

Title

DEPUTY OIL & GAS INSPECTOR, DIST. 8

Date

APR 14 2004

BURLINGTON
RESOURCES**San Juan Division - Intranet Well Information System
(DIMS)**

Thursday, April 1, 20

--Logon--	--By Date--	--By Well--	--By AFE--	--By Rig--
--Printouts--	--Production Notes--	--Accountability--	--Safety--	
	--Other--	API Units		

[Export to Excel](#)**Operations Detail Report for: ALLISON UNIT #61
LOE WORK**[Entire Well / All Events](#)**Time Breakdown Summary**

DAY	FROM	TO	HRS	DEPTH (ft)	PHASE	CODES	OPERATION
1 (LWK)	12/05/2003 06:00	07:00	1.00		OBJECT	SAFE a	12/5/2003 TRAVEL TO LOCATION HELD SAFETY MEETING TOPIC RIG MOVE BR SUPERVISOR TJR CREW
1 (LWK)	12/05/2003 07:00	08:00	1.00		OBJECT	MIMO a	MOVE RIG F/ALLISON #127 TO ALLISON UNIT COM #61
1 (LWK)	12/05/2003 08:00	09:30	1.50		OBJECT	RURD a	SPOT RIG ON LOCATION RU
1 (LWK)	12/05/2003 09:30	10:30	1.00		OBJECT	RURD a	RU PUMP & LINES RU FL BK TNK CK CSG PSI 300# TBG 200# VENT CSG TO TNK TRY TO BLOW DOWN TBG
1 (LWK)	12/05/2003 10:30	11:30	1.00		OBJECT	WAIT a	WAIT ON WIRE LINE TRK
1 (LWK)	12/05/2003 11:30	14:00	2.50		OBJECT	WIRE a	RUN GAUGE RING TO 6200' RUN IN W/ TBG PLUG SET GOING IN @ 3000' RETRIVE TBG PLUG COVERED W/SCALE & SAND RD WIRE LINE TRK
1 (LWK)	12/05/2003 14:00	15:00	1.00		OBJECT	WELH a	WORK ON RUSTED BOLTS IN WELL HEAD
1 (LWK)	12/05/2003 15:00	15:30	0.50		OBJECT	KILL a	PUMP 40-BBLS KILL FLD DOWN TBG
1 (LWK)	12/05/2003 15:30	16:30	1.00		OBJECT	NUND a	ND WELL HEAD NU & TEST BOP RU TBG EQUIP.
1 (LWK)	12/05/2003 16:30	17:30	1.00		OBJECT	RURD a	WORK TBG HANGER FREE INSTALL TBG RUBBER RU LINE TO SALES TURN TO SALES SDFN TRAVEL TO TJR YARD
2 (LWK)	12/06/2003 06:00	07:00	1.00		OBJECT	SAFE a	12/6/2003 TRAVEL TO LOCATION HELD SAFETY MEETING TOPIC BLOWING DOWN WELL BR SUPERVISOR TJR CREW MNT. AIR MAN
2	12/06/2003 08:00	08:00	1.00		OBJECT	FLOW	CSG 300# TBG 200# VENT TO TNK RU & PUMP

(LWK)	07:00					a	40-BBLS KILL FLD
2 (LWK)	12/06/2003 08:00	09:00	1.00		OBJECT	TRIP a	N TOO H W/ 68-JTS 23/8 PROD. TBG PINS CAME BAD
2 (LWK)	12/06/2003 09:00	10:00	1.00		OBJECT	WAIT a	N WAIT ON TBG FLOAT SPOT FLOAT PREP. TO LD BAD PIPE
2 (LWK)	12/06/2003 10:00	11:00	1.00		OBJECT	RRSR a	U TRY TO START PUMP STARTER BURNED UP
2 (LWK)	12/06/2003 11:00	12:00	1.00		OBJECT	RRSR a	N SWI TURN TO SALES DRAIN UP PUMP & LINES SDFN TRAVEL TO TJR YARD NO REPORT FOR 12/7/2003
3 (LWK)	12/07/2003 08:30	09:30	1.00		OBJECT	SAFE a	N 12/8/2003 TRAVEL TO LOCATION HELD SAFETY MEETING TOPIC LD TBG BR SUPERVISOR TJR CREW
3 (LWK)	12/07/2003 09:30	12:30	3.00		OBJECT	RRSR a	T INSTALL NEW STARTER IN PUMP
3 (LWK)	12/07/2003 12:30	13:00	0.50		OBJECT	KILL a	N PUMP 20-BBLS KILL FLD DOWN TBG
3 (LWK)	12/07/2003 13:00	14:00	1.00		OBJECT	PULD a	N LD 40-JTS 23/8 TBG STARTED TO FIND HOLES
3 (LWK)	12/07/2003 14:00	15:30	1.50		OBJECT	PULD a	N LD 80-JTS TOTAL BACKUP SLIPED TWISTED OFF JT IN SLIPS
3 (LWK)	12/07/2003 15:30	18:00	2.50		FISH	WAIT a	U WAIT ON BKR TOOLS
3 (LWK)	12/07/2003 18:00	18:30	0.50		FISH	FISH a	N PU BKR OVER SHOT FISH JT OUT SWI DRAIN UP PUMP TURN WELL TO SALES TRAVEL TO TJR YARD
4 (LWK)	12/09/2003 06:00	07:00	1.00		OBJECT	SAFE a	N 12/9/2003 TRAVEL TO LOCATION HELD SAFETY MEETING TOPIC PU TBG BR SUPERVISOR TJR CREW MNT AIR MAN
4 (LWK)	12/09/2003 07:00	08:00	1.00		OBJECT	KILL a	N CSG 300# TBG 200# VENT TO TNK PUMP 20-BBLS KILL FLD
4 (LWK)	12/09/2003 08:00	09:30	1.50		OBJECT	PULD a	N FINISH LD BAD 23/8 TBG BTM OF STRING HEAVY SCALE 176-JTS TOTAL TO BE TAKEN TO BR PIPE YARD
4 (LWK)	12/09/2003 09:30	10:00	0.50		OBJECT	RURD a	N CHANGE OUT TBG FLOATS
4 (LWK)	12/09/2003 10:00	10:30	0.50		OBJECT	PULD a	N PU 37/8 MILL INSTALL STRIPPER RUBBER
4 (LWK)	12/09/2003 10:30	13:00	2.50		OBJECT	PULD a	N TALLY & PU 75-JTS NEW 23/8 TBG
4 (LWK)	12/09/2003 13:00	13:30	0.50		OBJECT	SHDN a	N EAT LUNCH
4 (LWK)	12/09/2003 13:30	14:00	0.50		OBJECT	PULD a	N TALLY & PU 10-JTS 23/8 TBG BRAKE BAND IN TONGS BROKE
4 (LWK)	12/09/2003 14:00	16:00	2.00		OBJECT	WAIT a	T WAIT ON NEW BRAKE BAND
4 (LWK)	12/09/2003 16:00	17:00	1.00		OBJECT	PULD a	N FIX TONGS TALLY & PU 5-JTS STAY ABOVE PERFS SWI TURN TO SALES TRAVEL TO TJR

							YARD
5 (LWK)	12/10/2003 06:00	07:00	1.00		OBJECT	SAFE a	N 12/10/2003 TRAVEL TO LOCATION HELD SAFETY MEETING TOPIC CLEAN OUT W/AIR BR SUPERVISOR TJR CREW MNT. AIR MAN
5 (LWK)	12/10/2003 07:00	07:30	0.50		OBJECT	FLOW a	N CK CSG 300# TBG 20# VENT TO TNK
5 (LWK)	12/10/2003 07:30	09:30	2.00		OBJECT	PULD a	N FINISH PU & TALLY NEW 23/8 TBG TAG SCALE @ 7524'
5 (LWK)	12/10/2003 09:30	11:00	1.50		OBJECT	RURD a	N RU DRL. EQUIP & POWER SWIVEL
5 (LWK)	12/10/2003 11:00	12:00	1.00		OBJECT	CIRC a	N CIRC. HOLE W/AIR-MIST 15-BPH
5 (LWK)	12/10/2003 12:00	13:30	1.50		OBJECT	COUT a	N CLEAN OUT F/7524-7528' PLUGED FLOAT VAVLE IN BIT SUB TRY TO CLEAR FLOAT
5 (LWK)	12/10/2003 13:30	14:30	1.00		OBJECT	RURD a	N RD DRL. EQUIP. RU TBG EQUIP.
5 (LWK)	12/10/2003 14:30	16:00	1.50		OBJECT	TRIP a	N TOO H W/239-JTS 23/8 TBG W/ 37/8 MILL 5-INCHS SCALE IN FLOAT VAVLE CLEAN OUT FLOAT THREADS IN BOX ON BIT SUB BAD SWI TURN TO SALES
5 (LWK)	12/10/2003 16:00	17:00	1.00		OBJECT	RURD a	N DRAIN UP PUMP & LINES TRAVEL TO TJR YARD FUEL USE TO BE ADDED TO NEXT DAY
6 (LWK)	12/11/2003 06:00	07:00	1.00		OBJECT	SAFE a	N 12/11/2003 TRAVEL TO LOCATION HELD SAFETY MEETING TOPIC CLEANING OUT W/AIR-MIST BR SUPERVISOR TJR CREW MNT. AIR MAN
6 (LWK)	12/11/2003 07:00	07:30	0.50		OBJECT	FLOW a	N CSG 150# VENT TO TNK
6 (LWK)	12/11/2003 07:30	08:00	0.50		OBJECT	RURD a	N INSTALL NEW BIT SUB & NEW RUBBER
6 (LWK)	12/11/2003 08:00	09:30	1.50		OBJECT	TRIP a	N TIH W/37/8 MILL & 1/2 OF 23/8 TBG RU & CIRC. W/AIR
6 (LWK)	12/11/2003 09:30	11:00	1.50		OBJECT	TRIP a	N TIH W/REST OF 23/8 TBG RU DRL. EQUIP.
6 (LWK)	12/11/2003 11:00	11:30	0.50		OBJECT	CIRC a	N CIRC. HOLE W/AIR-MIST 15-BPH
6 (LWK)	12/11/2003 11:30	14:30	3.00		OBJECT	MILL a	N MILL & CLEAN SCALE F/7528' TO 7605' HARD DRILLING PLUGED MILL
6 (LWK)	12/11/2003 14:30	15:30	1.00		OBJECT	RURD a	N RD DRL. EQUIP RU TBG EQUIP.
6 (LWK)	12/11/2003 15:30	17:00	1.50		OBJECT	TRIP a	N TOO H W/23/8 TBG & 37/8 MILL SWI 48-JTS LEFT TO TOO H
6 (LWK)	12/11/2003 17:00	18:00	1.00		OBJECT	RURD a	N DRAIN UP PUMP & LINES TURN TO SALES SDFN TOTAL FUEL USE ON AIR PKG 109-GALS SDFN TRAVEL TO TJR YARD
7 (LWK)	12/12/2003 06:00	07:00	1.00		OBJECT	SAFE a	N 12/12/2003 TRAVEL TO LOCATION HELD SAFETY MEETING TOPIC HOUSE KEEPING BR SUPERVISOR TJR CREW MNT. AIR MAN
7	12/12/2003	07:30	0.50		OBJECT	FLOW	N CSG PSI 400# VENT TO TNK

(LWK)	07:00					a	
7 (LWK)	12/12/2003 07:30	08:30	1.00		OBJECT	TRIP a	N FINISH TOO H W/23/8 TBG 37/8 MILL CLEAN OUT MILL & FLOAT VAVLE
7 (LWK)	12/12/2003 08:30	10:00	1.50		OBJECT	TRIP a	N TIH W/ 120-JTS 23/8 TBG W/MILL CIRC. TBG W/AIR-MIST
7 (LWK)	12/12/2003 10:00	12:00	2.00		OBJECT	TRIP a	N FINISH TIH W/125-JTS 23/8 TBG RU DRL. EQUIP & POWER SWIVEL CIRC HOLE W/AIR-MIST 15- BPH
7 (LWK)	12/12/2003 12:00	15:30	3.50		OBJECT	MILL a	N DRL. OUT SCALE & SAND F/7605'-7665' HARD DRLING THROUGH DK. PERFS
7 (LWK)	12/12/2003 15:30	16:30	1.00		OBJECT	CIRC a	N CIRC. & BLOW CLEAN RD DRL. EQUIP PULL MILL ABOVE DK. PERFS.
7 (LWK)	12/12/2003 16:30	17:30	1.00		OBJECT	RURD a	N DRAIN UP PUMP & LINES SWI SDFN TRAVEL TO TJR YARD TOTAL FUEL USE 295-GALS ON AIR PKG
8 (LWK)	12/13/2003 06:00	07:00	1.00		OBJECT	SAFE a	N 12/13/2003 TRAVEL TO LOCATION HELD SAFETY MEETING TOPIC PINCH POINTS BR SUPERVISOR TJR CREW MNT. AIR MAN
8 (LWK)	12/13/2003 07:00	07:30	0.50		OBJECT	FLOW a	N CK CSG PSI 300# VENT TO TNK
8 (LWK)	12/13/2003 07:30	09:00	1.50		OBJECT	RURD a	N TIH W/12-JTS 23/8 TBG TAG @ 7665' RU DRL. EQUIP. & POWER SWIVEL
8 (LWK)	12/13/2003 09:00	10:00	1.00		OBJECT	CIRC a	N CIRC. HOLE W/AIR-MIST 15-BPH
8 (LWK)	12/13/2003 10:00	14:30	4.50		OBJECT	MILL a	N DRL. OUT SCALE & SAND F/7665'-7705' DRL. HARD ALL THE WAY MILL STICKING ALL THE WAY
8 (LWK)	12/13/2003 14:30	15:30	1.00		OBJECT	CIRC a	N CIRC. HOLE CLEAN & BLOW CLEAN
8 (LWK)	12/13/2003 15:30	16:30	1.00		OBJECT	RURD a	N RD DRL. EQUIP. & POWER SWIVEL RU TBG EQUIP TOO H W/ 14-JTS 23/8 TBG ABOVE DK. PERFS
8 (LWK)	12/13/2003 16:30	17:30	1.00		OBJECT	RURD a	N SWI DRAIN UP PUMP & LINES SDFN TOTAL FUEL USE ON AIR PKG 350-GALS NO REPORT FOR 12/14/2003 TRAVEL TO TJR YARD
9 (LWK)	12/15/2003 06:00	07:00	1.00		OBJECT	SAFE a	N 12/15/2003 TRAVEL TO LOCATION HELD SAFETY MEETING TOPIC DRIVING COND. BR SUPERVISOR TJR CREW MNT. AIR MAN
9 (LWK)	12/15/2003 07:00	07:30	0.50		OBJECT	FLOW a	N CK CSG PSI 500# VENT TO TNK
9 (LWK)	12/15/2003 07:30	08:30	1.00		OBJECT	CIRC a	N TIH W/14-JTS 23/8 TBG TAG BTM @ 7705' CIRC. HOLE CLEAN
9 (LWK)	12/15/2003 08:30	12:00	3.50		OBJECT	WAIT a	N PULL 37/8 MILL ABOVE DK. PERFS 7614' WAIT ON BJ UNICHEM FOR ACID JOB
9 (LWK)	12/15/2003 12:00	13:00	1.00		OBJECT	SPOT a	N RU BJ PUMP 330-GALS 15% TRIPLE INHIB. FLUSH W/10-BBLS WATER RD BJ
9 (LWK)	12/15/2003 13:00	14:30	1.50		OBJECT	TRIP a	N TOO H W/23/8 TBG 37/8 MILL LD TOOLS MILL LOOKED GOOD PU PROD. BHA

9 (LWK)	12/15/2003 14:30	15:30	1.00	OBJECT	BRCH a	N	TIH W/1/2 23/8 TBG BROACH TBG & CIRC. W/AIR-MIST
9 (LWK)	12/15/2003 15:30	16:30	1.00	OBJECT	TRIP a	N	TIH W/REST OF 23/8 TBG LEFT ABOVE DK. PERFS @ 7614'
9 (LWK)	12/15/2003 16:30	17:30	1.00	OBJECT	RURD a	N	SWI DRAIN UP PUMP & LINES SDFN TRAVEL TO TJR YARD
10 (LWK)	12/16/2003 06:00	07:00	1.00	OBJECT	SAFE a	N	12/16/2003 TRAVEL TO LOCATION HELD SAFETY MEETING TOPIC RU POWER SWIVEL BR SUPERVISOR TJR CREW MNT. AIR MAN
10 (LWK)	12/16/2003 07:00	08:00	1.00	OBJECT	FLOW a	N	CK CSG PSI 300# CKANGE OVER TO OTHER SIDE OF FL BK TNK VENT CSG TO TNK
10 (LWK)	12/16/2003 08:00	09:00	1.00	OBJECT	BRCH a	N	FINISH TIH W/20-JTS 23/8 TBG BROACH TBG
10 (LWK)	12/16/2003 09:00	10:00	1.00	OBJECT	CIRC a	N	RU DRL. EQUIP. & POWER SWIVEL CIRC HOLE W/AIR-MIST 15-BPH
10 (LWK)	12/16/2003 10:00	12:00	2.00	OBJECT	COUT a	N	CIRC. F/7705'-7709' HARD SCALE F/7709'-7735' CIRC. SAND
10 (LWK)	12/16/2003 12:00	14:00	2.00	OBJECT	RRSR a	T	MADE CON. CIRC. HOLE BLOCKS FELL ABOUT 40' SLOWLY SWIVEL SUB STUCK IN STRIPPER RUBBER HAD TO FIX DRL. LINE DRL. LINE & TBG ELEAVATORS WAS ALL THAT WAS BROKE BREAKS ON RIG HAD COOLED AND LET BLOCKS FALL
10 (LWK)	12/16/2003 14:00	14:30	0.50	OBJECT	CIRC a	N	CIRC. HOLE W/AIR-MIST 15-BPH
10 (LWK)	12/16/2003 14:30	15:30	1.00	OBJECT	COUT a	N	CLEAN OUT F/7766'-7799' CIRC. HOLE CLEAN
10 (LWK)	12/16/2003 15:30	16:30	1.00	OBJECT	RURD a	N	RD DRL. EQUIP & POWER SWIVEL TOO H W/23/8 TBG ABOVE DK. PERFS 7614' SWI SDFN TOTAL FUEL USE ON AIR PKG 350-GALS TRAVEL TO TJR YARD
11 (LWK)	12/17/2003 06:00	07:00	1.00	OBJECT	SAFE a	N	12/17/2003 TRAVEL TO LOCATION HELD SAFETY MEETING TOPIC RIG MOVE BR SUPERVISOR TJR CREW MNT. AIR MAN
11 (LWK)	12/17/2003 07:00	07:30	0.50	OBJECT	FLOW a	N	CK CSG PSI 300# VENT TO TNK
11 (LWK)	12/17/2003 07:30	08:30	1.00	OBJECT	TRIP a	N	TIH W/20-JTS 23/8 TBG TAG BTM @ 7792' RU TO CIRC.
11 (LWK)	12/17/2003 08:30	11:00	2.50	OBJECT	CIRC a	N	CIRC. HOLE W/ AIR-MIST 12-BPH CLEAN OUT TO PBTD 7799' CIRC. & BLOW WELL CLEAN RD CIRC. EQUIP.
11 (LWK)	12/17/2003 11:00	12:00	1.00	OBJECT	NUND a	N	INSERT & SEAT TBG HANGER ND BOP NU WELL HEAD PUMP OFF EX. CK REVERSE CIRC. WELL FLOWING TBG- 242-JTS 23/8 TBG 1-2'X23/8 TBG SUB 1-JT 23/8 TBG 1-23/8 1.78 SEAT NIPPLE 1- 23/8 EX. CK. 1-23/8 SAWTOOTH COLLAR BTM TBG @ 7651' KB SEAT NIPPLE @ 7650' KB PITOT GAUGE 7-OUNCES 2" OPEN 404 MCF RD AIR EQUIP.

11 (LWK)	12/17/2003 12:00	12:30	0.50		OBJECT	SHDN a	N	EAT LUNCH
11 (LWK)	12/17/2003 12:30	14:00	1.50		OBJECT	RURD a	N	RD FL BK TNK & PUMP CLEAN UP LOCATION RD LOAD OUT EQUIP. MOVE RIG & EQUIP. TO 29-7 563S

[Global Intranet](#) | [Comments and Feedback](#) | [Legal Notice](#) | [Privacy Statement](#)