Form 3160-5 (April 2004)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED	
FORM APPROVED	
OM B No. 1004-0137	
Expires: March 31, 2007	7

5. Lease Serial No.

NMSF-	-14-20	-603-2	199

6. If Indian, Allottee or Tribe Name

abandoned w	Navajo			
SUBMIT IN TRIPLICATE- Other instructions on reverse side.			7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well Gas Well Other			NW Cha Cha Unit  8. Well Name and No.	
2. Name of Operator Kenson Operating Company			NW Cha Cha # 30 WIW  9. API Well No.	
3a. Address 3100 La Plata Highway, Farmington, NM, 87401		3b. Phone No. (include area code) 505-564-3100	30-045-13104  10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec.,	Cha Cha Gallup			
Sec 22, T29N-R14W, 480' FSL 1980' FEL			11. County or Parish, State  San Juan County, New Mexico	
12. CHECK A	PPROPRIATE BOX(ES) T	O INDICATE NATURE OF NOTIC	CE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent Subsequent Report	Acidize Alter Casing Casing Repair	Fracture Treat Reclama New Construction Recomp	lete Other	
	Change Plans	Plug and Abandon Tempora	arily Abandon	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

\_\_ Plug Back

Intend to repair casing leaks to retain as water injection well.

1. Retrieve RBP at 3185'.

Final Abandonment Notice

- 2. RIH with workstring and 4 1/2" casing swedge to tight spot at 5187'. Tag PBTD at 5368', POOH.
- 3. Run casing integrity log, evaluate.
- 4. RIH with workstring, RBP, and packer, test for casing leaks and locations.

Convert to Injection

- 5. Squeeze casing leaks with cement, to be determined as testing is conducted.
- 6. Conduct final mechanical integrity test.
- 7. Install IPC injection tubing and packer.
- 8. Return well to water injection status.
- 9. Work expected to begin 09/01/04.
- 10. Work to be completed by 10/01/2004.



Water Disposal

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)

Charles H. Williams

Title Engineering Operations Manager

Signature

Charles A. Williams

ate

04/30/2004

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Original Signed: Stephen Mason

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Date MAY 0 7 2004

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)