30-045-10383

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 FARMINGTON, NM 87499 505-325-2627 • FAX: 505-325-1211

JUN 2004

May 10, 2004

New Mexico Oil Conservation Division Aztec District

1000 Rio Brazos Road

Invoice 3309

1 of 2

Rig #9

For the plug and abandonment of the HSGU #7, a Gallup well located in NW, Section 30, T-31-N, R-16-W, San Juan County, NM. Review report for work details. This work done under NMOCD PA: 41-521-07-00028; Purchase Doc.: 04-199-000549.

Cost Summary:

Aztec, NM 87410

ID	# Date	Item Description	Units	U	nit Cost	Ε	xtension
W	orkover Rig,	Travel and Supervision:					
		Contractors Supervisor / Cementer	0.5	\$	250.00	\$	125.00
· A'	1 5/5/04	Contractors Supervisor / Cementer	0.5	\$	250.00	\$	125.00
A ²	5/6/04	Contractors Supervisor / Cementer	1.0	\$	250.00	\$	250.00
A ²	1 5/7/04	Contractors Supervisor / Cementer	0.5	\$	250.00	\$	125.00
Αź	2 5/4/04	Crew travel, round trip time	1.0	\$	112.00	\$	112.00
A2	2 5/5/04	Crew travel, round trip time	2.0	\$	112.00	\$	224.00
Αź		Crew travel, round trip time	2.0	\$	112.00	\$	224.00
A2	2 5/7/04	Crew travel, one way	1.0	\$	112.00	\$	112.00
ΑS	3 5/4/04	Shallow Rig	6.00	\$	140.00	\$	840.00
A3	3 5/5/04	Shallow Rig	2.75	\$	140.00	\$	385.00
A:	3 5/6/04	Shallow Rig	9.75	\$	140.00	\$	1,365.00
, A	3 5/7/04	Shallow Rig	6.25	\$	140.00	\$	875.00
Ce	menting Se	rvices:					
B′	1 5/4/04	Cementing equipment on location	0.5	\$	450.00	\$	225.00
B′	1 5/5/04	Cementing equipment on location	0.5	\$	450.00	\$	225.00
B	1 5/6/04	Cementing equipment on location	1.0	\$	450.00	\$	450.00
B′	5/7/04	Cementing equipment on location	0.5	\$	450.00	\$	225.00
ВЗ	3 5/6/04	Cement, plug #1, sxs, Type II	34	\$	10.50	\$	357.00
В3	3 5/7/04	Cement, plug #2, sxs, Type II	69	\$	10.50	\$	724.50
В3	3 5/7/04	Cement, set P&A marker, sxs	17	\$	10.50	\$	178.50
Wi		ces:		,		,	
C,		Wireline unit on location, used	1.0	\$	250.00	\$	250.00
C		Perforate squeeze holes at 184'	1.0	\$	300.00	\$	300.00
Pa	ckers. Retai	ners & Casing Scrapers:		Ψ.		_	N + 1
D3		Cement retainer, tubing set, 5-1/2"	1.0	\$	900.00	\$	900.00
D4	· -	Casing scraper rental, 5-1/2"	1.0	\$	250.00	\$	250.00
W	orkstrings &	Miscellaneous Rentals:		*		7	
E1.	_	Workstring rental, 2-3/8, feet	1366	\$	0.12	\$	163.92
E6.		Companion flange rental, 5-1/2"	1.0	\$	50.00	\$	50.00
E1		Waste fluid container, days used	3.0	\$	30.00	\$	90.00

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 FARMINGTON, NM 87499 505-325-2627 • FAX: 505-325-1211

May 10, 2004

2 of 2

New Mexico Oil Conservation Division

Aztec District

1000 Rio Brazos Road

Invoice 3309

Rig #9

Aztec, NM 87410

For the plug and abandonment of the HSGU #7, a Gallup well located in

NW. Section 30, T-31-N, R-16-W, San Juan County, NM. Review report for work details.

This work done under NMOCD PA: 41-521-07-00028; Purchase Doc.: 04-199-000549.

Cost Summary:

Continued:

ID#	Date	Item Description	Units	U	nit Cost	E:	xtension
Trans	sportation	n and Miscellaneous Services:					
F1.a	5/4/04	Unit #141, Haul waste pit # 525 and workstring	2.0	\$	74.00	\$	148.00
F1.b	5/6/04	Unit #141, Move workstring into position	2.0	\$	74.00	\$	148.00
F1.c	5/7/04	Unit #141, hold workstring during well work	2.0	\$	74.00	\$	148.00
F1.d	5/7/04	Unit #19 & gooseneck, haul tubing to A+ yard	1.000	\$	50.00	\$	50.00
F4	4/26/04	Float with workstring, rental	3.0	\$	15.00	\$	45.00
F6.a	5/2/04	Unit #265, Haul 2 loads of water to central tank	8.0	\$	50.00	\$	400.00
F14	5/2/04	Purchase water , above	2.0	\$	20.00	\$	40.00
F6.b	5/4/04	Unit #134, Haul 1 load of water to location	2.0	\$	50.00	\$	100.00
F6.c	5/6/04	Unit #134, Haul 1 load of water to location	2.0	\$	50.00	\$	100.00
F6.d	5/7/04	Unit #134, Hold fresh water on location	2.0	\$	50.00	\$	100.00
F6.e	5/4/04	Unit #155, Haul / hold waste water from steel pit	2.0	\$	50.00	\$	100.00
F6.f	5/6/04	Unit #155, Haul / hold waste water from steel pit	2.0	\$	50.00	\$	100.00
F6.g	5/7/04	Unit #155, Haul / hold waste water from steel pit	2.0	\$	50.00	\$	100.00
F7	5/17/04	B-hoe, Clean up location and wellhead	3.75	\$	50.00	\$	187.50
F2	5/17/04	Helper for B-hoe, pick up trash and load junk	3.75	\$	20.00	\$	75.00
F11	5/7/04	P&A marker, purchase	1.0	\$	120.00	\$	120.00

Third Party Services:

Salvage Credit:

1.33 . [89]

> S1 Salvage, 2-3/8" EUE tubing, 42 joints, fiberglass lined ok for Patross Charle There

1178 0.70 (824.60)

\$ 10.162.82

6.3750%

THANK YOU

TOTAL DUE \$ 10,810.70

BEPUTY OIL & GAS INSPECTOR, DIST.

ORIGINAL SIGNED BY CHAPLIE T. PERFIEM

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



Sundry Notices and Reports on Wells

			5.	Lease Number 14-20-603-734
1.	Type of Well WIW		6.	If Indian, All. or Tribe Name Navajo
2	Name of Operator		7.	Unit Agreement Name Horseshoe Gallup Unit
	Vulcan Minerals & Energy, c/o NMOCD, Aztec District Office	•		•
3.	Address & Phone No. of Operator		8.	Well Name & Number HGU #07
	1000 Rio Brazos Road, Aztec, NM 87410 505-334-6178		9.	API Well No . 30-045-10383
4.	Location of Well, Footage, Sec., T, R, M		10.	Field and Pool Horseshoe Gallup
	1980' FNL, 2067' FWL, Sec. 30, T31N, R16W	•	11.	•
	CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOT	ICE, REPORT, OTH	IER D	ATA
	Type of Submission Type of Action			
	Notice of Intent Abandonment	_ Change of Plans		
	Recompletion	_ New Construction		
	X Subsequent Report Plugging Back	_ Non-Routine Fract	uring	
	Casing Repair	_ Water Shut off	4.7	
	Final Abandonment Altering Casing Other -	Conversion to Injec	tion	
13.	Describe Proposed or Completed Operations	NINACA 40	70. 0.	
	A-Plus Well Service Plugged and Abandoned the abo Purchase Agreement Number: 41-521-0700028; Purch			
5/4/0	MOL. RU. Layout relief line to steel pit. No pressure on v	well. ND wellhead.	Releas	se packer. NU BOP
	with companion flange, test. Shit in well. SDFD.			
5/5/0	3 37;			
5/6/0				
	round-trip 5-1/2" casing scraper to 1366'. TIH and set 5			
	load casing with 5 bbls of water. Circulate well clean wi			
	500#, held OK. Plug #1 with CR at 1366', spot 34 sxs of		abov	e CR up to 1073 to
5/7/0	isolate Gallup interval. TOH with tubing. Shut in well. SDI		o bolo	o at 194' Establish
3/1/(74 Held JSA. No pressure on well. RU A-Plus wireline truck. circulation out bradenhead with 6 bbls water. Pump addit			
	clean. Plug #2 with 69 sxs cement pumped down the 5-1			
	cement out bradenhead. ND BOP. Dig out and cutoff	wellhead Found c	iu Sui ment	down 25' in 5-1/2"
	casing and at surface in annulus. Mix 17 sxs cement to			
	MOL.	r iii odomig ana mot	a a	r markor. 110 and
	V. Euintille, Navajo Minerals, B. Freeman, Navajo EPA, an	d H. Villanueva, NM	OCD,	were on location.
SIC	ENATURE William F / Can Contractor		M:	ay 31, 2004
	William F. Clark			
	n de la companya de La companya de la co			
	ter and the second of the seco	getter in the	· · · · · · · · · · · ·	*
	s space for Federal or State Office use)			
	ROVED BY Title			Date
C(C)	IDITION OF APPROVAL if any			

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499 505-325-2627 • FAX (505) 325-1211 22403

Rig No	Date 05/04/04 Day TUE
Well Name HORSESHOE GALLUP UNIT	Company PLAYA MINERALS & ENERGY

FROM TO DESCRIPTION OF OPERATION **H**:30 2:30 ROAD RIG AND EQUIPMENT TO LOCATION 2:30 3:30 SPOTRIG. RIGUP 3:30 4:00 MIPPLE UP FLOWLINES TO PIT OPEN WELL (NO PRESSURE) 4:00 NIPPLE DOWN WELLHEAD. 4:30 RELEASE PACKER. 4:30 NIPPLE UP BOP/COMPANION FLANCE. TEST RAMS 5:30 SECURE WELL. 5:30 6:30 TRAVEL TO YARD.

Fuel & Motor Oil	Water Hauled
Rental Equipment	Cement Retainers
Cementing:	
Wireline	

1/2 day

CREW!	NAME	UNIT #	MILEAGE	HOURS
Supervisor	MIKE HIGDON	#21	•	
Operator.	JESUS JACOBO	# 49		7.0
Helper.	LORENZO RUDRIGUEZ			7.0
Helper	ADAN REYES			7.0
Helper	CHRIS MONTANEZ			7.0
Trainee:				

RCi Form - 0801114A

A - PLUS WELL SERVICE P.O. BOX 1979 • FARMINGTON, NM 87499 505-325-2627 • FAX (505) 325-1211

22404

Rig No_	9		Date <u>05/05</u>	/ 04 Day v	NED
Well Nam	e Horses	SHOE GALLUP UNIT #07	Company PLAY	A MINERALS &	ENERGY
FROM	то	DESCRIPTION	OF OPERATION		
5:30	5:45	LOAD RIG SUPPLIES			*
5:45	6:45	TRAVEL TO LOCATION		, , , , , , , , , , , , , , , , , , ,	
6:45	7:15	START RIGAND EQUIPMENT, HA	LD PRE-JOB SAFETY	MEETING.	
7:15		OPEN WELL . FLOWING OIL UP			
	9:00	LAY DOWN 15 JTS 2 18 TBG,			cup,
9:00		POWER TONGS HIGH SPEED MUTO	2 WENT OUT.		
	10:00	RIG DOWN POWER TONGS.			
10:00	10:30	SECURE WELL.			- · · · · · · · · · · · · · · · · · · ·
10:30	11:30	TRAVEL TO YARD.			
	1				
					N
	<u> </u>				
11390	ļ	Busine Florida Langella Maria	<u> </u>	er ja jak	
	-				
		·			
				····	
		HENRY VILLANUEVA /NMOCO)		
	·	VAL EUINTIELIE /NAVATO MINERALS	ON LOCATION		
	ļ	LERDY LEE / NAVAJO EPA)		
	<u> </u> -				
Fuel & Mc	ntor Oil	Water	Hauled		
		Cemel			
		,			······································
	9				
CRE		NAME	UNIT #	MILEAGE	HOURS
Superv	isor			MILEAGE	HOURS
Operato		MIKE HIGDON	H 21		+
		JESUS JACOBO	*19		6.0
Helper		ORENZO RODRIGUEZ			6.0
Holoor				1	1

6.0 ADAN REYES Helper 6.0 MONTANEZ" Trainee

ACI Form - 0801114A

P.O. BOX 1979 • FARMINGTON, NM 87499 505-325-2627 • FAX (505) 325-1211

Rig	No :	#9		

Date 05/06/05 Day THU

Well Name HORSESHOE GALLUP UNIT #07

Company PLAYA MINERALS & ENERGY

93/4 hr

FROM	то	DESCRIPTION OF OPERATION
5:30	5:45	LOAD RIL SUPPLIES
		TRAVEL TO LOCATION
		START RIC AND EQUIPMENT HELD PRE-JOB SAFETY MEETING
7:15	7:30	OPEN WELL (NO PRESSURE)
7:30		RIC UP TBG TONGS (27)
8:00		LAY DOWN 28 JTS - 21/8" TBG AND 51/2"AD-1 PACKER (43 JTS TOTAL)
	8:45	(PACKER HANGING UP AND DRAGGING)
8:45		PICK UP AND TIH/ 51/2" CSG SCRAPER AND 43 JTS -23/8"A.PCUS
	9:45	WORK STRING. EUT @ 1366'
9:45	10:30	TON/ TBG AND ESG SCRAPER
10:30		TIH / 5 1/2" DHS CRT AND 43 JTS TBG. SET CRT @ 1366; STING OUT
	11:30	of CRT.
11:30	75 M 15	PUMP 51/2 BBLS WATER DOWN TECTO CIRCULATE OUT CSG. CIRCULATE CLEAN
-		WITH ANADOMONAL 29 BBLS WATER PRESSURE TEST CSC TO STOPS!
	12:30	HELD PRESSURE 5 MIN. NO PRESSURE LOSS. BLED PRESSURE OFF.
12:30	3:00	STING JUTO CRT, INSECT CONTENTS OF PIT BELOW CRT. STING OUT OF CRT.
3:00		PLUG #1- MAY AND PUMP 34 EXS CAT FROM 1366 TO TOC @ 1073
	3:30	DISPLACE.
3:30		LAY DOWN THE AND STINGER
		S ECUITE WELL.
4:30		TRAVEL TO YARD
,		
		VAL EMINTILLIE NAVASO MINERALS
		LEROY LEE NAVAJO EPA
		HENRY VILLANUEVA / NMOCO
		' ,

Fuel & Motor Oil

Rental Equipment

Cement Retainers 51/2 OHS @ 1366

Cementing PLUG #/- 34 SxS

CREW	NAME	UNIT#	MILEAGE	HOURS
Supervisor	MIKE HIGDON	#2/		
Operator	JESUS JACOBO	#19		12.0
Helper	LORENZO RODRIGUEZ			12.0
Helper	ADAN REYES			12.0
Helper	CHRIS MONTANEZ			12.0
Trainee				

RCI Form - 0801114A

P.O. BOX 1979 • FARMINGTON, NM 87499 505-325-2627 • FAX (505) 325-1211

Pig No_#9	Date <u>05/07/09</u> Day <u>FRI</u>
Wall Name HORSESHOE GALLED LIVET #07	Company PLAYA MINERALS RENERGY

1 hr 7

6 1/4 ha

5:45		A. A
		LOAD RIG SUPPLIES
LIAC	6:45	TRAVEL TO LOCATION
0.73	7:15	START RIG AND EQUIPMENT, HELD PRE-JOB SAFETY INSETING
7:15		OPEN WELL (NO PRESSURE)
		RIG UP WIRELINE, RIH/WIRELINE. PERFORATE 2- 2/8 BI-WIRE SQUEEZE
	8:00	HOLES @ 184'. POH/ WIRELINE RIG DOWN WIRELINE.
8:00		PUMP 5/2 BBLS WATER DOWN CSG TO CIRCULATE OUT BRADENHEAD.
		CIRCULATE CLEAN/ AN ADDITIONAL 13 BBLS
8:30	· · · · · · · · · · · · · · · · · · ·	PLUL "2 - MIX AND PUMP 69 SXS CMT DOWN CSG TO CIRCULATE
	9:00	COOD CAT OUT BRADEN HEAD
	9:30	NIPPLE DOWN BOP.
9:30		DIG OUT AND CUT OFF WELLHEAD CMT@ 25 IN 5/2 CSC
		PLACE PLA MARKER / 17 SYS CMT @ SURF IN 83/80
11:30	1:00	RIG DOWN CUT OFF RIG ANCHOLS
		1
	14	
		115-20-1
		HENRY VILLANUEVA/NMOCA
		VAL EMINTILLE / NAVAJU EPA ON LUCATION

Fuel & Motor Oil	Water Hauled
Rental Equipment	Cement Retainers
Cementing PLuc # 2 - 69 5x5 P+	A MARKER /17 5×5
Wissing 7-21/8" QI-WIRE SALCON IL	(0 184' (An 11)

CREW	NAME	UNIT#	MILEAGE	HOURS
Supervisor	MIKE HIGDON	[#] 21		
Operator	JESUS JACOBO	¥19		7.5
Helper	LURENZO RUDRILLEZ			7.5
Helper	ADAN REYES			7.5
Helper	CHRIS MONTANEZ	·		7.5
Trainee				

RCI Form - 0801114A

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499 505-325-2627

Event: #1	From: HGu #10 To: HGU #07	Hours
Start:		nours
05/09/04	What: HAUL FODAT #98 AND PIT # 515 TO LOCATION AND SPOT IN PLACE	
<i>00/04/04</i> Stop:	Charge to: PLAYA MINERALS & ENERGY % NMOCO	2.0
ж.	Charge to Lain Minnernes & Breken 70 motors	1 2 . 0
Event: #2	From: H6u #07 To:	
Start:	What: STANDBY FOR RIGHTRUCK MINE Chris	<u> </u>
05/06/09	57,2-3	ļ
Stop:	Charge to: PLAYA MINERALS GENERGY YONMOCD	12.0
Event: #3	From: HGu 4007 To:	T
Start:	What: STANDBY FOR RIGHT TRUCK	
05/07/04	Office of the second se	
Stop:	Charge to: PLAYA MINERALS & ENERGY % NANOCI	2.0
		1
Event: #4	From: To:	
Start:	What:	-
04	Characteristics	
Stop:	Charge to:	<u> </u>
Event: #5	From: To:	
Start:	What:	
Stop:	Charge to:	
- 4 40	T-	T
Event: #6	From: To:	
Start:	What:	<u> </u>
Stop:	Charge to:	
stop.	Onarge to:	<u> </u>
Event: #7	From: To:	
Start:	What:	
Stop:	Charge to:	
vent: #8	From: To:	T T
Start:	What:	
, tu, t.		
Stop:	Charge to:	-
		1
1 15	Driver' May Cities	6.0
Diesel:	Driver: MIKE HIGDON Helper	6. 0
Oil:	NM MILES: CO MILES: UT MILES:	
/n.	OU WILES. UT WILES:	<u> </u>
Remarks:		<u> </u>
	NMOCO HSW #7	
······································		
	Bigup truck to hand workstrang	
	Bigup truck to haul workstrang	
ellegery Transport Agency	& Steel pit	<u> </u>

F1.2 F1.5

A - PLUS WELL SERVICE

22407

	DECONDITION OF OPENATION
Well Name Horseshor GALLUP UNIT #29	Company PLAYA MINERALS & ENERGY
Rig No	Date 05/07/04 Day FRI
1	1979 • FARMINGTON, NM 87499 25-2627 • FAX (505) 325-1211

FROM	то	DESCRIPTION OF OPERATION
1200	5:00	ROAD RIG AND EQUIPMENT TO LOCATION
5:00	6:00	TRAVEL TO YARD (Crew Travel)
*		
	-	
	1	
10		7.5
*** *		Section 1990 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	<u> </u>	
	 	
		(Ingt #19 5 600 sened #67
	 	Vives 11 200 state 01
	 	
	1	Houl tubing to At gail
		frank fusing 10 ft gard
	ļ	7 cross
		HS64#7 - /h @50
	1	1/360" / - / M & 30
		b cv
		456'U # 10 - 1 m @ 50
	ļ	
	ļ	

Fuel & Motor Oil_ Water Hauled _ Rental Equipment _____ _ Cement Retainers __ Cementing _ Wireline _

CREW	NAME.	UNIT#	MILEAGE	HOURS
Supervisor	MIKE HIGOON	#21-		
Operator	JESUS JACOBO	#19		5,0
Helper	LORENZO RODRIGUEZ			5.0
Helper	ADAN REYES			5.0
Helper	CHRIS MONTANEZ			5.0
Trainee	Community of the second of the			

, RCI Form - 0801114A

A-Plus Well Service, Inc.P.O. Box 1979, Farmington, NM 87499
505-325-2627

Date: <u> </u>	Truck #: _	<u> </u>
Event: #1	From: A - plus To:	Hours
Start: 5,30	What: Pre CK 965	
	·	15
Stop: 4:00	Charge to: $NMOCD$.	
vent: #2	From: A-plus To: Horse store Gallup	<u> </u>
Start: 6:00	What: harlal I lead From Farriton hydrat	6
	hand local Front Ship rock	
Stop: / 4:00	Charge to: $\mathcal{N}, \mathcal{M}, \alpha, c, \mathcal{D}$	
vent: #3	From: Horse stor Collyp To: A-phio	
Start: 19,00	What: Road Tine 15	
		1,5
Stop: 1.30	Charge to: NATO CD	
Event: #4	From: To:	
Start:	What:	
Tall is at the day of management than		
Stop:	Charge to:	
event: #5	From: To:	<u> </u>
Start:	What:	
Stop:	Charge to:	
vent: #6	From: To:	,
Start:	What:	
Stop:	Charge to:	
vent: #7	From: To:	
Start:	What:	\neg
Stop:	Charge to:	
vent: #8	From: To:	
Start:	What:	
		-
Stop:	Charge to:	
		·· · · · · · · · · · · · · · · · · · ·
	Driver: Le Ro, Mare Z	8
Diesel:	Helper 48 /0 =	
Oil:	NM MILES: 52 CO MILES: UT MILES:	
Remarks:		
	NMMCD #7	
	Harl 2 locals 41 h	
,	1 min 1 NOTHEN 16 TO	
	Central Sant	
	1,10 h	A
	I deli feeret	10 de

P.O. Box 1979, Farmington, NM 87499 505-325-2627

Date:				
Event: #1	From: HGU #10 To: HGU #07	Hours)	
Start:	What: HAUL I LOAD FRESH WATER AND		F6.b	
05/04/04	STAND BY		<i>P</i> •	
Stop:	Charge to: PLAYA MINERALS & ENERGY GONMOCD	7.0		
Event: #2	From: #6u#07 To:		_	
Start:	What: HAUL 1 LOAD FRESH WATER AND		// (,	
05/06/04	STANDBY		16°	
Stop:	Charge to: PLAYA MINERALS & ENERCY GU MMOLD	2.0	F6 C	
Event: #3	From: HGu #07 To:		.1	
Start:	What:		1 d	
05/07/04	STANDBY / FRESH WATER		16	
Stop:	Charge to: PLAYA MINERALS & ENERGY YO NMOCE	20		
Event: #4	From: To:			
Start:	What:		·	
Stop:	Charge to:			
	Jonatge to.			
Event: #5	From: To:			
Start:	What:			
C4	Champa Ass			
Stop:	Charge to:			
Event: #6	From: To:			
Start:	What:			
Stop:	Charge to:			
1. 1		Jan 1988 Propinsi Santa S	*.	
Event: #7	From: To:			
Start:	What:			
Stop:	Charge to:			
E	T	1		
Event: #8 Start:	From: To:			
Start.	wind.			
Stop:	Charge to:			
	Driver: MKEHIGDON	5 .0		
Diesel:	Helper			
Oil:	NM MILES: CO MILES: UT MILES;			
Remarks:				
	NMOCO HSW #7			
	Water Louer for I lone of			
	fresh water loved of		194 2	
	great water			

P.O. Box 1979, Farmington, NM 87499 505-325-2627

Date:	Truck :	#: <u>#</u> 155
Event: #1	From: AGU#10 To: HGU#07	Hours
Start:	What: TRAVEL TO LOCATION AND	
05/04/04	STANDRY FOR DISPOSAL	
Stop:	Charge to: PLAYA MINERALS & ENERLY YOUNDED	2.0
vent: #2	From: HGU #07 To:	
Start:	What: STANDRY FOR DISPOSAL	
05/06/04		
Stop:	Charge to: PLAYA MINERALS & ENERGY YO MACO	2.0
vent: #3	From: 146u #07 To:	
Start:,	What: STANDBY FOR DISPOSAL	
5/2/04		
Stop:	Charge to: PLAYA MINERALS AFNERGY % NMOCD	20
Event: #4	From: To:	: *··
Start:	What: A Cardon Control of the Architecture of	
Ston:	Charge to	
Stop:	Charge to:	
ent: #5	From: To:	
Start:	What:	
·		
Stop:	Charge to:	
vent: #6	From: To:	
Start:	What:	
Stop:	Charge to:	
event: #7	From: To:	
Start:	What:	
Stop:	Charge to:	
vent: #8	From: To:	
Start:	What:	
Stop:	Charge to:	
		e en ferendi i di
	Driver: MIKE HIGDON	6.0
Diesel:	Helper	
Oil:	NM MILES: CO MILES: UT MILES:	
Remarks:		
	NNOCO HSOUT	
· · · · · · · · · · · · · · · · · · ·	ronder (
	Water four for disposal	
	Water fruit for disposal	
· · · · · · · · · · · · · · · · · · ·	water	
		·
······································		

F6. e F6. f F6. g

A-Plus Well Service, Inc.P.O. Box 1979, Farmington, NM 87499
505-325-2627

Truck #: <u>54</u> Dâte: 5 /7 04

Event: #1	From: D - D - W To:	Hours
Start: 6, 30	From: A-B-W To: What: PRE TAIR UNIT 24 5 87 HOOK UP TO	
	87	1,5
Stop: 7, 60	Charge to:	
Event: #2	From: A.P.W To: CAUE PIPE	T
Start; 7, 60	From: A.P.W To: CAUE PIPE What: Oucono PIPE From THE 295 221	1.5
Stop: 《 : 3신	Charge to:	
Event: #3	From: A-P-W To: USGU # (10)	
Start: 名ごる	What: CLEAN # LOCATION "DONE"	
Stop: /0,'60	Charge to:	
	From: \$1560 \$ 10 To: \$1560 \$7 9	
	What: CLOAN LOCATION CONE"	多荟
Programme Company		3.25
Stop: / 45	Charge to:	
Event: #5	From: HSEU* 5 Tg: HSEU* 7)	
Start: /. 45	From: HSEU# S TO HSEU# 7) What: # CLOAN LOCATION FOONE	3.35
2		3.75
Stop: 4.145	Charge to:	
Event: #6	From: To:	
Start:	What:	
Stop:	Charge to:	
	From: To:	
Start:	What:	·
Stop:	Charge to:	
	From: To: What:	
Stop:	Charge to:	
		11
	Driver: DUANE CASTIN	11.5
	Helper TASEN BIZZELL	11.5
Oil:	NM MILES: SO CO MILES: UT MILES:	L
Remarks:	SO HWY - 20 DIRT	
- .	# (\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
	75647	
15/1	('lean Up)	
4.0		-
	14-21 Der 3	Alle

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 FARMINGTON, NM 87499 505-325-2627 • FAX: 505-325-1211

April 30, 2004

CAVE Enterprises

PO Box 79 Flora Vista, NM 87415

Invoice #3279

Rig #9

For used rods and tubing from **Horseshoe Gallup Unit** wells, located in Section 29, T31N, R16W, San Juan County, NM.

This material was credited to NMOCD on the appropriate invoice.

Cost Summary:

HSGU: Well	ry: Feet	Type and Size	V	alue	9	Salvage
#244	1116	36 joints 2-3/8" tubing	\$	0.80	\$	892.80
#242	992	32 joints 2-3/8" tubing	\$	0.80	\$	793.60
#8	1240	40 joints 2-3/8" tubing, heavy paraffin inside	\$	0.60	\$	744.00
#9	1178	38 joints 2-3/8" tubing, heavy paraffin inside	\$	0.60	\$	706.80
#220	1178 47	38 joints 2-7/8" tubing 3/4" used sucker rods, plain	\$ \$	0.90 5.00	\$ \$	1,060.20 235.00
# 7	1302	42 joints 2-3/8" tubing, fiberglass lined	\$	0.70	\$	911.40
#10	1178	38 joints 2-3/8" tubing, heavy paraffin inside	\$	0.60	\$	706.80
#271	1271	41 joints 2-3/8" tubing, heavy paraffin inside	\$	0.60	\$	762.60
#246	1240	40 joints 2-3/8" tubing, heavy paraffin inside	\$	0.60	\$	744.00
		and Market and American Cantagest of the Market and American American Cantagest of the Market and American American American American		•	\$	7,557.20
in the state	A Harrison	100 00 00 00 00 00 00 00 00 00 00 00 00				

NM TAX Exempt - Resale

TOTAL DUE

\$ 7,557.20

THANK YOU