Form 3160-5 (April 2004)

Notice of Intent

determined that the site is ready for final inspection.)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

## SUNDRY NOTICES AND REPORTS ON WELLS

Alter Casing

Casing Repair

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007
--

Well Integrity

Other TD &

		Expires:	March	31,	200
5	Lease Seria	i No.			

	٠.	LIMBO DE INILITA.		
14-20-603-2198				
•				

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name 13 <sub>Navajo</sub>		
			7. If Unit or CA/Agreement, Name and/or No.		
	Gas Well Other	070 FARMINGTON	NA 8. Well Name and No. NV Navajo 24 #1		
Name of Operator Richardson Operating Company  3a Address  3b. Phone No. (include area code)			9. API Well No. 30-045-31390		
3100 La Plata Highway, Farmington, NM, 87401 505-564-3100  4. Location of Well (Footoge, Sec., T., R., M., or Survey Description)			10. Field and Pool, or Exploratory Area West Kutz PC & Basin FC		
704' FNL, 1021' FEL, Sec. 24	, T29N, R14W		11. County or Parish, State  San Juan County, New Mexico		
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATURE OF NOTICE, R	EPORT, OR OTHER DATA		
TYPE OF SUBMISSION		TYPE OF ACTION			
	Acidize	Deenen Production (St	art/Resume) Water Shut-Off		

Recomplete Subsequent Report Production csg. Change Plans Temporarily Abandon Plug and Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once

testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has

New Construction

Fracture Treat

Reclamation

6/7/04 NU BOP, test BOP and surface casing to 600psi, held OK. Drill 372' of new 6 1/4" hole to 500'. Secure rig, SDFN. 6/8/04 Drill 718' of 6 1/4" hole to 1218'. TD well. TOH with DP/DC and bit. Secure rig, SDFN.

6/9/04 Run 42 joints of 4 1/2" 10.5# J-55 production casing. Land production casing at 1207' + 1' GL. Cement production casing with 100 sx Class B cement with 2% Sodium Metasilicate, 1/4#/sk celloflake, 12.50ppg, 2.06 yield, as lead. Tail in with 70 sx Class B cement with1/4#/sk celloflake, 15.60ppg, 1.18 yield. Circulate 15 bbl to surface. Bump plug with 800psi, shut in, WOC.



			<u>,                                    </u>	, C	<del>}</del>
14. Thereby certify that the foregoing is true and correct Name (Printed/Typed)  To Becksted	Title	Cone	Slund	2	ad new.
Signature OV Bloksted	Date		07/16/2004		ACCEPTED FOR RECORD
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by		Title		Date	JUL 2 3 2004
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office		FARMINGTON FIELD OFFICE BY	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.