Submit 3 Copies To Appropriate District Office District I 1625 N. French Dr. Hobbs NM 88240 State of New Mexico Energy, Minerals and Natural Resources WELL API NO.	ነ 102
DISUICE I A DE NO	
	1, 2004
20 045 29565	
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION 5 Indicate Type of Lease	
District III 1220 South St. Francis Dr. STATE V DEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505 6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505 K-5808	
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement N	ame
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) PORTUGE Albino Canyon PROPOSALS.)	
l m cry u	
Oil Wall Gos Well Y Other \\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
1. Type of Well: Oil Well Gas Well X Other 2. Name of Operator Burlington Resources Oil & Gas Company LP 3. Type of Well: 4. Type of Well: 5. JUL 2006 9. OGRID Number 6. 14538	
2. Name of Operator Burlington Resources Oil & Gas Company LP 3. Address of Operator On On Operator 19. OGRID Number 14538 3. On Operator 10. Pool name or Wildcat	
3. Address of Operator P.O. Roy 4280 Forwington NIM 87400 4280	
P.O. Box 4289, Farmington, NM 87499-4289	
4. Well Location	
Unit Letter A: 1090 feet from the North line and 830 feet from the East line	
Offit Letter A . 1090 leet from the North line and 830 leet from the East line	
Section 36 Township 32N Range 8W NMPM San Juan County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)	
Pit Location: ULSectTwpRngPit typeDepth to GroundwaterDistance from nearest fresh water well_	
Distance from nearest surface water Below-grade Tank Location UL Sect Two Rng :	
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng ; feet from the line and feet from the line	
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng; feet from the line	
feet from theline andfeet from theline	
feet from theline andfeet from theline 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
feet from theline andfeet from theline 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	G []
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	G 🗆
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	G 🗆
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND	G 🗆
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CEMENT JOB CEMENT JOB	G 🗆
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: LOG detail	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: LOG detail 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estima of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed com	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: LOG detail	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: LOG detail 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estima of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed components.	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: LOG detail 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estima of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed com	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: LOG detail 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estima of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed con or recompletion. PUMP REPAIR 5/17/04 MIRU TJR #5. COOH w/pump & rods. ND WH & NU & test BOP-OK. Tagged up, no fill. TOH w/tbg. TIH w/2-3/8"	ted date apletion
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: LOG detail Indicate Nature of Notice, Report or Other Data OTHER: LOG detail Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASIN CASING TEST AND CASING TEST AND CEMENT JOB OTHER: LOG detail Indicate Nature of Notice, Report or Other Data OTHER: LOG detail Indicate Nature of Notice, Report or Other Data Altering CASIN OTHER: LOG detail Indicate Nature of Notice, Report or Other Data OTHER: LOG detail Indicate Nature of Notice, Report or Other Data OTHER: LOG detail Indicate Nature of Notice, Report or Other Data OTHER: LOG detail Indicate Nature of Notice, Report or Other Data OTHER: LOG detail Indicate Nature of Notice, Report or Other Data OTHER: LOG detail Indicate Nature of Notice, Report or Other Data OTHER: LOG detail Indicate Nature of Nature of Nature or Other Data OTHER: LOG detail Indicate Nature of Nature of Nature or Other Nature or Other Data OTHER: LOG detail Indicate Nature of Natur	ted date apletion
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: LOG detail 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estima of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed con or recompletion. PUMP REPAIR 5/17/04 MIRU TJR #5. COOH w/pump & rods. ND WH & NU & test BOP-OK. Tagged up, no fill. TOH w/tbg. TIH w/2-3/8"	ted date apletion
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: LOG detail 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estima of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed con or recompletion. PUMP REPAIR 5/17/04 MIRU TJR #5. COOH w/pump & rods. ND WH & NU & test BOP-OK. Tagged up, no fill. TOH w/tbg. TIH w/2-3/8" J-55 tbg & set @ 3476' w/SN set @ 3437'. ND BOP, NU WH. TIH w/pump & rods. PT tbg to 500 psi -OK. RU pumping equi & released rig @ 1200 hrs 5/18/04.	ted date apletion , 4.7# p. RD
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: LOG detail CEMENT JOB OTHER: LOG detail CEMENT JOB 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estima of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed con or recompletion. PUMP REPAIR 5/17/04 MIRU TJR #5. COOH w/pump & rods. ND WH & NU & test BOP-OK. Tagged up, no fill. TOH w/tbg. TIH w/2-3/8" J-55 tbg & set @ 3476' w/SN set @ 3437'. ND BOP, NU WH. TIH w/pump & rods. PT tbg to 500 psi -OK. RU pumping equilable released rig @ 1200 hrs 5/18/04. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit of	ted date upletion 4.7# p. RD
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: LOG detail 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estima of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed con or recompletion. PUMP REPAIR 5/17/04 MIRU TJR #5. COOH w/pump & rods. ND WH & NU & test BOP-OK. Tagged up, no fill. TOH w/tbg. TIH w/2-3/8" J-55 tbg & set @ 3476' w/SN set @ 3437'. ND BOP, NU WH. TIH w/pump & rods. PT tbg to 500 psi -OK. RU pumping equi & released rig @ 1200 hrs 5/18/04.	ted date upletion 4.7# p. RD
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: LOG detail CEMENT JOB OTHER: LOG detail CEMENT JOB 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estima of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed con or recompletion. PUMP REPAIR 5/17/04 MIRU TJR #5. COOH w/pump & rods. ND WH & NU & test BOP-OK. Tagged up, no fill. TOH w/tbg. TIH w/2-3/8" J-55 tbg & set @ 3476' w/SN set @ 3437'. ND BOP, NU WH. TIH w/pump & rods. PT tbg to 500 psi -OK. RU pumping equilable released rig @ 1200 hrs 5/18/04. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit of	ted date upletion 4.7# p. RD
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CEMENT JOB CEMENT JOB OTHER: LOG detail CEMENT	ted date upletion 4.7# p. RD
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: LOG detail 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estima of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed con or recompletion. PUMP REPAIR 5/17/04 MIRU TJR #5. COOH w/pump & rods. ND WH & NU & test BOP-OK. Tagged up, no fill. TOH w/tbg. TIH w/2-3/8" J-55 tbg & set @ 3476' w/SN set @ 3437'. ND BOP, NU WH. TIH w/pump & rods. PT tbg to 500 psi -OK. RU pumping equi & released rig @ 1200 hrs 5/18/04. Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit ograde tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved p	ted date upletion 4.7# p. RD
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMPLETION CASING TEST AND CEMENT JOB OTHER: LOG detail CEMENT JOB OT	ted date upletion 4.7# p. RD
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CEMENT JOB CEMENT JOB OTHER: LOG detail CEMENT	ted date upletion 4.7# p. RD