

PN (ROOMS)

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

OIL CONSERVATION DIVISION

**DISTRICT I**  
P.O. Box 1980, Hobbs, NM 88240  
**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210  
**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-031-20735	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. L-6469	
7. Lease Name or Unit Agreement Name  STATE	
8. Well No. 3	
9. Pool name or Wildcat North Miguel Creek Field	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: _____	
2. Name of Operator ROBERT L. BAYLESS	
3. Address of Operator P.O. BOX 168 FARMINGTON, NM 87499	
4. Well Location Unit Letter <u>N</u> : <u>990</u> Feet from the <u>SOUTH</u> Line and <u>1650</u> Feet from The <u>WEST</u> Line Section <u>16</u> Township <u>16N</u> Range <u>6W</u> NMPM <u>MCKINLEY</u> County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6538' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

<b>NOTICE OF INTENTION TO :</b>		<b>SUBSEQUENT REPORT OF :</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Robert L. Bayless plugged and abandoned this well 5/30/03. The procedure is attached.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>Tom McCarthy</u>	TITLE <u>ENGINEER</u>	DATE <u>6/19/03</u>
TYPE OR PRINT NAME <u>Tom McCarthy</u>	TELEPHONE NO. <u>(505) 327-2659</u>	
(This space for State Use) APPROVED BY <u>H. Villanueva</u>	TITLE <u>DEPUTY OIL &amp; GAS INSPECTOR, DIST. 3</u>	DATE <u>SEP - 1 2004</u>
CONDITIONS OF APPROVAL, IF ANY: <u>9-1-04.</u>		

**Robert L. Bayless**  
**Plug and Abandon Report**

State No. 3

990' FSL & 1650' FWL, Section 16, T16N, R6W

McKinley County, NM

5/30/2003: Rig up JC Well Service. Pick up tubing and tally. Trip in and tag PBD at 1258'. Roll hole with water. Mix and spot 23 sack bottom plug at 1258'. Trip out tubing and WOC. Trip in and tag plug at 1102'. Pressure test casing to 200 PSI, OK. Perforated squeeze holes at 134'. Mix and pump 62 sacks cement. Circulated cement up casing and up backside. Rigged down. Class B cement was used.

Top off cement in both casings. Installed abandonment marker and backfilled pit. Cleaned up location.