Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

l			FORM APPROVED
			OM 8 No. 1004-0137
(Expires: March 31, 2007
		 •	

5. Lease Serial No. NMSF-079065

Do not upo M	ala daum dan mususasis		_	C 101 11	A 54
Do not use the abandoned w	1	Allottee or Tribe Name			
\$			MAIL OFF OF	NA DD O	21
SUBMIT IN TR	IPLICATE- Other inst	ructions on reve	TSA SIDA	7. If Unit or	CA/Agreement, Name and/or No.
1 7 637-11				1	,
1. Type of Well Oil Well	Gas Well Other	į	RECE	1VF1)	
			OZO SADAH	8 Well Nan	
2. Name of Operator Richardson (04 C		OTO TANIM	FRPC	i9 ^{-#} 1
*	Operating Company			9. API We	l No.
3a Address		3b. Phone No. (inched	e area code)	30-045-	31269
3100 La Plata Highway, Farmi	ington, NM, 87401	505-564-3100	الان أون الان الأن الأن الأن الأن الأن الأن الأ	10. Field and	Pool, or Exploratory Area
4. Location of Well (Footage, Sec.,	T. R. M. or Survey Description)	105	~ ⁶ 77,5 ~	T WALLEY.	itz PC & Basin FC
			2004	11 County o	r Parish. State
1265' FNL & 1420' FEL, Sec.	19 , T29N, R13W		0.3	11. County C	Turan, Suit
				San Jua	n County, New Mexico
12. CHECK AI	PPROPRIATE BOX(ES) TO	INDICATE NĂŢŪ	E OF NOTICE, R	EPORT; OR	OTHER DATA
TYPE OF SUBMISSION		ΤΫ́	PE OF ACTION		
	Acidize	Deepen	Production (Sta	nt/Resume)	Water Shut-Off
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	·	Well Integrity
-	 				Other Spud, Surface csg.
Subsequent Report	Casing Repair	New Construction	Recomplete		
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Ab	oandon	Production csg & TD
	Convert to Injection	Plug Back	Water Disposal		
Attach the Bond under which the following completion of the inv	ectionally or recomplete horizontal the work will be performed or provolved operations. If the operation all Abandonment Notices shall be	lly, give subsurface location ride the Bond No. on file values in a multiple communication.	ns and measured and tru with BLM/BIA. Require eletion or recompletion i	ne vertical depthe ed subsequent re in a new interval	of all pertinent markers and zones. ports shall be filed within 30 days a Form 3160-4 shall be filed once
casing, three joints plus 12 Cement surface casing wit WOC. 8/25/2004 NU BOP. Test Secure rig, SDFN. 8/26/2004 Test BOP blind cement from 75' to 127'. I 8/27/2004 Open BOP. Dr Secure rig, SDFN. 8/28/2004 TOH with DC/I 1133'. Seven centralizers	Drill 373' of 6 1/4" 500'. Clos ill 675' of 6 1/4" hole to 1175'	ther joint. Land surfact 3% CaCl2, 1/4#/sk cell 10psi, leak on casing. F 10si leak off in 30 minute 12 BOP. Secure rig, SD 12 TD well. Run wireli 12 11.6# J-55 product 12, seven turbolizers eve	e casing at 121'-1' G oflake, 15.60ppg, 1.1i teplace four valves of es. Test kill manifold FN. ne survey at 1175' = 1 on casing. Land pro- cry other joint from t	EL. Circulate of Byield. Circular will manifold it, test wellhead 1 1/4 degree. Studential to the casing top. Rig up cer	well clean. MIRU cementers. late 4 bbl cement to surface. l. Test to 600psi, slow leak. l. Replace pump gauge. Drill Short trip and close BOP. late 1164' +1' GL. Float shoe at menters. Cement production

14. I hereby certify to Name (Printed	hat the foregoing is true and correct (Typed)	1		
Jo Be	cksted	Title Compliance Admin	istrator	
Signature C	o becketed	Date	09/23/2004	ACCEPTED FOR RECORD
	THIS SPACE FOR FEDERAL	OR STATE OFFIC	E USE	2004
Approved by		Title		Date 2 7 2004
Conditions of approva certify that the applica	I, if any, are attached. Approval of this notice does not warra nt holds legal or equitable title to those rights in the subject le	ont or Office		FARMINGIUM FIELD OFFICE BY

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)