Form 3160-3 (August 1999)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

NMSF078	505
6 If Indian Al	lattae or Tribe Name

**SUNDRY NOTICES AND REPORTS ON WELLS** 

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRI	PLICATE - Other instru	ctions on reverse	side.		7. If Unit or CA/Agree	ement, Name and/or No.	
1. Type of Well			SEP	200	R. Well Name and No.		
Oil Well Gas Well Other		TAMAY IONES	<u>,, , , ,                             </u>	2004	D. API Well No.		
		TAMMY JONES E-Mail: twimsatt@br-	-Mail: twimsatt@br-inc.com			30-045-31803-00-S1	
3a. Address PO BOX 4289 FARMINGTON, NM 87499	3b. Phone No. (included) Ph: 505.599.406 Fx: 505.599.4064						
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Descriptio	on)	J.3.2.	استقلطعه	11. County or Parish,	and State	
Sec 24 T31N R9W SESW 10	65FSL 1940FWL				SAN JUAN COL	JNTY, NM	
12. CHECK APPI	ROPRIATE BOX(ES) T	O INDICATE NAT	URE OF NO	OTICE, REF	PORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
N	Acidize	Deepen	······································	☐ Productio	n (Start/Resume)	☐ Water Shut-Off	
□ Notice of Intent	Alter Casing	Fracture T		Reclamation		☐ Well Integrity	
Subsequent Report	Casing Repair	☐ New Cons		Recomple		Other Workover Operations	
Final Abandonment Notice	Change Plans	Plug and A		☐ Temporarily Abandon		Workover Operations	
_	Convert to Injection	□ Plug Back		☐ Water Disposal			
determined that the site is ready for f (8/19/04) MIRU. ND WH. NU (8/20/04) TIH w/CIBP, set @ wtr. Test csg & CIBP to 4000 SDON. (8/23/04) Frac Dakota w/2466 hole, test CIBP to 4000 psi, C Frac Point Lookout w/1153 bt Menefee @ 5071-5340' w/1 S 100,000# 20/40 sand. Flow bs (8/24/04) Flow back well. (8/25/04) ND frac valve. NU E sand @ 5825'. Est circ. Mill C	BOP. TOOH w/2-3/8" tbg 7800'. ND BOP. NU frac psi, OK. Perf Dakota @ 6 bbls slickwater, 40,000; 6K. Perf Point Lookout @ 6 bls slickwater, 100,000# 6 bls sl	valve. Pump 15 bbl 7609-7785' w/2 SPI # 20/40 sand. TIH w ! 5430-5812' w/1 SF 20/40 sand. TIH w/0 s. Frac Menefee w/	F, for a total o //CIBP, set @ PF, for a total CIBP, set @ 5 1032 bbls slice	of 82 holes. § 5860'. Loa of 25 holes 5400'. Perf ckwater,	ıd		
14. I hereby certify that the foregoing is  Col Name (Printed/Typed) TAMMY J	Electronic Submission For BURLINGTON R mmitted to AFMSS for pro	ESOURCES O&G CO	D LP, sent to 1 NASON on 09/	the Farming	ton SXM2034SE)		
Traine (17 mea/1ypea/   Mivily   3	ONLO	Title	REGULA	TORT SPEC	JIALIST		
Signature (Electronic	Submission)	Date	09/15/200	)4			
	THIS SPACE F	OR FEDERAL OI	R STATE OF	FFICE USI			
Approved By ACCEPTED		Title	STEPHEN M PETROLEU		ER	Date 09/15/2004	
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to cond	uitable title to those rights in the operations thereon.	he subject lease Offi	ce Farmingto				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it statements or representations a	a crime for any person las to any matter within i	mowingly and was jurisdiction.	villfully to mal	te to any department o	r agency of the United	

## Additional data for EC transaction #36114 that would not fit on the form

## 32. Additional remarks, continued

(8/26/04) TIH w/mill, tag fill @ 7740'. CO to CIBP @ 7800'. Flow well. (8/27/04) TIH w/RBP, set @ 6000'. Test Mesaverde formation. TOOH w/RBP. SDON. (8/30/04) TIH to CIBP @ 7800'. Est circ. Mill out CIBP @ 7800'. Clean out open hole @ 7836-7890'. TOOH w/mill. SDON. (8/31/04) TIH w/239 jts 2-3/8" 4.7# J-55 tbg, set @ 7823'. ND BOP. NU WH. RD. Rig released.

The well will produce as a Mesaverde/Dakota commingle under DHC1379AZ.