## 5. Lease UNITED STATES NMNM-03733 DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT 6. If Indian, Allottee or Tribe Name SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different (Do not use this form for proposals to drill or to deepen or plug back to a different (Do not use this form for proposals) 200 SEP 20 PM 12 16 8. Well Name and No. 1. Oil Well [ ] Gas Well [ ] Other [ ] RECEIVED BREECH 377 **GAS WELL** MN NOPPINAMAGE OTO 2. Name of Operator: **Caulkins Oil Company** 30-039-25690-00C5 3. Address of Operator: 10. Field and Pool, Exploratory Area (505) 334-4323 1409 W. Aztec Blvd. Ste B7, Aztec, NM 87410 DAKOTA, GALLUP, PICTURED CLIFFS 4. Location of Well (Footage, Sec., Twp., Rge.) 11. Country or Parish, State 1165' F/S 1025' F/W SEC. 23-26N-7W Rio Arriba Co., New Mexico 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION [ ] Notice of Intent [ ] Abandonment [ ] Change of Plans [ ]Recompletion [ ] New Construction [X] Subsequent Report [X] Plugging Back [ ] Non-Routine Fracturing [ ] Casing Repair [ ] Water Shut-Off [ ] Final Abandonment Notice [ ] Altering Casing [ ] Conversion to Injection 1 Other Dispose Water 17. Describe Proposed or Completed Operations: 9-2-04 Rig up. T. O. H. laying down 2 7/8" tubing. 9-3-04 Continue laying down remainder of 2 7/8" tubing. Rig up wireline truck. R.I.H. with 5 1/2" cast iron bridge plug set at 7331'. R.I.H. with bailer dump 2.2 sacks (2.5 cu. ft.) Type III cement, 7331 Dump 2.2 (2.5 cu. ft.), 7312' to 7293'. Wash up. W.O.C. 9-7-04 R.I.H. with 5 1/2" cast iron bridge plug, tag top of cement at 7292'. Set 5 1/2" cast iron bridge plug at 6353'. ACCEPTED FOR RECORD R.I.H. with bailer dump 2.2 sacks (2.5 cu. ft.), 6353' to 6334'. Shut down rig for repairs. SEP 2 2 2004 (continued on page 2) FARMINGTON FIELD OFFICE NOTE: The format is issued in lieu of U.S. BLM Form 3160-5 18. I HEREBY CERTIFY THE FOREGOING IS TRUE AND CORRECT SIGNED: Robert L. Verquer TITLE: Superintendent DATE: September 16, 2004

TITLE:

DATE:

APPROVED BY:

CONDITIONS OF APPROVAL, IF ANY

Caulkins Oil Company BLM Sundry Notice Breech 377 September 16, 2004 Page 2

9-8-04

R.I.H. with bailer, tag top of cement at 6332'.

Dump 2.2 sacks (2.5 cu. ft.) on top of plug #2, 6332' to 6113'.

R.I.H. with 5 1/2" cast iron bridge plug set at 4539'.

R.I.H. with bailer and 2.2 sacks (2.5 cu. ft.), tag cast iron bridge plug, cast iron bridge plug moved down casing.

Plug moved down to 4564'.

Unable to dump cement, pull out of hole and wash up cement from bailer.

R.I.H. with 5 1/2" cast iron bridge plug, set at 4539'.

R.I.H. with bailer dump 4.5 sacks (5 cu. ft.), 4539' to 4501'.

R.I.H. with cast iron bridge plug, set at 3871'.

R.I.H. with bailer dump 4.5 (5 cu. ft.), 3871' to 3833'.

T. I. H. with 95 joints 1 1/2" EUE tubing.

Land tubing on doughnut at 3031'.

Nipple up wellhead.

Rig down.