L & B Speed Drill, LLC

E & B Speed Dim, LLC	
501 Airport Drive · FARMINGTON, N	EW MEXICO 87401 · (505)564-3111
Date: October 6, 2004	
Fo: Richardson Operating Co. 4601 DTC Blvd. Suite 470 Denver, CO 80237	30-045-31942
Re: Directional Survey	
Below is the directional survey for your wel	Federal 42-10 # 3
859' @ 3/4 ⁰ 2502' @ 1/2 ⁰ 2512' @ 1/2 ⁰	(591071777) (2007)
Acknowle	dgment
State of New Mexico]	
County of San Juan]	- 1 11
Signed & Acknowledged By:	Billie Ferrell, Manager
The foregoing instrument was ackn	owledged before me this day of ary Public
Manufactures: 4/27/2009	2