



37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof: cored intervals; and all drill-stem tests, including depth interval tested on used, time tool open, flowing and shut-in pressures, and recoveries):				38. GEOLOGIC MARKERS			
FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP		TRUE VERT. DEPTH
				Ojo Alamo	MEAS. DEPTH		
				Kirtland			
				Fruitland	---		
				Pictured Cliffs	surface		
					800'		
					1134'		
				TOTAL DEPTH	1270'		