Form 3160-5 (November, 1996)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

- 1	FORM	1 APF	PROV	/ED
0	MB N	No. 10	04-	0135
_				

1996

	Expire	es: Ju	aly 3	٦,
ease Serial	No.	•		_

SUNDRY NOTICES AND REPORTS ON WELLS SF-079060 Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee, or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. NITIL 17 QM 0 00 7. If Whit or CA! Agreethent Designation SUBMIT IN TRIPLICATE- Other Instructions on the reverse side Northeast Blanco Unit 1. Type of Well 87 Well Name and Noc TON NM X Gas Well Oil Well 2. Name of Operator **NEBU 413A** 9. API Well No. Devon Energy Production Co. L.P. Attn: Kenny Rhoades 3a. Address 3b. Phone No. (include area code) 30-039-27299 10. Field and Pool, or Exploratory Area (505)320-6310 1751 Highway 511 Navajo Dam, NM 87419 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) **Basin Fruitland Coal** 11. County or Parish, State 1115' FSL & 1105' FEL SE /4. SE Sec. . T 30N Rio Arriba NM Latitude Longitude CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent Water Shut-off Acidize Deepen Production ( Start/ Resume) Fracture Treat Well Integrity Altering Casing Reclamation Other Subsequent Report Casing Repair New Construction Recomplete Deepen and run liner Change Plans Plug and abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug back Water Disnosal Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required susequnet reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in anew interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.) Devon Energy requests approval to perform the following work on the subject well. MIRU w/ service unit. Remove production rods and tubing string Clean wellbore to PBTD Rig up mud loggers and drill 100' of PC for sump. Logs will be distributed upon completion of work Install 5-1/2" uncemented liner and perforate same through productive coal zones Install production tubing and rod string Return well to sales -sump request granted 11/18/04 CONDITIONS OF APPROVAL SEE ATTACHED FOR CH Adhere to previously issued stipulations. CONDITIONS OF APPRIOVAL 14. I hereby certify that the foregoing is true and correct. Name (Printed/ Typed) Title Kenny Rhoades **Company Representative** Signature

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease

Date

which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitio or fraudulent statements or representations as to any matter within its jurisdiction.

Approved by

## **Conditions of Approval:**

Notice of Intent: to deepen the well 100' for a sump, and install the 5  $\frac{1}{2}$ " liner.

Devon Energy Corporation. NEBU #413A 1115 FSL & 1105 FEL Sec 20. T30N. R7W.

- 1) Refer and adhere to the original permit requirements and the following:
  - a) All workover pits will be fenced during the recavitation operation and fenced close after the completion of the work.
  - b) Pits must be lined with 12 mil, or greater, reinforced liner.
  - c) All coal fines must be confined to the pit. Any off location spray of coal fines must be immediately washed down with fresh water.
  - d) Pits must be reclaimed within 90 days of the completion of the workover operations.
- 2) Notify the Farmington District Office Inspection and Enforcement Division @ (505) 599-8907 within 24 hours prior to commencing well bore recavitation operations.
- 3) Prior to commencing recompilation operations. BPOE must be installed and tested in accordance with the requirements outlined in Onshore Order No. 2.
- 4) Within 30 days of completion of the operations as proposed, file one original and three copies of Sundry Notice (form 3160-5) detailing the work conducted.