Form 3160-5 FORM APPROVED OMB No. 1004-0135 UNITED STATES (August 1999) DEPARTMENT OF THE INTERIOR Expires November 30, 2000 BUREAU OF LAND MANAGEMENT S. Lease Serial No. SF-080539 SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side If Unit of CA/Agreement, Name and/or No. i. Type of Well Well Name and No. K) Oil Well | Gas Well | Other Name of Operator
Little Oil and Gas, Inc. Hurt Federal #1 API Well No. 30-039-24126 3b. Phone No. (include area code) P.O. Box 1258 Farmington, NM 505-327-6176 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Ojito Gallup Dakota 11. County or Parish, State 2900' FNL 1650' FEL Sec. 1, T25N, R3W Rio Arriba 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Production (Start/Resume) Acidize Deepen Water Shut-Off ☐ Notice of latent Alter Casing ☐ Fracture Treat ☐ Reclamation ☐ Well Integrity Casing Repair **New Construction** ☐ Recomplete Other Subsequent Report Change Plans Plug and Abandog ☐ Temporarily Abandon Final Abandonment Notice Plug Back Convert to Injection ☐ Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof if the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days determined that the site is ready for final inspection.)

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has

9-4-2003 Move in and rig up Professional Well Service. Casing pressure 85 psi. Blow down to tank. Unbeam well. Pick up rods and remove polish rod and liner. Attempt to unseat pump. Continue to work rods, could not get pump unseated. Rig up tongs and back off rods. Lay down 1-4', 1-6' sub. Pull and lay down 94 7/8 rods with guides and 3 7/8 plain rods. Rig up BOP. Rig over to single line. Pull 20 stands of 2 3/8 tubing. Tubing was dry. Shut down for night. Left well open to tank.

· .				
	errify that the foregoing is true and correct inted/Typed)			No.
8ylvi.	F. Little	Title	Operator	
Signature	I selevat be	The Date	9-18-03	
	// THIS SPA	CE FOR FEDERAL OR	STATE OFFICE USE	
Approved by	/s/ David R. Sitzler	Division d	f-Multi-Resources	Date SEP 1 4 2004
Conditions of a certify that the	ipproval, if any, are attached. Approval of this applicant holds legal or equitable title to those	notice does not warrant or	Office	

which would entitle the applicant to conduct operations thereon.