

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED  
OMB No. 1004-0135  
Expires July 31, 1996

5. Lease Serial No.

NM1419 Jic. 9

6. If Indian, Allottee or Tribe Name

Jicarilla Apache

7. If Unit or CA/Agreement, Name and/or N

D

ON NM

8. Well Name and No.

Jicarilla Apache A #5

9. API Well No.

30-039-05778

10. Field and Pool, or Exploratory Area

Otero Chacra

11. County or Parish, State

Rio Arriba, New Mexico

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Elm Ridge Resources, Inc.

3a. Address

PO Box 156 Bloomfield, NM 87413

3b. Phone No. (include area code)

505-632-3476

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

880' FSL & 990' FeI

Sec.25-T25N-R5W

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Elm Ridge Resources has Plug and Abandoned the above reference well as follows: Plug 1) Set retainer @ 3990'. Pumped 50 sks below into perms. Left 10 sks on top of retainer. Plug 2) Tagged top of cement @ 2800'. Shoot 2 holes @ 2790' Set retainer @ 2771' and pumped 30 sks of cement below. Left 25 sks on top. Plug 3) Shot 2 holes @ 1330'. Set retainer @ 1310'. Pumped 30 sks below and 12 sks on top. This will cover 100' inside of pipe. Plug 4) Shot 2 holes @ 275'. Pumped 100 sks and had 19 sks. of good cement circulate out of surface pipe. Topped of casing. Waited 2 hours and pumped another 10 sks because cement was dropping and this topped it off.

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Amy Mackey

Title

Production Assistant

Signature

Date

September 20, 2004

THIS SPACE FOR FEDERAL OR STATE USE

Approved by

/s/ David R. Sitzler

Title

Division of Multi-Resources

Date

JAN 3 2005

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

010 ALBUQUERQUE, N.M.

04 SEP 22 AM 11:52

RECEIVED  
BLM