

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised May 08, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-039-25825
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-10037-58
7. Lease Name or Unit Agreement Name San Juan 29-7 Unit
8. Well Number 92B
9. OGRID Number 14538
10. Pool name or Wildcat Blanco Mesaverde

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other ☐

2. Name of Operator
Burlington Resources Oil & Gas Company LP

3. Address of Operator
PO Box 4289, Farmington, New Mexico 87499

4. Well Location

Unit Letter E : 1525 feet from the North line and 120 feet from the West line

Section 16 Township 29N Range 7W NMPM Rio Arriba County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Pay add ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

(1-15-03) MIRU. TOOH w/213 3/4" rods & pump. ND WH. NU BOP. TOOH w/96 jts 2 3/8" tbg. SDON.

(1-16-03) TOOH w/rest of tbg. TIH w/4 1/2" CIBP, set @ 4518'. Load hole w/wtr. PT csg & CIBP to 3000 psi/15 min, OK. Blow well & CO. TOOH. ND BOP. NU WH. RD. Rig released.

(2-3-03) MIRU. Pump 500 gal 15% HCl down csg. TIH, perf Lewis w/1 SPF @ 3872, 4042, 4044, 4046, 4052, 4054, 4056, 4078, 4080, 4082, 4096, 4098, 4112, 4126, 4132, 4192, 4208, 4224, 4264, 4298, 4310, 4320, 4356, 4436, 4474' w/24 0.32" diameter holes total. Frac Lewis w/197 tons CO2, 34,000# 20/40 Brady sd. SDON.

(2-4/8-03) Blow well & CO. RD.

(5-9-03) MIRU. ND WH. NU BOP. TIH w/3 7/8" mill to 4000'. SD for weekend.

(5-12-03) TIH, blow well & CO to 4518'. Establish circ. Mill out CIBP @ 4518'. TIH, blow well & CO to 5520'. SDON.

(5-13-03) Mill to 5530'. TOOH w/mill. TIH w/175 jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 5476'). ND BOP. NU WH. RD. Rig released.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Reg Supr DATE 5-14-03

Type or print name

Telephone No.

(This space for State use)

APPROVED BY [Signature] TITLE DEPUTY OIL & GAS INSPECTOR, DIST. 61

MAY 16 2003
DATE

Conditions of approval, if any: