Form 3169-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

5. Lease Serial No. NMSF078336

abandoned wel	o. Il littiali, Anottee	or tribe Name		
SUBMIT IN TRII	7. If Unit or CA/Agre	ement, Name and/or No.		
1. Type of Well ☐ Oil Well Gas Well ☐ Oth	8. Well Name and No FLORANCE 114			
2. Name of Operator Contact: MARY CORLEY BP AMERICA PRODUCTION CO E-Mail: CORLEY ML@BP OPM			9. API Well No. 30-045-27540-	00 - S1
3a. Address 200 ENERGY CT FARMINGTON, NM 87402	3b. Ph:	Phone No (include area code 281-366-4491	10. Field and Pool, of BASIN FRUITL	
4. Location of Well (Footage, Sec., 7 Sec 11 T30N R9W NWSW 23 36.82484 N Lat, 107.75520 W	390FSL 0980FWL	W. 6.8	SAN JUAN CO	
12. CHECK APPE	ROPRIATE BOX(ES) TO INI	DICATE NATURE OF 1	NOTICE, REPORT, OR OTHE	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
□ Notice of Intent	☐ Acidize	□ Deepen	Production (Start/Resume)	☐ Water Shut-Off
_	Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
Subsequent Report	☐ Casing Repair	☐ New Construction	Recomplete	Other
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	☐ Temporarily Abandon	
	Convert to Injection	☐ Plug Back	☐ Water Disposal	
determined that the site is ready for f Cavitate and run new liner: 11/29/2005 MIRUSU. NDWI- retrieve the 5.5" liner. TOH. T shoe? some coal fines from 2 6' of fill. C/O w/good circ? ret & without mist & pad S? no re Natural surge well? no return ? returns = BB sized? med to & flowed for 1.5 hrs. RIH & su 3/4" choke & flowed for 1.5 hr RIH & tag 15' of fill. Blow well	A. NU BOP. Blow down well. U IH & tag @ 2790'. Attempted to 2660' ? 2690'. Blow down well. urns flake to BB size. New breeturns. RIH & tag 15' of fill. C/C s. Blow down well. Break circ to heavy coal. Blow well dry. PU tr	nseat TBG hanger & PC to break circ ? no returns Did 6 air surges ? no re ak coals & fines. Made { 0 to TD, Getting BB size & RIH ? tag 13' of fill. C/ to CSG shoe & opened f fill. C/O to TD. Opene	s. PU to CSG sturns. RIH & tag 5 surges with d coal. PU O well bore I well on 3/4" choke ed well on es & flakes.	
14. Thereby certify that the foregoing is Comm Name (Printed/Typed) MARY CO	Electronic Submission #5318 For BP AMERICA PRO nitted to AFMSS for processing I	DDUCTION CO, sent to the by MATTHEW HALBERT of	e Farmington	
Signature (Electronic S		Date 01/19/2		<u></u>
· · · · · · · · · · · · · · · · · · ·	THIS SPACE FOR F	EDERAL OR STATE	OFFICE USE	
Approved By ACCEPT	ED		N HALBERT EUM ENGINEER	Date 01/25/2005
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conditions.	uitable title to those rights in the subjuct operations thereon.	Office Farming	•	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crime statements or representations as to an	e for any person knowingly an y matter within its jurisdiction	d willfully to make to any department.	r agency of the United

Additional data for EC transaction #53185 that would not fit on the form

32. Additional remarks, continued

Getting returns BB sized to marble sized. Blow well dry. Tag 10' of fill. Break circ & C/O ? BB sized to pea sized coals. Surge well ? returns starting to diminish. RIH & tag 20' of fill. C/O to TD. RU power swivel & wash down to TD ? 4803'. Blow down well. RIH w/5.5" liner and hanger & land liner @ 2802', TOL 2486'. POH. ND stripper head & BOP. Load TBG w/2% KCL. RU & ran CCL log from 2804' to 2394'. RU & perforate w/4 JSPF, .620 inch diameter: 2621' - 2630' (36 holes); 2655' -2669' (56 holes); 2701' - 2715' (56 holes); 2748' - 2758' (40 holes); 2777'-2793' (64 holes). NU stripper head. Install 3/4" choke & flow back for 2.5 hrs. RIH w/2 3/8" production TBG & land @ 2783'. ND BOP. NUWH.