Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

. Lease Serial No. NMNM014378

6	ΤfΤi	ndian.	Allotte	ee or '	Tribe	Name

SUBMIT IN TRII	PLICATE - Other instruc	tions on reverse sid	e.	7. If Unit or CA/Agreen	nent, Name and/or No.			
1. Type of Well ☐ Oil Well ☐ Gas Well ☐ Oth	ner	<u> </u>	CE 26 27 20 20 20	8. Well Name and No. H LOE FED B 2E				
Name of Operator FOUR STAR OIL GAS COMP		KEN JACKSON E-Mail: kewj@chevronte	xaço.com	9. API Well No. 30-045-24554-00-D2				
3a. Address 11111 S WILCREST HOUSTON, NM 77099		3b. Phone No. (include a Ph: 281.561,4991) Fx: 281.561,3702	area code) 005	BASIN DAKOTA BLANCO PICTURED CLIFFS				
4. Location of Well <i>(Footage, Sec., T</i> Sec 23 T29N R12W SWNW 1 36.71449 N Lat, 108.07344 W	1700FNL 1050FWL		22110163×	SAN JUAN COUI				
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE NATU	RE OF NOTICE, R	EPORT, OR OTHER	DATA			
TYPE OF SUBMISSION	TYPE OF ACTION							
Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Recomplete Workover Operations Casing Repair Plug and Abandon Temporarily Abandon Convert to Injection Plug Back Water Disposal 3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandomment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) The subject well produces downhole commingled from both the Pictured Cliffs and Dakota formations. The Pictured Cliff formation keeps sanding out and plugging the pump, causing the well to be shut-in and requiring numerous workovers to clean out and reset the pump, londer to reduce workovers and return the Dakota to production. Four Star requests approval to abandon the Pictured Cliffs formation. The procedure to abandon the Pictured Cliffs formation is as follows: Set a composite bridge plug @1760' below the PC perfs @ 1638'-1734' Squeeze the Pictured Cliffs with 250 sxs of Class "G" cement. Wait on cement and drill cement out to CBP and test casing to 500#. If casing holds drill out CBP, stimulate as needed and return Dakota to production.								
14. Thereby certify that the foregoing is Col Name (Printed/Typed) KEN JACI	Electronic Submission f For FOUR STAR mmitted to AFMSS for prod	OIL GAS COMPÁNY, s cessing by STEVE MAS	ent to the Farmingto	on				
, , , , , , , , , , , , , , , , , , ,			ALLOAN					
Signature (Electronic S			02/25/2005					
	THIS SPACE FO	OR FEDERAL OR S	TATE OFFICE U	JSE				
Approved By STEPHEN MASON Conditions of approval, if any, are attache	ed. Approval of this notice does	_ +	TROLEUM ENGIN	IEER	Date 02/25/2005			
certify that the applicant holds legal or eq which would entitle the applicant to condi Title 18 U.S.C. Section 1001 and Title 43	uitable title to those rights in th uct operations thereon.	e subject lease Office	Farmington	maka ta any da-a-ta-a-t	ogonou of the United			
States any folce Setitions or frondulant	o.s.c. section 1212, make it a	a crime for any person know	wingly and willfully to i	make to any department or a	agency of the United			