

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.

OMB No. 1004-0133
Expires July 31, 1996

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

PARAWON OPERATING LLC

3a. Address

c/o: D. Drake, PO Box 5575, Farmington, NM 87499

3b. Phone No. (include area code)

505-326-7633

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1800' FNL 1980' FEL (G) Sec. 10 T30N R16W

5. Lease Serial No.

NMNM-077281

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

2005 MAR 8 AM 8 10

8. Well Name and No.

NE HOGBACK (BENTW28)

9. APN/Well No.

30-045-09751

10. Field and Pool, or Exploratory Area

Horseshoe Gallup

11. County or Parish, State

San Juan County, New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
☒ Notice of Intent	☐ Acidize ☐ Deepen ☐ Production (Start/Resume) ☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing ☐ Fracture Treat ☐ Reclamation ☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair ☐ New Construction ☐ Reconplete ☐ Other
	☐ Change Plans ☐ Plug and Abandon ☐ Temporarily Abandon
	☐ Convert to Injection ☒ Plug Back ☐ Water Disposal

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompletes horizontally, give subsurface formations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-3 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final reclamation.)

Parwon Operating plans to plug and abandon this well per the following procedure: Round trip a 5.5" casing scraper to 1450' on 2.375" workstring. Set a cement retainer at 1450'. Load the casing with water and circulate the well clean. Pressure test the casing to 500#. Then spot 25 sxs Type III cement inside above the CR. TOH and LD tubing. Perforate the 5.5" casing at 265'. Establish circulation to surface with water. Mix and pump approximately 100 sxs cement down the casing to circulate good cement to surface. Shut in and WOC. Cut off well head, install P&A marker.

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

David Drake

Title

Manager

Signature

David Drake

Date

March 3, 2005

THIS SPACE FOR FEDERAL OR STATE USE

Approved by

Jim Lovato

Title

Petr. Eng.

Date

3/8/05

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations or to any officer or employee of the United States any such false, fictitious or fraudulent statements or representations.

(Instructions on reverse)

NMOCD

WELL DIAGRAM

Operator: Parawon Operating Lease: NM-077281
Well: 26 NE Hogback Location: G 10-30N-16W
County and State: San Juan Co., NM
Reviewed By: J Lovato Date: 3/7/8
Remarks: _____

