Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS									
Do	not use	this form	for	proposals	to	drill	or	reenter	an

ontract# 362

FORM APPROVED OMB No. 1004-0135

 $\tilde{\vec{\pi}}$

6. If Indian, Allottee

abandoned well.	Use Form 3160-3 (APD)	for such proposals.	203	Jicarilla Apache
SUBMIT IN TRIPL	ICATE - Other instru	ctions on reverse	side	7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well X Oil Well Gas Well 2. Name of Operator Elm Ridge Resources, Inc.	Other	OTO TOKULOW	A Service Control	8. Well Name and No. Martin Whittaker #25 9. API Well No.
3a. Address PO Box 156, Bloomfield, NM 4. Location of Well (Footage, Sec., T.,		3b. Phone No. (include a 505-632-3476	area code)	30-039-23371 10. Field and Pool, or Exploratory Area S. Lindrith Gallup Dakota Ext.
1650 FSL X 1190 FWL Sec.6-T23N-R4W			:	11. County or Parish, State Rio Arriba County, NM
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATUR	E OF NOTICE, REPOR	RT, OR OTHER	DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (1) Reclamation Recomplete Temporarily Water Dispos	Other
If the proposal is to deepen directionally Attach the Bond under which the work Following completion of the involved ope	y or recomplete horizontally, give so will be performed or provide the B crations. If the operation results in	absurface locations and measur tond No. on file with BLM/B a multiple completion or reco	red and true vertical SIA. Required subsompletion in a new	osed work and approximate duration thereof. I depths of all pertinent markers and zones equent reports shall be filed within 30 days interval, a Form 3160-4 shall be filed once have been completed, and the operator has

Elm Ridge Resources, Inc. plans to Plug and Abandon the above referenced well as follows: Plug 1) Set cement retainer @ 4780'. Pump 150 sks (casing vol + 100%). Plug 2) 100' balanced plug 4670'- 4570'. Pump 15 sks of cement. Plug 3) 176' balanced plug 4120' - 3944. Pump 20 sks of cement. Plug 4) 100' balanced plug 2935'- 2835. Pumped 15 sks of cement. Plug 5) 621' balanced plug 2547'-1926'. Pump 75 sks of cement. Plug 6) Shoot 2 holes @ 350'. Pump 120 sks of cement. Circulate to surface. Leave cement in 7" to surface. Cut off wellhead 3' below grade. Set dryhole marker and reclaim location.

						11 BU	77 30 -1		
14. I hereby certify t	that the foregoing is true and correct					3	. O	Fin	-
Name (Printed/Typed) Amy Mackey		Title				12.			
			Production Assitant			ä		1.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4	
Signature My	Vacles	Date		January 12, 2005			Ö	?	_
	THIS SPAC	E FOR FEE	ERAL OR ST	ATE USE			G)		Š
Approved by	/s/ David R. Sitzler	Div	iston of	Multi-Resour	C PS	FEB 1	8 2	2005	=
certify that the applican	, if any, are attached. Approval of this notice does not holds legal or equitable title to those rights in the eapplicant to conduct operations thereon.		Office						_
Title 18 U.S.C. Sectio	n 1001, makes it a crime for any person knowing	to make to any	department or agency of	the United St	ates any fal	se fic	titious or	=	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or traudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

determined that the site is ready for final inspection.)

CONDITIONS OF APPROVAL FOR PERMANENT ABANDONMENT

Operator Elm Ridge Resources Inc.

Well Name Jic 362 Martin Whittaker #25

- 1. Plugging operations authorized are subject to the "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- 2. For wells on Federal leases, Cole Thomas with the Cuba Field Office is to be notified at least 24 hours (48 hours if possible) before the plugging operations commence. His phone number is (505) 289-3748. Office hours are 7:45 a.m. to 4:30 p.m.

For wells on Jicarilla leases notify Bryce Hammond with the Jicarilla Apache Tribe at least 24 hours (48 hours if possible) before the plugging operations commence. His phone number is (505) 759-1783 ext. 28.

- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made :

A cement plug is needed from 1230' to 1330' to cover the top of the Ojo Alamo at 1280'.

A cement plug is needed from 440' to 540' to cover the top of the Nacimiento at 490'.