## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re enter an

RECEI	FORM APPROVED OMB NO 1004-0137
	Expires July 31, 2010

JUN 13 2 111 Lease Serial No.

	~ 0	<u>USA SF-080657</u>
armines	~~-:	6. If Indian, Allottee or Tribe Name

armington Fie	ld Off:
feau of Land M	anagemen.

abandoned well Use For	n 3160-3 (APD) for s	such proposal	rarmi s. ຳປາລອບເ	ington Field of Land Ma	d Office nagemer			
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No San Juan 32-5 Unit			
1 Type of Well Oil Well X Gas Well Other					8 Well Name and No San Juan 32–5 Unit 111			
Energen Resources Corporation				\ <del>\</del>	9. API Well No.			
3a. Address		3b. Phone No. (inc	lude area cod	J_1	30-039-26637			
2010 Afton Place, Farmington, NM 8		505-325-	505-325-6800			10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey I	• •			1	Basin Fruitland Coal			
SHL: (A) Sec.31-T32N-R05W; 1005'FN BHL: (P) Sec.31-T32N-R05W; 760'FSL					11. County or Parish, State			
10 CUECK A PROCEDIA TO	D DOVICEO TO DID	-	E OR MOTE		Rio Arriba	NM NM		
12. CHECK APPROPRIATI	E BOX(ES) TO INDI	ICATE NATUR	E OF NOTIO	CE, REPOR	T, OR OTHER	DATA		
TYPE OF SUBMISSION			TYPE OF	F ACTION				
Notice of Intent	Acidıze	Deepen		Production (	Start/Resume)	Water Shut-Off		
	Alter Casing	Fracture Tre	at	Reclamation		Well Integrity		
x Subsequent Report	Casing Repair	New Constr	iction	Recomplete	Γ	Other set he	oriz.	
- Final Abandonment Notice	Change Plans	Plug and Ab	andon	Temporarily	Abandon	liner & produ		
T mai Abandoninent Notice	Convert to Injection	Plug Back		Water Dispo	col	tubing		
This subsquent report for the San recomplete filed on 10/26/10 appr 5/9/11 TIH with whipstock. Mill Fruitland Coal to a MD of liner, set at 4514' MD. Toriginal vertical perfs frat 3227'.  5/18/11 TIH with 2.375" 4.7# J-5	window from 3076 5776'. (see atta OL 3128'. Perfer com 3358'-3375' at	04/06/11. '-3100'. Dr. ached drilili rations in ti nd 3429'-343	ill 6.25" ng survey ne Fruitl 9' are is	horizont  TIH v  and Coal  colated by	cal sidetrace with 4.50" p are from 30 y a removable sed 5/18/11	ck hole in the perforated 524'- 4465'. Le brige plug	æ	
See attachments for production liner specifications.				RCVD JUN 17'11 OIL CONS. DIV. DIST. 3				
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)		T241-						
Anna Stotts				y Analyst		men ead he		
Signature Anna Sol			3/11	<del></del>	A A	TED FOR RE	liku.	
THIS	S SPACE FOR FEDE	RAL OR STAT	E OFFICE	USE	J	UN 16 22/21	<u> </u>	
Approved by		Title			Dat	-	- A 100	
Conditions of approval, if any, are attached Approval of this not the applicant holds legal or equitable title to those rights in the su entitle the applicant to conduct operations thereon		y that Office			NY_	CV.	diagram.	

Instructions for Subsequent report on 2011 Sidetracks: Add this info to the subsequent report (liner report) for the caption well below.

## San Juan 32-5 Unit #111 ST:

- \*Energen Resources has set 2 Baker Hughes Swell Packers for isolation per NMOCD requirements.
- \*The swell packers were spaced out on the 4-1/2" 11.6# liner to be placed as follows:
  - The lower swell packer was placed at the Fruitland formation/Kirtland shale interface from 3156′ 3171′ MD.
  - The upper swell packer was placed right below the T-Lock swivel on the Baker hook hanger from 3103′ 3118′ MD, roughly 10 20 feet outside the milled window.
- \* Per NMOCD requirements, a Noise Log will be run in the sidetrack to determine if there is a seal behind the swell packers.
- \*A minimum of 10 days must be given for the swell packers to expand and seal the wellbore. The NMOCD will be contacted 24 hours in advance of running the noise log in the San Juan 32-5 Unit #111 ST.