Form 3160-5			RECEIVE		
(April 2004)	UNITED STATE DEPARTMENT OF THE BUREAU OF LAND MAN	INTERIOR	JUL <b>08</b> 2011		FORM APPROVED OM B No 1004-0137 Expires March 31, 2007
				5 1.0000 00110	
SUNDRY	Y NOTICES AND REI	PORTS ON I		The second se	Allottee or Tribe Name
abandoned w	vell. Use Form 3160-3 (	APD) for such	proposals.	Navajo	
	RIPLICATE- Other inst	ructions on re	everse side.	7. If Unit or	CA/Agreement, Name and/or No.
I Type of Well ✓ Oil Well□ □ [	Gas Well Other			8. Well Nan Hanson	
2. Name of Operator BC&D Operating C/O Nacogdoches Oil & Gas Inc.			inc. 9. A		
3a Address 816 North Street, Nacogdoches Tx. 75963		3b. Phone No (include area code)   936-560-4747		30-031- 10. Field and	05527 I Pool, or Exploratory Area
4 Location of Well (Footage, Sec., T., R., M., or Survey Description)					Hospah-Gallup
1686' FSL & 820' FWL Section	on 6 17N 8W				or Parish, State ey County, New Mexico
12. CHECK A	APPROPRIATE BOX(ES) TO	INDICATE NA	TURE OF NOTICE,	 REPORT, OR	OTHER DATA
TYPE OF SUBMISSION		· · · · · · · · · · · · · · · · · · ·	TYPE OF ACTION		
Notice of Intent		Deepen	Production (S	tart/Resume)	Water Shut-Off
_	Alter Casing	Fracture Treat	non Recomplete		Well Integrity
Subsequent Report	Change Plans	Plug and Abanc		bandon	· · · · · · · · · · · · · · · · · · ·
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposa	1	
following completion of the in testing has been completed F determined that the site is read <b>6-13-2011- RIH with WS</b> ,	volved operations. If the operation inal Abandonment Notices shall be	de the Bond No. on results in a multiple filed only after all re truck broke dow	file with BLM/BIA Requi completion or recompletion quirements, including reclain n. SDFN.	ared subsequent re a in a new interval mation, have beer	n completed, and the operator has
following completion of the in testing has been completed F determined that the site is read 6-13-2011- RIH with WS, 6-15-2011- RIH with WS 6-17-2011-RIH with WS, around surface casing. St 6-20-2011- RIH with WS	wolved operations. If the operation inal Abandonment Notices shall be by for final inspection.) , tagged bottom @ 1586', pump p 50 sks @15.1 ppg, pump bott to 1409', mix and pump 32 sks	de the Bond No. on results in a multiple filed only after all re o truck broke dow om plug. LD WS. @ 15.1 ppg. LD V D WS. Mix and pu 65 sks @15.1 ppg	file with BLM/BIA Requi completion or recompletion quirements, including reclai n. SDFN. Cut 2" hole in surface c WS. ump 50 sks @15.2 ppg fo ; for top plug.	a in a new interval mation, have been a sing for valve assing for valve or outside plug.	ports shall be filed within 30 days , a Form 3160-4 shall be filed once a completed, and the operator has At 30 sks, cement came out and
following completion of the in testing has been completed F determined that the site is read 6-13-2011- RIH with WS, 6-15-2011- RIH with WS 6-17-2011-RIH with WS, around surface casing. St 6-20-2011- RIH with WS	nvolved operations. If the operation inal Abandonment Notices shall be by for final inspection.) , tagged bottom @ 1586', pump p 50 sks @15.1 ppg, pump bott to 1409', mix and pump 32 sks tag bottom plug at 1160.76'. Li hutdown pump. Consult BLM. to 652.70'. Mixed and pumped nt @30'. Mix and pumped 7 sks	de the Bond No. on results in a multiple filed only after all re o truck broke dow om plug. LD WS. @ 15.1 ppg. LD V D WS. Mix and pu 65 sks @15.1 ppg	file with BLM/BIA Requi completion or recompletion quirements, including reclai n. SDFN. Cut 2" hole in surface c WS. ump 50 sks @15.2 ppg fo ; for top plug.	a in a new interval mation, have been a sing for valve assing for valve or outside plug.	ports shall be filed within 30 days , a Form 3160-4 shall be filed once a completed, and the operator has At 30 sks, cement came out and
following completion of the in testing has been completed F determined that the site is read 6-13-2011- RIH with WS, 6-15-2011- RIH with WS 6-17-2011-RIH with WS 6-17-2011-RIH with WS 6-20-2011- RIH with WS 6-21-2011- Tagged cemen 14 Thereby certify that the fore Name ( <i>Printed/Typed</i> ) Mike Allen	nvolved operations. If the operation inal Abandonment Notices shall be by for final inspection.) , tagged bottom @ 1586', pump p 50 sks @15.1 ppg, pump bott to 1409', mix and pump 32 sks tag bottom plug at 1160.76'. L' hutdown pump. Consult BLM. to 652.70'. Mixed and pumped nt @30'. Mix and pumped 7 sks egoing 1s true and correct	de the Bond No. on results in a multiple filed only after all re o truck broke dow om plug. LD WS. @ 15.1 ppg. LD V D WS. Mix and pu 65 sks @15.1 ppg @ 15.1 ppg. Cut of	file with BLM/BIA Requi completion or recompletion quirements, including reclai n. SDFN. Cut 2" hole in surface c WS. ump 50 sks @15.2 ppg fo ; for top plug.	a in a new interval mation, have been assing for valve or outside plug.	Ports shall be filed within 30 days , a Form 3160-4 shall be filed once a completed, and the operator has At 30 sks, cement came out and At 30 sks, cement
following completion of the in testing has been completed F determined that the site is read 6-13-2011- RIH with WS, 6-15-2011- RIH with WS 6-16-2011- RIH with WS 6-17-2011- RIH with WS 6-20-2011- RIH with WS 6-21-2011- Tagged cemen	wolved operations. If the operation inal Abandonment Notices shall be by for final inspection.) , tagged bottom @ 1586', pump p 50 sks @15.1 ppg, pump bott to 1409', mix and pump 32 sks tag bottom plug at 1160.76'. L hutdown pump. Consult BLM. to 652.70'. Mixed and pumped nt @30'. Mix and pumped 7 sks egoing is true and correct	de the Bond No. on results in a multiple filed only after all re o truck broke dow om plug. LD WS. @ 15.1 ppg. LD V D WS. Mix and pu 65 sks @15.1 ppg @ 15.1 ppg. Cut of Tit Da	file with BLM/BIA Requi completion or recompletion quirements, including reclain n. SDFN. Cut 2" hole in surface c WS. ump 50 sks @15.2 ppg for to top plug. off casing. Place P&A m le VP Engineering ite	ured subsequent re n in a new interval mation, have beer assing for valve or outside plug. narker. 07/06/2011	Ports shall be filed within 30 days , a Form 3160-4 shall be filed once a completed, and the operator has At 30 sks, cement came out and At 30 sks, cement
following completion of the in testing has been completed F determined that the site is read 6-13-2011- RIH with WS, 6-15-2011- RIH with WS 6-16-2011- RIH with WS 6-17-2011- RIH with WS 6-20-2011- RIH with WS 6-21-2011- Tagged cemen 14 Thereby certify that the ford Name ( <i>Printed/Typed</i> ) Mike Allen	nvolved operations. If the operation inal Abandonment Notices shall be by for final inspection.) , tagged bottom @ 1586', pump p 50 sks @15.1 ppg, pump bott to 1409', mix and pump 32 sks tag bottom plug at 1160.76'. L' hutdown pump. Consult BLM. to 652.70'. Mixed and pumped nt @30'. Mix and pumped 7 sks egoing 1s true and correct	de the Bond No. on results in a multiple filed only after all re o truck broke dow om plug. LD WS. @ 15.1 ppg. LD V D WS. Mix and pu 65 sks @15.1 ppg @ 15.1 ppg. Cut of Tit Da	file with BLM/BIA Requi completion or recompletion quirements, including reclain n. SDFN. Cut 2" hole in surface c WS. ump 50 sks @15.2 ppg for to top plug. off casing. Place P&A m le VP Engineering ite	ured subsequent re n in a new interval mation, have beer assing for valve or outside plug. narker. 07/06/2011	ports shall be filed within 30 days , a Form 3160-4 shall be filed once a completed, and the operator has At 30 sks, cement came out and
following completion of the in testing has been completed F determined that the site is read 6-13-2011- RIH with WS, 6-15-2011- RIH with WS 6-16-2011- RIH with WS 6-17-2011- RIH with WS 6-20-2011- RIH with WS 6-21-2011- Tagged cemen 14 Thereby certify that the ford Name ( <i>Printed/Typed</i> ) Mike Allen	nvolved operations. If the operation inal Abandonment Notices shall be by for final inspection.) , tagged bottom @ 1586', pump p 50 sks @15.1 ppg, pump bott to 1409', mix and pump 32 sks tag bottom plug at 1160.76'. L' hutdown pump. Consult BLM. to 652.70'. Mixed and pumped at @30'. Mix and pumped 7 sks egoing 1s true and correct Subministry THIS SPACE FOR attached Approval of this notice al or equitable title to those rights i	de the Bond No. on results in a multiple filed only after all re o truck broke dow om plug. LD WS. @ 15.1 ppg. LD V D WS. Mix and pu 65 sks @15.1 ppg @ 15.1 ppg. Cut of Tit Da FEDERAL OI does not warrant or	file with BLM/BIA Requi completion or recompletion quirements, including reclain n. SDFN. Cut 2" hole in surface c WS. ump 50 sks @15.2 ppg for to top plug. off casing. Place P&A m le VP Engineering tte R STATE OFFICI	ured subsequent re n in a new interval mation, have beer easing for valve or outside plug. narker. 07/06/2011 E USE	Ports shall be filed within 30 days , a Form 3160-4 shall be filed once a completed, and the operator has At 30 sks, cement came out and At 30 sks, cement
following completion of the in testing has been completed F determined that the site is read 6-13-2011- RIH with WS, 6-15-2011- Mix and pump 6-16-2011- RIH with WS, 6-17-2011- RIH with WS, 6-20-2011- RIH with WS 6-20-2011- RIH with WS 6-21-2011- Tagged cemen Name ( <i>Printed/Typed</i> ) Mike Allen Signature $\mathcal{E}$ ( <i>i</i> to $73 \wedge ic$ Approved by Conditions of approval, if any, arc certify that the applicant holds lega	nvolved operations. If the operation inal Abandonment Notices shall be by for final inspection.) , tagged bottom @ 1586', pump p 50 sks @15.1 ppg, pump bott to 1409', mix and pump 32 sks tag bottom plug at 1160.76'. L' hutdown pump. Consult BLM. to 652.70'. Mixed and pumped at @30'. Mix and pumped 7 sks egoing 1s true and correct Submer Fride THIS SPACE FOR attached Approval of this notice al or equitable title to those rights i to conduct operations thereon. le 43 U.S.C. Section 1212, make it a	de the Bond No. on results in a multiple filed only after all re o truck broke dow om plug. LD WS. @ 15.1 ppg. LD V D WS. Mix and pu 65 sks @15.1 ppg @ 15.1 ppg. Cut of [] [	file with BLM/BIA Requi completion or recompletion quirements, including reclain n. SDFN. Cut 2" hole in surface c WS. ump 50 sks @15.2 ppg for the state of the surface of	ured subsequent re n in a new interval mation, have beer easing for valve or outside plug. narker. 07/06/2011 E USE	Ports shall be filed within 30 days , a Form 3160-4 shall be filed once a completed, and the operator has At 30 sks, cement came out and At 30 sks, cement
following completion of the in testing has been completed F determined that the site is read 6-13-2011- RIH with WS, 6-15-2011- Mix and pump 6-16-2011- RIH with WS, 6-17-2011- RIH with WS, around surface casing. St 6-20-2011- RIH with WS 6-21-2011- Tagged cemen Name ( <i>Printed/Typed</i> ) Mike Allen Signature $\mathcal{E}$ ( <i>i</i> tradic Approved by Conditions of approval, if any, arc certify that the applicant holds lega which would entitle the applicant to Title 18 USC Section 1001 and Tit	nvolved operations. If the operation inal Abandonment Notices shall be by for final inspection.) , tagged bottom @ 1586', pump p 50 sks @15.1 ppg, pump bott to 1409', mix and pump 32 sks tag bottom plug at 1160.76'. L' hutdown pump. Consult BLM. to 652.70'. Mixed and pumped at @30'. Mix and pumped 7 sks egoing 1s true and correct Submer Fride THIS SPACE FOR attached Approval of this notice al or equitable title to those rights i to conduct operations thereon. le 43 U.S.C. Section 1212, make it a	de the Bond No. on results in a multiple filed only after all re o truck broke dow om plug. LD WS. @ 15.1 ppg. LD V D WS. Mix and pu 65 sks @15.1 ppg @ 15.1 ppg. Cut of [] [	file with BLM/BIA Requi completion or recompletion quirements, including reclain n. SDFN. Cut 2" hole in surface c WS. ump 50 sks @15.2 ppg for the state of the surface of	ured subsequent re n in a new interval mation, have beer easing for valve or outside plug. narker. 07/06/2011 E USE	Ports shall be filed within 30 days , a Form 3160-4 shall be filed once a completed, and the operator has At 30 sks, cement came out and At 30 sks, cement