OIL CONS. D	DIV DIST. 3		RECE	VED		
•	2 2015 UNITED STATES DEPARTMENT OF THE INTERIOR JREAU OF LAND MANAGEMENT			OMB Expires	1 APPROVED No. 1004-0137 : March 31, 2007	
SUNDRY	NOTICES AND	REPORTS ON WELL	Farmington	3. Lease Serial No. No-G-1401-1868		
	form for propo	6. If Indian, Allottee or Tribe Name 791-45				
	BMIT IN TRIPLICATE	7. If Unit of CA/Agre	ement, Name and/or No.			
1. Type of Well	Gas Well	8. Well Name and No. Chaco 2308 04L #459H				
 Name of Operator WPX Energy Production, LI 	C	9. API Well No. 30-045-35627				
3a. Address 3b. Phone No. (include area code) PO Box 640 Aztec, NM 87410 505-333-1808				10. Field and Pool or Exploratory Area Nageezi Gallup / Basin Mancos		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) SHL: 2431' FSL & 427' FWL, SEC 4, T23N, R8W BHL: 1272' FSL & 230' FWL SEC 5, T23N, R8W				11. Country or Parish, State San Juan, NM		
		TE BOX(ES) TO INDICATE	NATURE OF NOTIO	CE, REPORT OR OTHE	R DATA	
TYPE OF SUBMISSION			TYPE OF ACTIO	N		
Notice of Intent	Acidize	Deepen Fracture Treat	Production (S	Well Integrity		
	Casing Repair	New Construction Plug and Abandon	Recomplete Temporarily A		Other AMENDED COMPLETION	
Final Abandonment	Convert to	Plug Back	POOL NAME	CHANGE		
Bond under which the work w of the involved operations. If t	ally or recomplete horizon ill be performed or provid- he operation results in a m	ntally, give subsurface locations a e the Bond No. on file with BLM multiple completion or recompletion	nd measured and true ver BIA. Required subseque on in a new interval, a For	tical depths of all pertinent of nt reports must be filed with rm 3160-4 must be filed onc	markers and zones. Attach the in 30 days following completion	
4/9/15- MIRU HWS #17, NU &	tested BOP. Test good	l.				
TlH w/ seal assembly on 4 ½", : jts for spacing (5.75, 2.10, and 24,000# on casing hanger.						
TIH w/ 2-3/8" PH6 work string	& CO to 10435'. Shut ir	n well.				
<u>4/11/15</u> -Pressure tested 4 ½" d 30 minutes-Test Good. Press te			- Test Good. Pressure	tested 7" casing to 150	Opsi/charted record test for	
4/12/15- Perf Gallup 1 st stage.	10250'-10375' + RSI TC	OL @10434'. (Reported RSI	@ 10438' on the final	casing) with 18, 0,40" h	oles. RD	

<u>4/15/15-4/19/15</u> - Prepare for frac. 14. I hereby certify that the pregoing is true and correct. Name (<i>Printed/Typed</i>) Marie E. Jaramillo	Title Permit Tech III	
Signature THIS SPACE FOR FEDI	Date 51215 ERAL OR STATE OFFICE	EUSE
Approved by	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not wa r certify that the applicant holds legal or equitable title to those rights in the sub ease which would entitle the applicant to conduct operations thereon.		
itle 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime Inited States any false, fictitious or fraudulent statements or representations as		ly to make to any department or agency of the

(Instructions on page 2)

Copyright 2006 Forms In Word (www.formsinword.com). For individual or single-branch use only. William Tambekou



6

Chaco 2308 04L #459H - page 2

4/20/15-Frac Gallup 1st stage 10250'-10434'- with 213,027# 20/40 PSA Sand

Set flo-thru frac plug @ 10210' MD. Perf 2nd stage 9964'-10150'- with 24, 0.40" holes. Frac Gallup 2nd stage with 218,184#, 20/40 PSA Sand Set flo-thru frac plug @ 9920' MD. Perf 3rd stage 9678'-9864'- with 24, 0.40" holes. Frac Gallup 3rd stage with 215,169#, 20/40 PSA Sand Set flo-thru frac plug @ 9620' MD. Perf 4th stage 9392'-9578'- with 24, 0.40" holes.

4/21/15- Frac Gallup 4th stage with 214,678#, 20/40 PSA Sand.

Set flo-thru frac plug @ 9320' MD. Perf 5th stage 9106'-9292'-with 24, 0.40" holes. Frac Gallup 5th stage with 215,004#, 20/40 PSA Sand Set flo-thru frac plug @ 9040' MD. Perf 6th stage 8820'-9003'- with 24, 0.40" holes. Frac Gallup 6th stage with 220,466#, 20/40 PSA Sand Set flo-thru frac plug @ 8770' MD. Perf 7th stage 8534'-8721'- with 24, 0.40" holes. Frac Gallup 7th stage with 210,960#, 20/40 PSA Sand Set flo-thru frac plug @ 8480' MD. Perf 7th stage 8248'-8434'- with 24, 0.40" holes. Frac Gallup 8th stage with 215,394#, 20/40 PSA Sand Set flo-thru frac plug @ 8480' MD. Perf 8th stage 8248'-8434'- with 24, 0.40" holes. Frac Gallup 8th stage with 215,394#, 20/40 PSA Sand Set flo-thru frac plug @ 8180' MD. Perf 9th stage 7962'-8148'- with 24, 0.40" holes.

4/22/15-Frac Mancos 9th stage with 214,951#, 20/40 PSA Sand

Set flo-thru frac plug @ 7900' MD. Perf 10th stage 7678'-7862'- with 24, 0.40" holes. Frac Mancos 10th stage with 215,499#, 20/40 PSA Sand Set flo-thru frac plug @ 7620' MD. Perf 11th stage 7390'-7576'- with 24, 0.40" holes. Frac Mancos 11th stage with 215,600#, 20/40 PSA Sand Set flo-thru frac plug @ 7340' MD. Perf 12th stage 7104'-7290'- with 24, 0.40" holes. Frac Mancos 12th stage with 263,464# 20/40 PSA Sand Set flo-thru frac plug @ 7060' MD. Perf 13th stage 6818'-7004'- with 24, 0.40" holes.

4/23/15-Frac Mancos 13th stage with 263,522#, 20/40 PSA Sand

Set flo-thru frac plug @ 6760' MD. Perf 14th stage 6531'-6718'- with 24, 0.40" holes. Frac Mancos 14th stage with 263,313#, 20/40 PSA Sand Set flo-thru frac plug @ 6480' MD. Perf 15th stage 6250'-6432'- with 24, 0.40" holes. Frac Mancos 15th stage with 263,313#, 20/40 PSA Sand Set flo-thru frac plug @ 6180' MD. Perf 16th stage 5960'-6146'- with 24, 0.40" holes. Frac Mancos 16th stage with 265,123#, 20/40 PSA Sand Set 4-1/2" CBP @5300'. RDMO Frac & WL.

4/25/15- MIRU HWS. Pressure Tested BOP- OK.

DO CBP @ 5300'.

4/26/15 - DO flo- thru Frac plug @ 6180', 6480', 6760', 7060', 7340', 7620', 7900', 8180', 8480', 8770', 9040', 9320', 9620', and 9920'.

4/27/15-DO flo- thru Frac plug @ 10210'. Circ., & CO well to 10435'.

Pulled and landed tieback string.

Land tbg @ 5784', as Follows: Start in hole w/ Gas lift system as follows, half mule shoe @ 5784', 1jt 2 3/8 tubing, 1.875 XN nipple w/ 1.82 nogo @ 5751', 2jts of 2 3/8 tubing, 7' X 2 7/8 arrowset packer @5685', on/off tool w/ 2.25F profile @ 5677', 1 4' 2 7/8 pup jt, 1jt 2 7/8 6.5# J-55 tubing, GLV #1, 7jts 2 7/8, 2 7/8 2.313X nipple @ 5421', 14jts GLV #2, 15jts GLV #3, 15jts GLV #4, 17jts GLV#5, 17jts GLV#6, 18jts GLV #7, 20jts GLV #8, 22jts GLV #9, 37jts, hanger, Set packer and pack off 30K over, re-land hanger w/ 12K tension on packer. 14.5 KB. Rig down.

NOTE: Delivery and flowback test information will be reported on delivery sundry.