Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMNM99735 6. If Indian, Allottee or Tribe Name							
						SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No.	
						1. Type of Well				8. Well Name and No. SYNERGY 21-7-7 130	
Oil Well Gas Well Other: COAL BED METHANE 2. Name of Operator Contact: GLEN PAPP				9. API Well No.							
SYNERGY OPERATING, LLC E-Mail: gpapp@synergyoperating.com			、 、	30-043-21020-0							
3a. Address	•	3b. Phone No. (include area code) Ph: 505-599-4908		10. Field and Pool or Exploratory Area BASIN FRUITLAND COAL							
FARMINGTON, NM 87499 4. Location of Well (Footage, Sec., T., R., M., or Survey Description		Fx: 505-599-4900		11. County or Parish, State							
Sec 7 T21N R7W NWNW 695FNL 710FWL 36.071780 N Lat, 107.623830 W Lon		9/29/20	OCD REC'D								
12. CHECK THE	CAPPROPRIATE BOX(ES)) TO INDICATE NATURE C	F NOTICE, I	REPORT, OR OTH	IER DATA						
TYPE OF SUBMISSION		TYPE OF ACTION									
□ Notice of Intent	□ Acidize	Deepen	Productio	on (Start/Resume)	□ Water Shut-Off						
	□ Alter Casing	Hydraulic Fracturing	🗖 Reclamat	tion	Well Integrity						
Subsequent Report	Casing Repair	□ New Construction	Recompl	ete	□ Other						
Final Abandonment Notic	-	Plug and Abandon	□ Temporarily Abandon								
BF	Convert to Injection	Plug Back	U Water Di	sposal							
Attach the Bond under which the following completion of the invo	tionally or recomplete horizontally work will be performed or provid- lved operations. If the operation re al Abandonment Notices must be fi	ent details, including estimated startin , give subsurface locations and measu e the Bond No. on file with BLM/BL ssults in a multiple completion or rec led only after all requirements, includ	ured and true ver A. Required subs ompletion in a ne	tical depths of all pertin sequent reports must be w interval, a Form 316	ent markers and zones. filed within 30 days 0-4 must be filed once						
Synergy Operating LLC ha	as completed the plugging of	the wellbore in the subject we	ell.								
Attached in a separate file	are the follow documents:										
1) Daily reports of the dow 2) Copy of the MIT(Mecha	nhole plugging operations nical Integrity Test) pressure	e chart									
Synergy plans to begin the prior to commencing field		lure this fall and will notify the	BLM's FFO								
14. I hereby certify that the foregoin	Electronic Submission # For SYNERGY	#530153 verified by the BLM We OPERATING, LLC, sent to the processing by JOE KILLINS on (Farmington	-							
Name(Printed/Typed) THOM	• ·										
Signature (Electronic Submission) Date 09/			2020								
	THIS SPACE F	OR FEDERAL OR STATE	OFFICE US	E							
Approved By ACCEPTED		JOE KILL _{Title} ENGINEE	LINS ER Date 09/21/2020								
Conditions of approval, if any, are att certify that the applicant holds legal o which would entitle the applicant to c	e subject lease										
Title 18 U.S.C. Section 1001 and Titl States any false, fictitious or fraudu	e 43 U.S.C. Section 1212, make it a lent statements or representations a	a crime for any person knowingly and s to any matter within its jurisdiction	l willfully to mal	te to any department or	agency of the United						
(Instructions on page 2) ** BLM R	EVISED ** BLM REVISE	D ** BLM REVISED ** BLI	M REVISED	** BLM REVISE	D **						

Synergy # 130 – Summary

8/18/20 - Synergy # 130

Notify NMOCD and BLM of planned MIT test. MIRU WSI Enterprises. Perform MIT test on 5-1/2" production casing and CIBP @ 650'. Test to 530# and chart for 30 mins. Good Test. Move to Synergy # 142.

8/30/20 - MIRU 1'' Poly coil equipment. ND WH, GIH w/ 1'' poly coil with connection at 500' of roll, spool in the hole and tag up on CIBP at 650'. NU WH and fitting, ready for cement crew and cementing notification.

9/11/20 – BLM Representative Jimmie Dobson witnessing cement activity. MIRU Aztec Well Service Cementers. ND WH, NU Cementing Wellhead assembly for poly pipe. Dig out around wellhead with backhoe. Establish circulation with fresh water, pump 12 bbls Fresh Water Ahead, Pump 92 sacks total cement (108.56 ft3) at 15.6 ppg, circulate cement to surface. Cement Plug from 650' to Surface. ND WH. Welder Cut off wellhead below ground level. Check Surface cement depth at 24', Fill and Top off Cellar with cement. Wash Up Equipment. RD and Release Equipment to Farmington Yard.

