Submit 3 Copies To Appropriate District	State of New Me	xico	Form C-103
Office — ~ ~ District I	Energy, Minerals and Natural Resources		May 27, 2004_
1625 N. French Dr., Hobbs, NM 88240	Ziivi DJ , I.IIIi zi wi wi I i i i i i i i i i i i i i i i		WELL API NO.
District II	OIL CONSERVATION	DIVISION	30-039-21598
1301 W. Grand Ave., Artesia, NM 88210		•	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran		STATE FEE
District IV	Santa Fe, NM 87	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		456	NMNM14920
87505		100/3	<u></u>
(DO NOT USE THIS FORM FOR PROPO	TICES AND REPORTS ON WELLS SEALS TO DRILL OR TO DEEPEN ON THE ICATION FOR PERMIT" (FORM C-1971) FOR	JG BACK TO A	7. Lease Name or Unit Agreement Name VALENCIA CANYON UNIT
1. Type of Well: Oil Well	Gas Well X Other	A 9 0	8. Well Number 17
2. Name of Operator XTO ENERGY INC.	E. C.	T. SON.	9./OGRID Number 167067
3. Address of Operator	V.	35. 119	710. Pool name or Wildcat
2700 FARMINGTON AVE, SUITE K-1, FARMINGTON, NM 8740 CHOZA MESA PICTURED CLIFFS			
4. Well Location			
Unit Letter: N;	1040 feet from the SOUTH	line and <u>1570</u>	
Section 26 To		4W NMF	
	11. Elevation (Show whether DR,	RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application X	or Closure		
Pit type WORKOVER Depth to Groundwater >100' Distance from nearest fresh water well >100' Distance from nearest surface water >1000'			
Pit Liner Thickness: 12 mil Belo	w-Grade Tank: Volume	bbls; Construction	viateriai
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF I	NTENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS.□ P AND A □
PULL OR ALTER CASING		CASING/CEMENT	JOB 🗍
	-		_
OTHER: WORKOVER PIT	X	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
•			
XTO Energy plans to install a lined	workover pit for cement and water	used during Plug &	Abandon operations. The pit will be
	OCD Guidelines after work is comple		
	,		
11 1 2 2 4 6 2			
I hereby certify that the information	above is true and complete to the be	est of my knowledge	e and belief. I further certify that any pit or below-
grade tank has been will be constructed or closed according to NMOCD guidelines _, a general permit _ or an (attached) alternative OCD-approved plan			
SIGNATURE AND LANGE			
SIGNATURE TITLE REGULATORY COMPLIANCE TECH DATE 3/3/05 Type or print name HOLLY C. PERKINS. E-mail address: Holly parking@utonorgy.com. Telephone No. 505 324 1000			
Type or print name HOLLY C. PERKINS E-mail address: Holly perkins@xtoenergy.com Telephone No. 505-324-1090			
For State Use Only MAR - 7 2005			
For State Use Only	RKINS E-mail address: Holly pe	rkins@xtoenergy.co	m Telephone No. 505-324-1090
	RKINS E-mail address: Holly pe	rkins@xtoenergy.co	m Telephone No. 505-324-1090
APPROVED BY: 1 1	RKINS E-mail address: Holly per	rkins@xtoenergy.co	
	RKINS E-mail address: Holly pe	rkins@xtoenergy.co	m Telephone No. 505-324-1090