## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## RECEIVED

OCT 18 2011

Sundry Notices and Reports on Wells		Farmington Field Office
	5.	Bureau of Land Managemen, Lease Number
	٥.	SF-079514
1. Type of Well GAS	6.	If Indian, All. or Tribe Name
2. Name of Operator  BURLINGTON	7.	Unit Agreement Name San Juan 29-7 Unit
RESCURCES OIL & GAS COMPANY LP  3. Address & Phone No. of Operator	8.	Well Name & Number San Juan 29-7 Unit 83M
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.
4. Location of Well, Footage, Sec., T, R, M		30-039-30713
Surface: Unit H (SENE), 2105' FNL & 1295' FEL, Section 3, T29N, R7W, NMPM	10.	Field and Pool Blanco MV/Basin DK
BH: Unit J (NWSE), 1999' FSL, & 1763' FEL, Section 3, T29N, R7W, NMPM	11.	County and State Rio Arriba, NM
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OT	THER	DATA
Type of Submission Type of Action  Notice of Intent Abandonment Change of Plans Recompletion New Construction	<u> x</u>	Other - Cathodic
X Subsequent Report Plugging Non-Routine Fracturing Casing Repair Water Shut off		
Final Abandonment Altering Casing Conversion to Injection	_	
13. Describe Proposed or Completed Operations Attached is a drawing for the placement of the cathodic ground, rectifier and cable for the subject	t well	RCVD OCT 25 '11
		OIL CONS. DIV.
		DIST. 3
14. I hereby certify that the foregoing is true and correct.		
Signed Inth OUTILL Denise Journey Title: Staff Regula	atory ]	Cechnician Date 10-17-1
(This space for Federal or State Office use)  APPROVED BY		_ Date
CONDITION OF APPROVAL, if any:  Title 18 U S C Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction	D EV	R RECORN

NMOCD

...


OCT 1 8 2011


FARMINGTON FIELD OFFICE BY \_\_\_\_\_\_/\_\_\_ QC



## San Juan 29-7 Unit 83M & 83B

Section 3, T29N, R7W, N.M.P.M., Rio Aribba County, NM





Drill ground bed #2 approximately 102' south of #83M wellhead at staked location. Upgrade existing CPS #2239W to a 40-16 3 negative rectifier, and relocate to staked location on entrance to location. Extend existing positive to existing ground bed and existing negative to #533 wellhead and make repairs as needed Install cables to new ground bed #2 and #83M & #83B wellheads at lengths below. Split costs between both wells.

#83M Cables

Negative 396'

G.B. #2 Positive 498'

#83B Cables

Negative. 294'

Existing Cables ≈ 20'

Total Ditch. 518'

By: Steven Gillette Date 8/8/10