submitted in lieu of Form 3160-5

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Type of Well GAS  Name of Operator  ConocoPhillips  Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700  Location of Well, Footage, Sec., T, R, M Unit D (NWNW), 790' FNL & 790' FWL, Section 28, T2	JAN 31 2012  Farmington Field Office Bureau of Land Managen	6. If Ind Tribe 10017. Unit A Linda - 8. Well I Linda	e Number 78914 lian, All. or e Name Agreement Name rith B Unit Name & Number rith B Unit 1	
ConocoPhillips  Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700  Location of Well, Footage, Sec., T, R, M	Farmington Field Office Bureau of Land Managen	6. If Ind Tribe  ner  ner  8. Well Linds  9. APIV	lian, All. or Name Agreement Name rith B Unit Name & Number rith B Unit 1	
ConocoPhillips  Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700  Location of Well, Footage, Sec., T, R, M	Bureau of Land Manage	- 8. Well Linds Linds  9. API V	rith B Unit  Name & Number  rith B Unit 1	
PO Box 4289, Farmington, NM 87499 (505) 326-9700  Location of Well, Footage, Sec., T, R, M		Lindi 9. API V –	rith B Unit 1	
PO Box 4289, Farmington, NM 87499 (505) 326-9700  Location of Well, Footage, Sec., T, R, M		Lindi 9. API V –	rith B Unit 1	
Location of Well, Footage, Sec., T, R, M		_	Well No.	
		30-03		
			30-039-22137	
Unit D (NWNW), 790' FNL & 790' FWL, Section 28, T24N, R3W, NMPM			and Pool indrith Gallup DK	
			ty and State Arriba, NM	
2. CHECK APPROPRIATE BOX TO INDICATE NATUR	RE OF NOTICE, REPORT, O	THER DATA		
Type of Submission Type of Action  Notice of Intent Abandonment	Change of Plans	X Other –	Payadd	
X Subsequent Report Plugging Casing Repair Final Abandonment Altering Casing	New Construction Non-Routine Fracturing Water Shut off Conversion to Injection			
3. Describe Proposed or Completed Operations				
Please See Attached				
		• • • •	WD FEB 3'12	
		OI	L CONS. DIV.	
			DIST. 3	
4. I hereby certify that the foregoing is true and correct.				
Signed Crystal Tarloup Crystal T	afoya Title Staff Regula	atory Technician	Date 1/31/20	
		Date _		
CONDITION OF APPROVAL, if any: itle 18 U S C Section 1001, makes it a crime for any person knowingly and willfully to make any depart the United States any false, fictitious or fraudulent statements or representations as to any matter within its	gurisdiction	ASSEPTED P	or record	
	a	FEB 0		
	NNOCD	PLD U		

PC

Lindrith B Unit 1 API# 3003922137 West Lindrith Gallup Dakota ConocoPhillips Company

**12/2/2011** MIRU AWS 448. ND WH. NU BOPE. PT BOPE. Test – OK. POOH w/ tbg.

12/7/2011 RIH w/ CBP @ 7100'. Run GR/CCL/CBL. TOC @ 3354'. RD W/L.

12/8/2011 PT 4 ½" csg to 1000#. Test – Failed.

12/10/2011 Set Compression Pkr @ 6007'. Test 4 ½" csg from 6007' – Surface @ 3000#. Test – OK. POOH w/ Pkr @ 6007'.

12/12/2011 Set RBP @ 6007'. PT 4 ½" csg to 3600#/30min. Test – OK. POOH w/ RBP.

**12/13/2011** RD RR @ 15:30hrs.

**12/27/2011** Install Frac valve. PT to 3600#/30min. Test – OK.

12/28/2011 RU W/L to Perf Gallup w/ .34" diam. – 2SPF @ 6386', 6367', 6345', 6341', 6331', 6310', 6302', 6295', 6286', 6278', 6270', 6268', 6252', 6252', 6247', 6246', 6242', 6198', 6186', 6180' = 40 Holes. Acidize w/ 10bbls 15% HCl. Frac w/ 176,232gals SlickWater w/ 12,740# of 100 Mesh Sand & 90,000# of 40/70 Sand Brown.

12/29/2011 Set CBP @ 6000'. RD RR Flowback & Frac Equipment.

**1/16/2012** MIRU KEY 12.

1/17/2012 ND WH. NU BOPE. PT BOPE. Test – OK. Tag CBP @ 6000' & M/O.

1/18/2012 C/O to GBP @ 7100'. Flowback.

1/18/2012 Notified BLM (Stephen Mason) & OCD (Brandon Powell) of request to leave CBP @ 7100' & flow upper Gallup formation & drill out CBP at a later date. Verbal approval received.

**1/23/2012** Flow Test Gallup.

1/24/2012 RIH w/ 211jts, 2 3/8", 4.7#, J-55 tbg set @ 6630' w/ F-Nipple @ 6598'. ND BOPE. NU WH.

1/25/2012 RIH w/ Pump & Rods. RD RR @ 06:00hrs on 1/25/12.