Form 3160-5 (April 2004)

## UNITED STATES: DEPARTMENT OF THE INTERIOR BURGALLOGE LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires March 31; 2007

BUREAU OF LAND MANAGEMENT 5. Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS. NMSF047039B Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name PM 12 abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side 200 IT HIR or GA/Agreement, Name and/or No. EARMINGTON NM 1. Type of Well 8. Well Name and No Oil Well X Gas Well Other JF DAY E #2 2. Name of Operator XTO Energy Inc. 9. API Well No. 3a. Address 30-045-32528 2700 Farmington Ave., Bldg, K. Ste 1 Farmington 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) BASIN DAKOTA OTERO CHACRA 855' FSL & 1,860' FWL SEC. N17, T28N, R10W 11 County or Parish, State 12 CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Production (Start/Resume) Notice of Intent Acidize Deenca Water Shirt-Off Fraginge Treat Reclamation Aher Czemo Well Integray X Subsequent Report Casing Repair New Construction Recomulete Other TO S ST PROD

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Band under which the work will be performed or provide the Bond No, on the with BLM/BLA. Required subsequent reports shall be filled within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filled once testing has been completed. Final Abandonment Notices shall be filled only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

Place and Abandon

Plug Back

Temporarily Abandon

Water Disposal

Change Plans

Convert to Injection

Reached driller's TD of 6,858' KB @ 9:00 a.m., 02/27/05. TIH w/166 jts 5-1/2", 15.5#, J-55, LT&C csg to 6,853' KB. Cmt'd csg as follows: 450 sx Premium Lite HS w/0.5% FL-32, 0.2% CD-32, 1/4 PPS celloflake & 2% phenoseal (mixed @ 12.5 ppg & 2.01 cuft/sx) followed by 100 sx Type III Neat cmt (mixed @ 14.2 ppg & 1.42 cuft/sx). Dropped bomb & op DV tool. Cmtd 2nd stage as follows: 800 sx Type III w/8% gel, 1/4 PPS celloflake & 2% phenoseal (mixed @ 11.9 ppg & 2.60 cuft/sx) followed by 100 sx Type III Neat cmt (mixed @ 14.5 ppg & 1.39 cuft/sx). Closed DV tool. Circ 85 bbls cmt to surf. Release Patterson #743 03/02/05.

\*\*PRODUCTION: CSG WILL BE PRESSURE TESTED @ COMPLETION\*\*

Final Abandonment Notice

14. Thereby certify that the foregoing is true and correct Name (PrintedTyped)  KELLY K. SMALL	Title DRILLING ASSI	STANT
Love & Small	Date 03/02/05	ACCEPTED FOR RECORD
THIS SPACE FOR FEI	DERAL OR STATE OFFICE US	
Approved by	Title	D₩AR 1 ∩ 2005
Conditions of approval, if any, are attached. Approval of this notice does not vertify that the applicant holds legal or equitable talle to those rights in the subwhich would entitle the applicant to conduct operations thereon.	warrant or Office bject lease	FARMING UP FIELD OFFICE BY

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fletitions or fraudulent statements or representations as to any matter within its jurisdiction.