

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB NO. 1004-0137  
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such purposes.

5. Lease Serial No.

NM020501

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.  
OHIO C GOVT #3E

9. API Well No.

30-045-24335

10. Field and Pool, or Exploratory Area  
BASIN DAKOTA

11. County or Parish, State

SAN JUAN NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- |                                               |                                                      |                                                    |                                         |
|-----------------------------------------------|------------------------------------------------------|----------------------------------------------------|-----------------------------------------|
| <input type="checkbox"/> Acidize              | <input type="checkbox"/> Deepen                      | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input type="checkbox"/> Alter Casing         | <input type="checkbox"/> Fracture Treat              | <input type="checkbox"/> Reclamation               | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Casing Repair        | <input type="checkbox"/> New Construction            | <input type="checkbox"/> Recomplete                | <input type="checkbox"/> Other          |
| <input type="checkbox"/> Change Plans         | <input checked="" type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon       |                                         |
| <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back                   | <input type="checkbox"/> Water Disposal            |                                         |

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

XTO Energy Inc. P&A'd this well by: MIRU serv rig. Rlsd TAC. TIH w/NC, SN & tbg. EOT @ 5931'. ND BOP; NU WH. Rptd to Charlie Perrin w/NMOCD @ 4:15 p.m. & Ron Snow w/BLM @ 4:30 p.m. about procedure to P&A. Steve Hayden appr P&A procedure @ 8:30 a.m. 3/31/05. MIRU cmt trks. Stung into CICR. Repeated 3 times. Ppd dwn tbg w/15 sx cmt (15.6 #/gal, 1.18 ft/sx) 3 bbls cmt. Cmt plug fr/5996' (CICR) to 5799'. Rptd progress to Charlie Perrin w/NMOCD @ 9:00 a.m. 4/1/05. Rcv'd appr to continue. TIH w/NC, tbg. RU cmt trk. PT csg to 500 psig. Ppd 25 sx (15.6 #/gal, 1.18 ft/sx), 5.3 bbls cmt. Cmt plug fr/52130'-4915'. WOC 4 hrs. TOH w/tbg. LD 6 jts tbg full of cmt. TIH w/tbg. Ppd 25 sx (15.6 #/gal, 1.18 ft/sx) 5.3 bbls cmt. Cmt plug fr/3188'-2855'. RD cmt trk. Oscar Torres w/BLM witnessed operations. RU cmt equip. Ppd dwn tbg w/11 sx (15.6 #/gal, 1.18 cuft/sx) 2.3 bbls cmt. Cmt plug fr/2599'-2448'. Ppd dwn tbg w/11 sx (15.6 ppg #/gal, 1.18 cuft/sx) 2.3 bbls cmt. Plug fr/1650'-1446'. MIRU WLU. Perf'd 3 sqz holes @ 1342'. RD WLU. Ppd dwn tbg w/15 sx (15.6 #/gal, 1.18 cuft/sx) 3.2 bbls cmt. Plug fr/1404'-1204'. RU WLU. Perf'd 3 sqz holes @ 740'. RD WLU. Ppd dwn tbg w/11 sx (15.6 #/gal, 1.18 cuft/sx) 2.3 bbls cmt. Plug fr/793'-648'. RU WLU. Perf'd 3 sqz holes @ 568'. Ppd dwn tbg w/8 sx (15.6 #/gal, 1.18 cuft/sx) 1.6 bbls cmt. Plug fr/617'-517'. RU WLU. Perf'd 3 sqz holes @ 418'. RDMO WLU. Ppd dwn 4-1/2" csg & EIR fr/7" csg @ 0.8 BPM @ 1450 psig. Circ clean. Ppd dwn 4-1/2" csg w/97 sx (15.6 ppg, 1.18 cuft/sx) 2.0 bbls cmt. Circ cmt to surf. ND BOP. RDMO cmt trks. Oscar Torres w/BLM witnessed operations. RDMO rig. Plug 1956'-1811'

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

HOLLY C. PERKINS

Title

REGULATORY COMPLIANCE TECH

Date 4/11/05

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by

Title

APR 14 2005

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCD