



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

April 28, 2005

Mr. Ray Martin
XTO Energy, Inc.
2700 Farmington Avenue
Bldg K, Suite 1
Farmington, NM 87401

Re: Sullivan Frame A 1E, A 30-29N-10W API 30-045-24432

Dear Mr. Martin:

The 2005 Packer Leakage Test on the referenced well indicates communication between the producible zones. In order to comply with Rule #112A, you are hereby directed to initiate remedial activity and retest the well to show separation of the zones prior to August 1, 2005. Notify the Aztec OCD in time to witness the retest.

Reference RBDMS-CTP0511760360 on your sundries and any other communication regarding this failure and repair.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Charlie T. Perrin
District III Supervisor
cperrin@state.nm.us

CTP/mk

CC: CTP
Well File