Form 3160-5 (April 2004)

Approved by

Original Signed: Stephen Mason

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO-1004-0137 Expires March 31, 2007

5. Lease Serial No.

NAME OF THE PERSON OF THE PERS
INMSHI

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-entering abandoned well. Use Form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE-	7. If Unit or CA/Agreement, Name and/or No	
1. Type of Well Oil Well X Gas Well Other 2. Name of Operator XTO Energy Inc. 3a. Address	3b Phone, No. (include	8. Well Name and No. SCHWERDTFEGER A #23  9. API Well No.
2700 Farmington Ave., Bldg. K. Ste 4. Location of Well (Footage, Sec., T., R., M., or Survey, 810' FSL & 1844' FEL SEC 08-T27N-	1 Farmington, 9/5/505	(1 0)-045-11/05
12. CHECK APPROPRIATE	BOX(ES) TO INDICATE NATURE O	F NOTICE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION		TYPE OF ACTION
X Notice of Intent  Subsequent Report  Final Abandonment Notice	Acidize Deepen  Alter Casing Fracture Treat  Casing Repair New Construction  Change Plans X Plug and Abandon  Convert to Injection Plug Back	
If the proposal is to deepen directionally or recompartate the Bond under which the work will be perfollowing completion of the involved operations. Itesting has been completed. Final Abandonment determined that the final site is ready for final inspection. Proposes to plug 1. Notify BLM & NMOCD of pluggin 2. MIRU PU. NU relief line & bl 3. PU & tally 1.25" IJ they works 4. Plug #1: (PC perfs, FTC & Kir w/workstring & tag CIEP. Load composes to read subsequent plugs as a (in 2-stages), above CR to isolat 5. Plug #2 (Ojo Alamo top, 1920) perforating, then establish rate cag & leave 8 sx inside cag, disp wireline cmt retainer @ 1870'. It sqz 31 sx outside cag & leave 4 4 6. Plug #3 (8-5/8" surf cag, 293 w/wtr. Mix & pmp approx 80 sx ty	plete horizontally, give subsurface locations and nethermed or provide the Bond No. on file with BI if the operation results in a multiple completion of Notices shall be filed only after all requirements. ction.)  & abandon this well per the foliag operations.  Low dwn well; kill w/wtr as necessaring. Round-trip 2.875" gauge: tland tops, 2786' - 1960'): RII ag w/wtr & circ well clean. PT appropriate. Mix 25 sx Type II: the PC perfs through the Kirtland in 1820'): Perf 3 bi-wire sqz linto sqz holes; mix & pmp 39 sx place to 1500'. WOC & tag cmt.  THE w/tbg & establish rate into a specific square to cover Ojo Alamo top in 1820': Perf 2 sqz holes perf cag flange. Install P&A markets.	ssary. ND WH & NU BOP. Test BOP. ring to 2786'. H & set 2.875" CIBP @ 2786'. TIH csg to 500#. If csg doesn't tst, then I cmt & spot a balanced plug inside csg top. TOH w/tbg. holes @ 1920'. If csg tstd before Type III cmt dwn csg; sqz 31 sx outside If csg doesn't tst, then set 2.875" sqz holes. Mix & pmp 35 sx Type III cmt, . TOH & LD tbg. @ 293'. Establish circ out BH valve rc good cmt out BH valve. SWEE WOC. ker w/cmt to comply w/regs. RIMO PU.
Name (Printed Typed)	Title	ŦŢ Ä

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Date

4/13/05

<u>ئ</u>

Z

Date