Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103
Office District I	Energy, Minerals and Natural Resou		May 27, 2004
1625 N. French Dr., Hobbs, NM 87240	•	WELL API NO.	
District II	OIL CONSERVATION DIVIS	ION 30-045-	
1301 W. Grand Ave., Artesia, NM 88210	1220 South St. Francis Dr	I E Indicata Traca	f Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM-87505	STATE X	fee □
District IV	Salla re, 1114-64500		
1220 S. St. Francis Dr., Santa Fe, NM 87505		6. State Oil & Gas	Lease No.
SUNDRY NOTICE	S AND REPORTS ON WILLS	(Q) 17 Lease Name or	Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLICA"	CALS TO DRILL OR TO DEEPEN OR AND STORE OF STREET OF STR	BACKEDO A STATE GAS COM A	•
PROPOSALS.)		=¶	
1. Type of Well:	Other 12 Maria	8. Well Number	
Oil Well Gas Well	Other Vers	#	
2. Name of Operator	(c)	9. OGRID Number	r
XTO Energy Inc.	CAN IS AND SI SI SI	167	067
3. Address of Operator		10. Pool name or	Wildcat
•	K. Ste 1 Farmington, NM 87401	AZTEC PC / BASI	IN FRUTTLAND COAL
4. Well Location	<u> </u>		
Unit Letter M:8	feet from the SOUTH	line and feet from	m the WEST line
Section 16	Township 31N Range	12W NMPM	County SAN JUAN
	11. Elevation (Show whether DR, RKB	RT, GR, etc.)	
Pit or Below-grade Tank Application	6,170' GL		
	Distance from nearest fresh water we	I Distance from nearest surf	ace water
Pit Liner Thickness: mil	Below-Grade Tank: Volumebb	ls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
12. Check A ₁	ppropriate Box to Indicate Nature	of Notice, Report, or Other	r Data
	· ·	• •	
NOTICE OF INTE	NTION TO:	SUBSEQUENT REI	PORT OF:
	NTION TO:	• •	
NOTICE OF INTE	NTION TO: PLUG AND ABANDON REMED	SUBSEQUENT REI	PORT OF: ALTERING CASING PLUG AND
NOTICE OF INTE	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS COMME MULTIPLE CASING	SUBSEQUENT REFINAL WORK	PORT OF: ALTERING CASING
NOTICE OF INTE	NTION TO: PLUG AND ABANDON ☐ REMED CHANGE PLANS ☐ COMME	SUBSEQUENT REFINAL WORK	PORT OF: ALTERING CASING PLUG AND
NOTICE OF INTERPRETATION TEMPORARILY ABANDON DULL OR ALTER CASING	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS COMME MULTIPLE COMPLETION CASING CEMEN	SUBSEQUENT REFINAL WORK INCE DRILLING OPNS. T JOB	PORT OF: ALTERING CASING PLUG AND
NOTICE OF INTERPRETATION TEMPORARILY ABANDON DULL OR ALTER CASING OTHER:	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS COMME MULTIPLE CASING COMPLETION OTHER	SUBSEQUENT REFINAL WORK	PORT OF: ALTERING CASING PLUG AND ABANDONMENT
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS COMME MULTIPLE COMPLETION CASING CEMEN	SUBSEQUENT REF	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Cluding estimated date
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion.	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS COMME MULTIPLE CASING COMPLETION OTHER Operations. (Clearly state all pertinent de	SUBSEQUENT REF	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Pluding estimated date f proposed completion
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. Reached driller's TD of 2,7	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS COMME MULTIPLE COMPLETION CASING CEMEN OTHER operations. (Clearly state all pertinent de SEE RULE 1103. For Multiple Comple	SUBSEQUENT REFINAL WORK INCE DRILLING OPNS. TEST AND TOB tails, and give pertinent dates, incidents: Attach wellbore diagram of the wide of the wid	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Pluding estimated date f proposed completion
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. Reached driller's TD of 2, 2,806.47'. Cmtd prod csg w	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS CASING COMPLETION CASING CEMEN OTHER Operations. (Clearly state all pertinent de SEE RULE 1103. For Multiple Comple	SUBSEQUENT REFINAL WORK ENCE DRILLING OPNS. TEST AND T JOB tails, and give pertinent dates, inclines: Attach wellbore diagram of the control of the cont	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Pluding estimated date f proposed completion 4, J-55, LT&C csg to seal (mixed @ 11.9
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. Reached driller's TD of 2, 2,806.47'. Cmtd prod csg w ppg & 2.60 cuft/sx) follow	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS CASING COMME MULTIPLE COMPLETION CASING CEMEN OTHER Operations. (Clearly state all pertinent de SEE RULE 1103. For Multiple Comple 807' @ 9:30 p.m., 07/30/05. PU & //310 sox Cl. "C" cmt w/1/4 PPS cel. ed by 100 sox Cl. "C" cmt w/1/4 Cac.	SUBSEQUENT REFINAL WORK ENCE DRILLING OPNS. TEST AND T JOB Tails, and give pertinent dates, inclines: Attach wellbore diagram of the control of the con	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Pluding estimated date f proposed completion 4, J-55, LT&C csg to seal (mixed @ 11.9 s phenoseal (mixed @ 20.00 phenoseal (
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. Reached driller's TD of 2, 2,806.47'. Cmtd prod csg w ppg & 2.60 cuft/sx) follow	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS CASING COMPLETION CASING CEMEN OTHER Operations. (Clearly state all pertinent de SEE RULE 1103. For Multiple Comple	SUBSEQUENT REFINAL WORK ENCE DRILLING OPNS. TEST AND T JOB Tails, and give pertinent dates, inclines: Attach wellbore diagram of the control of the con	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Pluding estimated date f proposed completion 4, J-55, LT&C csg to seal (mixed @ 11.9 s phenoseal (mixed @ 20.00 phenoseal (
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. Reached driller's TD of 2, 2,806.47'. Cmtd prod csg w ppg & 2.60 cuft/sx) follow 14.5 ppg & 1.41 cuft/sx).	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS COMME MULTIPLE CASING CEMEN OTHER Operations. (Clearly state all pertinent de SEE RULE 1103. For Multiple Comple 807' © 9:30 p.m., 07/30/05. PU & /310 sx cl "C" cmt w/1/4 PPS celled by 100 sx cl "C" cmt w/1% Cacc circ 32 bbls cmt to surf. Release	SUBSEQUENT REFINAL WORK ENCE DRILLING OPNS. TEST AND T JOB Tails, and give pertinent dates, inclines: Attach wellbore diagram of the control of the con	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Pluding estimated date f proposed completion 4, J-55, LT&C csg to seal (mixed @ 11.9 s phenoseal (mixed @ 20.00 phenoseal (
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. Reached driller's TD of 2, 2,806.47'. Cmtd prod csg w ppg & 2.60 cuft/sxx) follow 14.5 ppg & 1.41 cuft/sxx). ***PRODUCTION CSG WILL BE P.	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS CASING COMME MULTIPLE COMPLETION CASING CEMEN OTHER Operations. (Clearly state all pertinent de SEE RULE 1103. For Multiple Comple 807' @ 9:30 p.m., 07/30/05. PU & //310 sox Cl. "C" cmt w/1/4 PPS cel. ed by 100 sox Cl. "C" cmt w/1/4 Cac.	SUBSEQUENT REFINAL WORK ENCE DRILLING OPNS. TEST AND T JOB Tails, and give pertinent dates, inclines: Attach wellbore diagram of the control of the con	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Pluding estimated date f proposed completion 4, J-55, LT&C csg to seal (mixed @ 11.9 s phenoseal (mixed @ 20.00 phenoseal (
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. Reached driller's TD of 2, 2,806.47'. Cmtd prod csg w ppg & 2.60 cuft/sx) follow 14.5 ppg & 1.41 cuft/sx).	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS COMME MULTIPLE CASING CEMEN OTHER Operations. (Clearly state all pertinent de SEE RULE 1103. For Multiple Comple 807' © 9:30 p.m., 07/30/05. PU & /310 sx cl "C" cmt w/1/4 PPS celled by 100 sx cl "C" cmt w/1% Cacc circ 32 bbls cmt to surf. Release	SUBSEQUENT REFINAL WORK ENCE DRILLING OPNS. TEST AND T JOB Tails, and give pertinent dates, inclines: Attach wellbore diagram of the control of the con	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Pluding estimated date f proposed completion 4, J-55, LT&C csg to seal (mixed @ 11.9 s phenoseal (mixed @ 20.00 phenoseal (
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. Reached driller's TD of 2, 2,806.47'. Cmtd prod csg w ppg & 2.60 cuft/sxx) follow 14.5 ppg & 1.41 cuft/sxx). **PRODUCTION CSG WILL BE P.	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS COMME MULTIPLE CASING CEMEN OTHER Operations. (Clearly state all pertinent de SEE RULE 1103. For Multiple Comple 807' @ 9:30 p.m., 07/30/05. PU & /310 sx Cl "C" cmt w/1/4 PPS celled by 100 sx Cl "C" cmt w/1/4 PPS celled by 100 sx Cl "C" cmt w/1/4 Release RESSURE TESTED @ COMPLETION**	SUBSEQUENT REFINAL WORK ENCE DRILLING OPNS. TEST AND T JOB Tails, and give pertinent dates, inclines: Attach wellbore diagram of the control of the con	PLUG AND ABANDONMENT PLUG AND ABANDONMENT Pluding estimated date f proposed completion A, J-55, LT&C csg to seal (mixed @ 11.9 s phenoseal (mixed @ 200 a.m., 08/01/05.
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. Reached driller's TD of 2, 2,806.47'. Cmtd prod csg w ppg & 2.60 cuft/sxx) follow 14.5 ppg & 1.41 cuft/sxx). ***PRODUCTION CSG WILL BE P.	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS COMME MULTIPLE CASING COMPLETION OTHER Operations. (Clearly state all pertinent de SEE RULE 1103. For Multiple Comple 807' 9:30 p.m., 07/30/05. PU & /310 sx Cl "C" cmt w/1/4 PPS celled by 100 sx Cl "C" cmt w/1/4 PPS celled by 100 sx Cl "C" cmt w/1/4 Release RESSURE TESTED @ COMPLETION**	SUBSEQUENT REFINAL WORK ENCE DRILLING OPNS. TEST AND TOB Tails, and give pertinent dates, inclines: Attach wellbore diagram of the wide of the wid	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Pluding estimated date f proposed completion F, J-55, LT&C csg to seal (mixed @ 11.9 s phenoseal (mixed @ 200 a.m., 08/01/05.
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. Reached driller's TD of 2, 2,806.47'. Cmtd prod csg w ppg & 2.60 cuft/sxx) follow 14.5 ppg & 1.41 cuft/sxx). ***PRODUCTION CSG WILL BE P.	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS COMME MULTIPLE CASING CEMEN OTHER Operations. (Clearly state all pertinent de SEE RULE 1103. For Multiple Comple 807' @ 9:30 p.m., 07/30/05. PU & /310 sx Cl "C" cmt w/1/4 PPS celled by 100 sx Cl "C" cmt w/1/4 PPS celled by 100 sx Cl "C" cmt w/1% Cacce and by 100 sx Cl "C" cmt w/1% Cacce as a bols cmt to surf. Release the strue and complete to the best of resed according to NMOCD guidelines , a seed according to NMOCD guidelines .	SUBSEQUENT REFINAL WORK ENCE DRILLING OPNS. TEST AND T JOB Tails, and give pertinent dates, inclines: Attach wellbore diagram of the second of the seco	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Pluding estimated date f proposed completion F, J-55, LT&C csg to seal (mixed @ 11.9 s phenoseal (mixed @ 200 a.m., 08/01/05.
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. Reached driller's TD of 2, 2,806.47'. Cmtd prod csg w ppg & 2.60 cuft/sx) follow 14.5 ppg & 1.41 cuft/sx). **PRODUCTION CSG WILL BE PRODUCTION CS	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS COMME MULTIPLE CASING CEMEN OTHER Operations. (Clearly state all pertinent de SEE RULE 1103. For Multiple Comple 807' @ 9:30 p.m., 07/30/05. PU & /310 sx Cl "C" cmt w/1/4 PPS celled by 100 sx Cl "C" cmt w/1/4 PPS celled by 100 sx Cl "C" cmt w/1% Cacce and by 100 sx Cl "C" cmt w/1% Cacce as a bols cmt to surf. Release the strue and complete to the best of resed according to NMOCD guidelines , a seed according to NMOCD guidelines .	SUBSEQUENT REFINAL WORK INCE DRILLING OPNS. TEST AND TOB Tails, and give pertinent dates, inclines: Attach wellbore diagram of the second o	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Pluding estimated date f proposed completion Pluding estimated dat
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. Reached driller's TD of 2, 2,806.47'. Cmtd prod csg w ppg & 2.60 cuft/sx) follow 14.5 ppg & 1.41 cuft/sx). **PRODUCTION CSG WILL BE PRODUCTION CS	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS COMME MULTIPLE CASING CEMEN OTHER Operations. (Clearly state all pertinent de SEE RULE 1103. For Multiple Comple 807' @ 9:30 p.m., 07/30/05. PU & //310 sox Cl "C" cmt w/1/4 PPS cell ed by 100 sox Cl "C" cmt w/1/4 PPS cell ed by 100 sox Cl "C" cmt w/1/4 Release RESSURE TESTED @ COMPLETION** Ove is true and complete to the best of resed according to NMOCD guidelines , a second coording to NMOCD guidelines , a second coording to NMOCD guidelines TITLE RE	SUBSEQUENT REFINAL WORK ENCE DRILLING OPNS. TIST AND TOB Tails, and give pertinent dates, inclines: Attach wellbore diagram of the second	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Pluding estimated date f proposed completion Pluding estimated dat
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. Reached driller's TD of 2, 2,806.47'. Cmtd prod csg w ppg & 2.60 cuft/sxx) follow 14.5 ppg & 1.41 cuft/sxx). **PRODUCTION CSG WILL BE POSITION CSG W	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS COMME MULTIPLE CASING CEMEN OTHER OPERATION OTHER OPERATION. (Clearly state all pertinent de SEE RULE 1103. For Multiple Comple 807' @ 9:30 p.m., 07/30/05. PU & //310 sx Cl "C" cmt w/1/4 PPS celled by 100 sx Cl "C" cmt w/1/4 PPS celled by 100 sx Cl "C" cmt w/1/4 Caccinc 32 bbls cmt to surf. Release RESSURE TESTED @ COMPLETION** Ove is true and complete to the best of resed according to NMOCD guidelines , a selection of the state of the st	SUBSEQUENT REFINAL WORK INCE DRILLING OPNS. THE TOTAL TOTAL TEST AND TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TEST AND TOTAL TOTAL TEST AND TOTAL TEST.	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Pluding estimated date f proposed completion Pluding estimated da
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. Reached driller's TD of 2, 2,806.47'. Cmtd prod csg w ppg & 2.60 cuft/sxx) follow 14.5 ppg & 1.41 cuft/sxx). **PRODUCTION CSG WILL BE POSITION CSG W	NTION TO: PLUG AND ABANDON REMED CHANGE PLANS COMME MULTIPLE CASING CEMEN OTHER OPERATION OTHER OPERATION REMED CASING CEMEN OTHER OPERATION CEMEN OTHER OPERATION OTHER OPERATIO	SUBSEQUENT REFINAL WORK INCE DRILLING OPNS. X TEST AND TOB Tails, and give pertinent dates, incicons: Attach wellbore diagram of the second	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Pluding estimated date f proposed completion Pluding estimated dat