Form 3160-5 (March 2012)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

FEB 04 2013 5. Lease Serial No.

Do not use this form for proposals to drill or to resenteran Field Officerilla Anache SUNDRY NOTICES AND REPORTS ON WELLS abandoned well. Use Form 3160-3 (APD) for such proposais Mana 3 cities. Apache 7. If Unit of CA/Agreement, Name and/or No SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No. ✓ Oil Well Gas Well Other Logos #2 2. Name of Operator Logos Operating, LLC 9. API Well No 30-043-21120 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 4001 North Butler, Building 7101 Farmington, New Mexico 87401 WC 22N5W6; Dakota(O) 97990 303-550-1877 4. Location of Well (Footage, Sec., T.R.M., or Survey Description) 1930' FSL & 730' FEL 11. County or Parish, State Sandoval, New Mexico Section 6, Township 22N, Range 5W 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Other DK Water shut off Casing Repair New Construction Recomplete ✓ Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Convert to Injection Plug Back Final Abandonment Noti Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 12/27/12 MIRU. TOOH with tubing and rods. 1/3/13 Set CIBP at 6263'. Pressure tested CIBP for 15 minutes- passed test. TIH with 2-7/8" tubing and set at 4777'. Ran in hole with tubing and rods and returned to production. RCVD FEB 18'13 OIL CONS. DIV. ACCEPTED FOR RECORD DIST. 3 FFR 1 1 2013 FARMINGTON FIELD OFFICE BY William Tambelcou a Grade Onfly feature Junds 14. I hereby certify that the foregoing is true and correct. Name (Printed/Oped) Title Director of Administration and Engineering Support Kristy Graham Date 01/25/2013 Signaturd THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by litte

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false. fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Office

entitle the applicant to conduct operations thereon.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would