

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

FORM 3160-5
OBSOLETE
Expires 11/31/1996

JUN 06 2013

Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.

35. Lease Serial No.
NM 86082
Office Indian, Allottee or Tribe Name



7. If Unit or CA/Agreement, Name and/or No.

1. Type of Well
 Oil Well Gas Well Other

8. Well Name and No.

2. Name of Operator
SG Interests I, Ltd, c/o Nika Energy Operating, LLC

WEST BISTI 26-12-5 #1

3a. Address
PO Box 2677, Durango, CO 81301

3b. Phone No. (include area code)
(970) 259-2701

9. API Well No.
30-045-29040

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1214' FNL, 1503' FEL (NWNE) Sec 5, T26N-R12W

10. Field and Pool, or Exploratory Area
Basin Fruitland Coal

11. County or Parish, State
San Juan, New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Deepen
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Fracture Treat
	<input type="checkbox"/> Production (Start/Resume)
	<input type="checkbox"/> Reclamation
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Well Integrity
	<input type="checkbox"/> Other
	<input checked="" type="checkbox"/> Plug & Abandon
	<input type="checkbox"/> Amended Sundry of Plug & Abandon
	<input type="checkbox"/> Convert to Injection
	<input type="checkbox"/> Plug Back
	<input type="checkbox"/> Water Disposal

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomplate in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

MIRU. Bradenhead press & CP 0 psi. TIH w/2 jts 2-3/8" tbg to tag fill to 1293.58' KB PBTD, show no fill. Pumped 3 bbls fresh water spacer, pump 13 sx type G cmt, 3 bbls @ 15.9#. TOOH w/40 jts 2-3/8" tbg, mule shoe. Let cmt set for 2 hrs. RIH w/junk basket to depth of 890' KB, tagged fluid then went to 1100' KB. Tagged cmt. POOH w/junk basket. RIH to 1025' KB to set 4-1/2" CIBP. TIH w/13 jts 2-3/8" tbg to depth of 410' KB. pumped 1 bbl fresh water spacer, pumped 45 sx type G cmt, 9 bbls @ 15.9#. POOH w/tbg. RIH w/hose to 300' KB. Pumped 13 sx Type G cmt to surface. RD @ 3:30 p.m. 3/26/13. Cmt @ surface on 3/27/13, installed P&A marker, waiting on orders from NAPI, NMOCD & BLM to totally reclaim location. (BLM rep Jamie Joe on location during P&A).

RCVD JUN 11 '13
OIL CONS. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

William Schwab III

Title

Agent for SG Interests I Ltd

Signature

Date

June 5, 2013

THIS SPACE FOR FEDERAL OR STATE USE

Approved by

Title

Date

Office

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

NMOCD

AV

ACCEPTED FOR RECORD

JUN 07 2013

FARMINGTON FIELD OFFICE

AV