Submit 3 Copies To Appropriate District Office District I State of New Mexico Energy, Minerals and Natural Resources	Form C-103 June 19, 2008
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30.045-33981 5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name STATE GAS COM BD
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 01R
2. Name of Operator	9. OGRID Number
XTO ENERGY, INC.	5380
3. Address of Operator 382 CR 3100, AZTEC, NM 87410	10. Pool name or Wildcat BASIN DAKOTA/BLANCO MESAVERDE
4. Well Location	
Unit Letter K: 1975' feet from the SOUTH line and 1960' feet from the WEST line	
	ounty SAN JUAN
11. Elevation (Show whether DR, RKB, RT, GR, etc 6056' GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUE	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	_
	ILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	II JOB
DOWINHOLE COMMININGLE	
OTHER: OTHER: SET C	
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar	nd give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15'13
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15'13
 Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations fr/6,825' - 7,0 	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15'13 35' per the followin DIL CONS. DIV.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations fr/6,825' - 7,0 10/3/13: MIRU 	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15'13 35' per the followin BIL CONS. DIV. DIST. 3
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations fr/6,825' - 7,0 10/3/13: MIRU 10/5/13: Set CIBP. Notified Charlie Perrin w/NMOCD @ 11:00 am for MIT test schedule 10/7/13: Realized CIBP was set @ 6,838'. Reset CIBP @ 6,775' & Set Pkr @ 6,740'. Left 	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15 '13 35' per the followin DIL CONS. DIV. DIST. 3 d for 1:00 pm on 10/7/13.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations fr/6,825' - 7,0 10/3/13: MIRU 10/5/13: Set CIBP. Notified Charlie Perrin w/NMOCD @ 11:00 am for MIT test schedule 10/7/13: Realized CIBP was set @ 6,838'. Reset CIBP @ 6,775' & Set Pkr @ 6,740'. Let MIT test @ 9:00 am on 10/8/13. 	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15 '13 35' per the followin DIL CONS. DIV. DIST. 3 d for 1:00 pm on 10/7/13. et message w/Brandon Powell w/NMOCD for
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations fr/6,825' - 7,0 10/3/13: MIRU 10/5/13: Set CIBP. Notified Charlie Perrin w/NMOCD @ 11:00 am for MIT test schedule 10/7/13: Realized CIBP was set @ 6,838'. Reset CIBP @ 6,775' & Set Pkr @ 6,740'. Let MIT test @ 9:00 am on 10/8/13. 10/8/13: PT CIBP @ 6,775' to 700 psig for 10". Tstd OK. Notified Brandon Powell w/NM 	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15 '13 35' per the followin DIL CONS. DIV. DIST. 3 d for 1:00 pm on 10/7/13. et message w/Brandon Powell w/NMOCD for
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations fr/6,825' – 7,0 10/3/13: MIRU 10/5/13: Set CIBP. Notified Charlie Perrin w/NMOCD @ 11:00 am for MIT test schedule 10/7/13: Realized CIBP was set @ 6,838'. Reset CIBP @ 6,775' & Set Pkr @ 6,740'. Lef MIT test @ 9:00 am on 10/8/13. 10/8/13: PT CIBP @ 6,775' to 700 psig for 10". Tstd OK. Notified Brandon Powell w/NN am on 10/9/13. 10/9/13: . TIH w/2-3/8", 4.7#, 8rd, EUE tbg. SN@ 4,856. EOT 4,857. XTO,PT CIBP to	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15 '13 35' per the followin DIL CONS. DIV. DIST. 3 d for 1:00 pm on 10/7/13. dt message w/Brandon Powell w/NMOCD for MOCD @ 3:30 pm on 10/8/13 fir MIT @ 9:00 to 570 psig for 30 min w/chart, please see
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations fr/6,825' – 7,0 10/3/13: MIRU 10/5/13: Set CIBP. Notified Charlie Perrin w/NMOCD @ 11:00 am for MIT test schedule 10/7/13: Realized CIBP was set @ 6,838'. Reset CIBP @ 6,775' & Set Pkr @ 6,740'. Let MIT test @ 9:00 am on 10/8/13. 10/8/13: PT CIBP @ 6,775' to 700 psig for 10". Tstd OK. Notified Brandon Powell w/NN am on 10/9/13. 10/9/13: TIH w/2-3/8", 4.7#, 8rd, EUE tbg. SN@ 4,856. EOT 4,857. XTO.PT CIBP to attached chart. MV prefs fr/4,709'-4,933'. DK perfs fr/6,825'-7,035'. Paul Washe on loc	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15 '13 35' per the followin DIL CONS. DIV. DIST. 3 d for 1:00 pm on 10/7/13. d message w/Brandon Powell w/NMOCD for MOCD @ 3:30 pm on 10/8/13 fir MIT @ 9:00 0 570 psig for 30 min w/chart, please see to witness MIT tst.
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations fr/6,825' – 7,0 10/3/13: MIRU 10/5/13: Set CIBP. Notified Charlie Perrin w/NMOCD @ 11:00 am for MIT test schedule 10/7/13: Realized CIBP was set @ 6,838'. Reset CIBP @ 6,775' & Set Pkr @ 6,740'. Lef MIT test @ 9:00 am on 10/8/13. 10/8/13: PT CIBP @ 6,775' to 700 psig for 10". Tstd OK. Notified Brandon Powell w/NN am on 10/9/13. 10/9/13: . TIH w/2-3/8", 4.7#, 8rd, EUE tbg. SN@ 4,856. EOT 4,857. XTO,PT CIBP to	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15 '13 35' per the followin DIL CONS. DIV. DIST. 3 d for 1:00 pm on 10/7/13. d message w/Brandon Powell w/NMOCD for MOCD @ 3:30 pm on 10/8/13 fir MIT @ 9:00 0 570 psig for 30 min w/chart, please see to witness MIT tst.
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations fr/6,825' – 7,0 10/3/13: MIRU 10/5/13: Set CIBP. Notified Charlie Perrin w/NMOCD @ 11:00 am for MIT test schedule 10/7/13: Realized CIBP was set @ 6,838'. Reset CIBP @ 6,775' & Set Pkr @ 6,740'. Let MIT test @ 9:00 am on 10/8/13. 10/8/13: PT CIBP @ 6,775' to 700 psig for 10". Tstd OK. Notified Brandon Powell w/NN am on 10/9/13. 10/9/13: TIH w/2-3/8", 4.7#, 8rd, EUE tbg. SN@ 4,856. EOT 4,857. XTO.PT CIBP to attached chart. MV prefs fr/4,709'-4,933'. DK perfs fr/6,825'-7,035'. Paul Washe on loc	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15 '13 35' per the followin DIL CONS. DIV. DIST. 3 d for 1:00 pm on 10/7/13. d message w/Brandon Powell w/NMOCD for MOCD @ 3:30 pm on 10/8/13 fir MIT @ 9:00 0 570 psig for 30 min w/chart, please see to witness MIT tst.
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations fr/6,825' – 7,0 10/3/13: MIRU 10/5/13: Set CIBP. Notified Charlie Perrin w/NMOCD @ 11:00 am for MIT test schedule 10/7/13: Realized CIBP was set @ 6,838'. Reset CIBP @ 6,775' & Set Pkr @ 6,740'. Let MIT test @ 9:00 am on 10/8/13. 10/8/13: PT CIBP @ 6,775' to 700 psig for 10". Tstd OK. Notified Brandon Powell w/NN am on 10/9/13. 10/9/13: TIH w/2-3/8", 4.7#, 8rd, EUE tbg. SN@ 4,856. EOT 4,857. XTO.PT CIBP to attached chart. MV prefs fr/4,709'-4,933'. DK perfs fr/6,825'-7,035'. Paul Washe on loc	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15 '13 35' per the followin DIL CONS. DIV. DIST. 3 d for 1:00 pm on 10/7/13. d message w/Brandon Powell w/NMOCD for MOCD @ 3:30 pm on 10/8/13 fir MIT @ 9:00 0 570 psig for 30 min w/chart, please see to witness MIT tst.
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations fr/6,825' – 7,0 10/3/13: MIRU 10/5/13: Set CIBP. Notified Charlie Perrin w/NMOCD @ 11:00 am for MIT test schedule 10/7/13: Realized CIBP was set @ 6,838'. Reset CIBP @ 6,775' & Set Pkr @ 6,740'. Let MIT test @ 9:00 am on 10/8/13. 10/8/13: PT CIBP @ 6,775' to 700 psig for 10". Tstd OK. Notified Brandon Powell w/NN am on 10/9/13. 10/9/13: . TIH w/2-3/8", 4.7#, 8rd, EUE tbg. SN@ 4,856. EOT 4,857. XTO.PT CIBP to attached chart. MV prefs fr/4,709'-4,933'. DK perfs fr/6,825'-7,035'. Paul Webe on loc 10/10/13: PWOPL. Drpd BHBS & dial pad plngr. RDMO Returned only the Mesaverde to Spud Date:	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15 '13 35' per the followin DIL CONS. DIV. DIST. 3 d for 1:00 pm on 10/7/13. d message w/Brandon Powell w/NMOCD for MOCD @ 3:30 pm on 10/8/13 fir MIT @ 9:00 0 570 psig for 30 min w/chart, please see to witness MIT tst.
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations fr/6,825' – 7,0 10/3/13: MIRU 10/5/13: Set CIBP. Notified Charlie Perrin w/NMOCD @ 11:00 am for MIT test schedule 10/7/13: Realized CIBP was set @ 6,838'. Reset CIBP @ 6,775' & Set Pkr @ 6,740'. Let MIT test @ 9:00 am on 10/8/13. 10/8/13: PT CIBP @ 6,775' to 700 psig for 10". Tstd OK. Notified Brandon Powell w/NN am on 10/9/13 TIH w/2-3/8", 4.7#, 8rd, EUE tbg. SN@ 4,856. EOT 4,857. XTO PT CIBP to attached chart. MV prefs fr/4,709'-4,933'. DK perfs fr/6,825'-7,035'. Paul Webbe on loc 10/10/13: PWOPL. Drpd BHBS & dial pad plngr. RDMO Returned only the Mesaverde to Spud Date: Rig Release Date:	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15 '13 35' per the followin DIL CONS. DIV. DIST. 3 d for 1:00 pm on 10/7/13. It message w/Brandon Powell w/NMOCD for MOCD @ 3:30 pm on 10/8/13 fir MIT @ 9:00 25 570 psig for 30 min w/chart, please see to witness MIT tst. To production.
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations fr/6,825' – 7,0 10/3/13: MIRU 10/5/13: Set CIBP. Notified Charlie Perrin w/NMOCD @ 11:00 am for MIT test schedule 10/7/13: Realized CIBP was set @ 6,838'. Reset CIBP @ 6,775' & Set Pkr @ 6,740'. Let MIT test @ 9:00 am on 10/8/13. 10/8/13: PT CIBP @ 6,775' to 700 psig for 10". Tstd OK. Notified Brandon Powell w/NN am on 10/9/13. 10/9/13: . TIH w/2-3/8", 4.7#, 8rd, EUE tbg. SN@ 4,856. EOT 4,857. XTO.PT CIBP to attached chart. MV prefs fr/4,709'-4,933'. DK perfs fr/6,825'-7,035'. Paul Webe on loc 10/10/13: PWOPL. Drpd BHBS & dial pad plngr. RDMO Returned only the Mesaverde to Spud Date:	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15 '13 35' per the followin OLCONS. DIV. DIST. 3 d for 1:00 pm on 10/7/13. It message w/Brandon Powell w/NMOCD for MOCD @ 3:30 pm on 10/8/13 fir MIT @ 9:00 25 570 psig for 30 min w/chart, please see to witness MIT tst. To production.
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations fr/6,825' – 7,0 10/3/13: MIRU 10/5/13: Set CIBP. Notified Charlie Perrin w/NMOCD @ 11:00 am for MIT test schedule 10/7/13: Realized CIBP was set @ 6,838'. Reset CIBP @ 6,775' & Set Pkr @ 6,740'. Let MIT test @ 9:00 am on 10/8/13. 10/8/13: PT CIBP @ 6,775' to 700 psig for 10". Tstd OK. Notified Brandon Powell w/NN am on 10/9/13. 10/9/13: . TIH w/2-3/8", 4.7#, 8rd, EUE tbg. SN@ 4,856. EOT 4,857. XTO.PT CIBP to attached chart. MV prefs fr/4,709'-4,933'. DK perfs fr/6,825'-7,035'. Paul Webe on loc 10/10/13: PWOPL. Drpd BHBS & dial pad plngr. RDMO Returned only the Mesaverde to Spud Date: Rig Release Date: Rig Release Date:	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15 '13 and 55' per the followin BIL CONS. DIV. DIST. 3 d for 1:00 pm on 10/7/13. It message w/Brandon Powell w/NMOCD for MOCD @ 3:30 pm on 10/8/13 fir MIT @ 9:00 to 570 psig for 30 min w/chart, please see to witness MIT tst. to production.
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations fr/6,825' – 7,0 10/3/13: MIRU 10/5/13: Set CIBP. Notified Charlie Perrin w/NMOCD @ 11:00 am for MIT test schedule 10/7/13: Realized CIBP was set @ 6,838'. Reset CIBP @ 6,775' & Set Pkr @ 6,740'. Let MIT test @ 9:00 am on 10/8/13. 10/8/13: PT CIBP @ 6,775' to 700 psig for 10". Tstd OK. Notified Brandon Powell w/NN am on 10/9/13. 10/9/13: . TIH w/2-3/8", 4.7#, 8rd, EUE tbg. SN@ 4,856. EOT 4,857. XTO.PT CIBP to attached chart. MV prefs fr/4,709'-4,933'. DK perfs fr/6,825'-7,035'. Paul Webe on loc 10/10/13: PWOPL. Drpd BHBS & dial pad plngr. RDMO Returned only the Mesaverde to Spud Date: Rig Release Date: Rig Release Date:	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15 '13 and 55' per the followin BIL CONS. DIV. DIST. 3 d for 1:00 pm on 10/7/13. It message w/Brandon Powell w/NMOCD for MOCD @ 3:30 pm on 10/8/13 fir MIT @ 9:00 to 570 psig for 30 min w/chart, please see to witness MIT tst. to production.
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations fr/6,825' – 7,0 10/3/13: MIRU 10/5/13: Set CIBP. Notified Charlie Perrin w/NMOCD @ 11:00 am for MIT test schedule 10/7/13: Realized CIBP was set @ 6,838'. Reset CIBP @ 6,775' & Set Pkr @ 6,740'. Let MIT test @ 9:00 am on 10/8/13. 10/8/13: PT CIBP @ 6,775' to 700 psig for 10". Tstd OK. Notified Brandon Powell w/NM am on 10/9/13. 10/9/13: . TIH w/2-3/8", 4.7#, 8rd, EUE tbg. SN@ 4,856. EOT 4,857. XTO.PT CIBP to attached chart. MV prefs fr/4,709'-4,933'. DK perfs fr/6,825'-7,035'. Paul Webe on loc 10/10/13: PWOPL. Drpd BHBS & dial pad plngr. RDMO Returned only the Mesaverde to Spud Date: Rig Release Date: Rig Release Date: Signature Herby certify that the information above is true and complete to the best of my knowledges of the start of the best of my knowledges. Signature Herby Certify that the information above is true and complete to the best of my knowledges.	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15 '13 35' per the followin OLCONS. DIV. DIST. 3 d for 1:00 pm on 10/7/13. It message w/Brandon Powell w/NMOCD for MOCD @ 3:30 pm on 10/8/13 fir MIT @ 9:00 to 570 psig for 30 min w/chart, please see to witness MIT tst. To production. DATE 10/11/13
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations ft/6,825' – 7,0 10/3/13: MIRU 10/5/13: Set CIBP. Notified Charlie Perrin w/NMOCD @ 11:00 am for MIT test schedule 10/7/13: Realized CIBP was set @ 6,838'. Reset CIBP @ 6,775' & Set Pkr @ 6,740'. Let MIT test @ 9:00 am on 10/8/13. 10/8/13: PT CIBP @ 6,775' to 700 psig for 10". Tstd OK. Notified Brandon Powell w/NN am on 10/9/13. 10/9/13: . TIH w/2-3/8", 4.7#, 8rd, EUE tbg. SN@ 4,856. EOT 4,857. XTO PT CIBP to attached chart. MV prefs ft/4,709'-4,933'. DK perfs ft/6,825'-7,035'. Paul Webe on loc 10/10/13: PWOPL. Drpd BHBS & dial pad plngr. RDMO Returned only the Mesaverde to Spud Date: Rig Release Date: Rig Release Date: Spud Date: Rig Release Date: Title Pagulator y Type or print name KRISTEN D, LYNCH E-mail address: Kristen lynch@xtoener	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15 '13 35' per the followin OLCONS. DIV. DIST. 3 d for 1:00 pm on 10/7/13. It message w/Brandon Powell w/NMOCD for MOCD @ 3:30 pm on 10/8/13 fir MIT @ 9:00 to 570 psig for 30 min w/chart, please see to witness MIT tst. To production. DATE 10/11/13
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations fr/6,825' – 7,0 10/3/13: MIRU 10/5/13: Set CIBP. Notified Charlie Perrin w/NMOCD @ 11:00 am for MIT test schedule 10/7/13: Realized CIBP was set @ 6,838'. Reset CIBP @ 6,775' & Set Pkr @ 6,740'. Let MIT test @ 9:00 am on 10/8/13. 10/8/13: PT CIBP @ 6,775' to 700 psig for 10". Tstd OK. Notified Brandon Powell w/NN am on 10/9/13. 10/9/13: . TIH w/2-3/8", 4.7#, 8rd, EUE tbg. SN@ 4,856. EOT 4,857. XTO PT CIBP to attached chart. MV prefs fr/4,709'-4,933'. DK perfs fr/6,825'-7,035'. Paul Wabbe on loc 10/10/13: PWOPL. Drpd BHBS & dial pad plngr. RDMO Returned only the Mesaverde to Spud Date: Rig Release Date: Rig Release Date: Type or print name KRISTEN D, LYNCH E-mail address: Kristen lynch@xtoener For State Use Only Deputy Oil & Gas 10.00.	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15 '13 35' per the followin OIL CONS. DIV. DIST. 3 d for 1:00 pm on 10/7/13. It message w/Brandon Powell w/NMOCD for MOCD @ 3:30 pm on 10/8/13 fir MIT @ 9:00 25 570 psig for 30 min w/chart, please see to witness MIT tst. To production. DATE 10 11 13 gy.com PHONE: (505)333-3206 Inspector,
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. XTO ENERGY, INC. has set a CIBP @ 6,775' above the DK perforations fr/6,825' – 7,0 10/3/13: MIRU 10/5/13: Set CIBP. Notified Charlie Perrin w/NMOCD @ 11:00 am for MIT test schedule 10/7/13: Realized CIBP was set @ 6,838'. Reset CIBP @ 6,775' & Set Pkr @ 6,740'. Let MIT test @ 9:00 am on 10/8/13. 10/8/13: PT CIBP @ 6,775' to 700 psig for 10". Tstd OK. Notified Brandon Powell w/NN am on 10/9/13. 10/9/13: . TIH w/2-3/8", 4.7#, 8rd, EUE tbg. SN@ 4,856. EOT 4,857. XTO PT CIBP to attached chart. MV prefs fr/4,709'-4,933'. DK perfs fr/6,825'-7,035'. Paul Wabbe on loc 10/10/13: PWOPL. Drpd BHBS & dial pad plngr. RDMO Returned only the Mesaverde to Spud Date: Rig Release Date: Rig Release Date: Signature Ariston Description of the best of my knowledge of print name KRISTEN D, LYNCH E-mail address: Kristen lynch@xtoener For State Use Only	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion RCVD OCT 15 '13 35' per the followin DIL CONS. DIV. DIST. 3 d for 1:00 pm on 10/7/13. It message w/Brandon Powell w/NMOCD for MOCD @ 3:30 pm on 10/8/13 fir MIT @ 9:00 25 570 psig for 30 min w/chart, please see to witness MIT tst. To production. DATE 10/11/13 gy.com PHONE: (505)333-3206 Inspector,

