Form 3160-5 (August 2007)

Subsequent Report

☐ Final Abandonment Notice

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM	APPROVED)
OMB N	VO. 1004-013	
Expires	: July 31, 201	

SUNDRY NOTICES	AND REPORTS	ON WELLS
Do not use this form for p	proposals to drill	or to re-enter an

Lease Serial No. NMSF078109

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name		
SUBMIT IN TR	IPLICATE - Other inst	ructions on reverse side.		7. If Unit or CA/Agre	ement, Name and/or No.
Type of Well Oil Well	ther			8. Well Name and No. GALLEGOS CAN	
Name of Operator BP AMERICA PRODUCTION	Contact N CO E-Mail: Toya.Co			9. API Well No. 30-045-07906-0)0-S1
3a. Address 200 ENERGY COURT FARMINGTON, NM 87401		3b. Phone No. (include area co Ph: 281-366-7148	de)	10. Field and Pool, or WEST KUTZ P	Exploratory ICTURED CLIFFS
4. Location of Well (Footage, Sec.,	T., R., M., or Survey Descript	ion)		11. County or Parish,	and State
Sec 28 T29N R12W NENE 1	016FNL 1016FEL			SAN JUAN CO	UNTY, NM
12. CHECK API	PROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, R	EPORT, OR OTHE	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
☐ Notice of Intent	☐ Acidize ☐ Alter Casing	□ Deepen □ Fracture Treat	☐ Produc	tion (Start/Resume)	☐ Water Shut-Off☐ Well Integrity

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

□ Plug Back

■ New Construction

□ Plug and Abandon

☐ Recomplete

☐ Water Disposal

☐ Temporarily Abandon

BP America would like to submit the operation summaries for the installation of a wellhead for monitoring the subject well.

□ Casing Repair

□ Change Plans

Convert to Injection

Please see attached summaries for September-October 2013.

RCVD OCT 21 '13 OIL CONS. DIV. DIST. 3

Other

14. I hereby certify that th	ne foregoing is true and correct. Electronic Submission #222684 verifie For BP AMERICA PRODUCTIO Committed to AFMSS for processing by ST	N ĆO,	sent to the Farmington	Ξ)	
Name (Printed/Typed)	TOYA COLVIN	Title	REGULATORY ANALYST		
Signature	(Electronic Submission)	Date	10/11/2013		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved By ACC	CEPTED		STEPHEN MASON PETROLEUM ENGINEER	Date 10/17/2013	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	⇒ Farmington		
	I and Title 43 U.S.C. Section 1212, make it a crime for any poor fraudulent statements or representations as to any matter w			artment or agency of the United	

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Operations for the GCU 69 - September- October 2013

September 2013

09/30/2013- ND DIVERTER & REMOVE WELL P&A MARKER AND INSTALL SLIP ON WELLHEAD, BEGIN PRESSURE MONITORING.

October 2013

10/01/2013- RE-TEST ALL WELLHEAD NUTS AND STUDS, RIG UP DAYLIGHTER AND BEGIN EXCAVATING AROUND WELLHEAD

10/02/2013- EXCAVATE AROUND WELLHEAD

10/03/2013- EXCAVATE AROUND WELLHEAD, REMOVE WELLHEAD AND CUT CASING , RE-INSTALL SLIP LOCK CSG HEAD, RIG UP AND TEST CSG & WELLHEAD- GOOD TESTS

10/04/2013- PUMP IN TEST IN SURFACE CASING, TEST CEMENT PLUG AND VALVES ON PRODUCTION CASING. CONTINUE TO MONITOR SURFACE AND PRODUCTION CASING PRESSURES.