Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

DEC 20 21 15 Lease Serial No. RCVD DEC 26 '13 SUNDRY NOTICES AND REPORTS ON WELLS NMNM-018463 II CONS DIU Do not use this form for proposals to drill or to re-enternanon Field Owe abandoned well. Use Form 3160-3 (APD) for such proposals no Mail 160 If Indian, Allottee or Tribe Name 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No. Chaco 2308-09A #145H Oil Well Gas Well Other 2. Name of Operator 9. API Well No. WPX Energy Production, LLC 30-045-35496 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area PO Box 640 Aztec, NM 87410 505-333-1808 Lybrook Gallup 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State SHL: 917' FNL & 240' FEL SEC 9 23N 8W San Juan County, NM BHL: 380' FNL & 230' FWL SEC 9 23N 8W 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent Alter Casing Fracture Treat Well Integrity Reclamation Other SPUD/SURFACE Casing Repair New Construction Recomplete Subsequent Report CASING Plug and Abandon Change Plans Temporarily Abandon Convert to Final Abandonment Plug Back Water Disposal Injection Notice 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) **NOTE: MO-TE SET SURFACE** 12/16/13- SPUD 12-1/4" HOLE @ 0815 HRS 🗸 12/17/13- TD 12-1/4" SURF HOLE @ 415', 1430 HRS. RAN 13 JTS, 9-5/8", LT&C, 36#, j-55, CSG SET @ 410', FC @ 375' Pump 10 bbls gel water, 5 bbls FW spacer, & 51.6 bbls Type G cmt (250 sxs) @ 15.8 PPG. Drop plug & disp w/ 29 bbls H2O. Bump plug @ 350 psi. Circ 25 bbls good cmt to surface. RDMO Mo-Te. NOTE: WPX will MI AWS # 980 to Install & test BOP at a later date. We will file another sundry at that time. 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Larry Higgins Permit Suprv 12/20/13 Signature Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Date Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject Office lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the

United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.