

FEB 21 2014

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

5. Lease Serial No.
NMSF-078360

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.
Chaco 2306-20M #208H

9. API Well No.
30-043-21170

10. Field and Pool or Exploratory Area
Lybrook Gallup

11. Country or Parish, State
Sandoval County, NM

1. Type of Well
 Oil Well Gas Well Other

2. Name of Operator
WPX Energy Production, LLC

3a. Address
PO Box 640 Aztec, NM 87410

3b. Phone No. (include area code)
505-333-1808

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
SHL: 485' FSL & 155' FWL SEC 20 23N 6W
BHL: 451' FSL & 231' FWL SEC 19 23N 6W

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Offlease Measurement
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	PCUN MAP 5 '14
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	OIL CONS. DIV.
				DIST. 3

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

WPX Energy requests authorization for offlease measurement of oil. The surface location for the well and associated facilities including oil tanks are located in Section 20, T23N, R6W, NMPM which is adjacent to the lease in which it is producing. The oil is collected via truck at this facility.

- No commingling of any other off-lease oil or gas will take place at this location

14. I hereby certify that the foregoing is true and correct.

Name (Printed/Typed)
Heather Riley

Title Regulatory Team Lead

Signature *Heather Riley* Date 2/20/2014

THIS SPACE FOR FEDERAL OR STATE OFFICE USE


Approved by *[Signature]* Title *Petr. Eng* Date *3/3/14*

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.





LYBROOK SOUTH 009

LYBROOK SOUTH 011

LYBROOK SOUTH 010

18

17

NMSF 0078359

GRACE FEDERAL 19 001

LYBROOK SOUTH 013

LYBROOK SOUTH 015

LYBROOK SOUTH 012

NMSF 0078360

LYBROOK SOUTH 014

19

LYBROOK SOUTH 016

EMILY 001

T23N R06W

NMNM 028740

CHAPMAN 001

Farmington Field Office

LU-LU 001

CHAPMAN A 001

30 NMNM 117564

LYBROOK B 001

LU-LU 002

LULU 005

NMNM 028741

LU-LU 003

LU-LU 004

QUINELLA 001 NMNM 058871

31

NMNM 089021

GUSY STATE 001

PINON FEDERAL

LYBROOK A32

33