Form 3160-5 (August 2007)

UNITED STATES -DEPARTMENT OF THE INTERIOR, BUREAU OF LAND MANAGEMENT

; ; ;,;	\ J	

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

5. Lease Serial No.

SF-047

WELLS

5. Lease Serial No.

SF-047

6. If Indian, Allottee or Tribe Name

SF-047020-A

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter and 💢
handoned well. Hee Form 2160-2 (APD) for euch proposale

	e this form for proposals			KUVU FEB 25 114	
abandoned	l well. Use Form 3160-3 (A	APD) for such propos	álsន ្រៀងជាក	ON COMS DIU	
SUBMIT IN TRIPLICATE - Other instructions on page 2.			7. If Unit of CA/Agre	7. If Unit of CA/Agreement, Name and/or No.	
1. Type of Well Oil Well Sas Well Other				DIST. A	
			8. Well Name and No	8. Well Name and No.	
				Congress 16	
2. Name of Operator			9. API Well No.	*	
Burling	gton Resources Oil & Gas	Company LP		30-045-25657	
3a. Address		3b. Phone No. (include area of	ode) 10. Field and Pool or	10. Field and Pool or Exploratory Area	
PO Box 4289, Farmingt	on, NM 87499	(505) 326-970	0	Gallup	
4. Location of Well (Footage, Sec., T.,)	R.,M., or Survey Description)	·	11. Country or Parish	, State	
Unit	A, 660' FNL & 660' FEL, S	Sec. 34, T29N, R11W	San Ju	an , New Mexico	
12. CHECK	THE APPROPRIATE BOX(ES)	TO INDICATE NATURE	OF NOTICE, REPORT O	R OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
X Notice of Intent	Acidize	Deepen	Production (Start/Resur	ne) Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	X Other	
	Change Plans	Plug and Abandon	Temporarily Abandon	Landfarm Removal	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

In response to a Bradenhead repair, 2,934 yards of soil containing river cobbles was transported from the Sategna #2 to the Congress 16 (36.6875, -107.97164) to "farm" in May of 2002. The following agreed upon plan is to rectify the "land farm" and restore the Congress 16 location.

Farmed material will be removed and used to build up the adjacent road from Way Point (UTM) 36.689833, -107.972831 (northwest edge of pipeline) to 36.685665, -107.969994 (crest of hill southeast), or until material is

The noxious weed Halogeton (presently in the soil) will be sprayed upon emergence and before it blooms, and will follow a minimum two-year weed management program both on location and distributed area.

After farmed material is removed, location will be reseeded with a native sage brush and grassland seed mix of BLM FFO's selection for the area.

Oco Accepted For Record

Field Environmental Specialist	
2/19/2014 Date	
OR STATE OFFICE USE	
Branch Chief FEB 2 4 2014	
Office	

false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction