IJ	SUNDRY Do not use the		TERIOR EMENT S ON WELLS AUG 21 2014 for such proposals.	FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996 5. Lease Serial No. 1-149-IND-7971 6. If Indian, Allottee or Tribe Name Navajo			
	SUBMIT IN TRIPL 1. Oil Well 🗓 Gas Well	ICATE – Other instru	ictions on reverse side	7. If Unit or CA/Agreement, Name and/or No. N/A 8. Well Name and No.			
	2. Name of Operator Elm Ridge Exploration Compa		Buena Suerte 28M #1 9. API Well No.				
P	3a. Address PO Box 156 Bloomfield, NM 8 4. Location of Well (Footage, Sec., T.,	87413 R., M., or Survey Description)	3b. Phone No. (include area code) 505-632-3476 ext. 201	30-045-28950 10. Field and Pool, or Exploratory Area Basin Fruitland Coal			
	790' FSL X 1210' FWL "M" Sec.28-T26N-R11W			11. County or Parish, State San Juan County, NM			
	12. CHECK APPROPRIATE BOX(I	ES) TO INDICATE NATURE TYPE OF ACTION	OF NOTICE, REPORT, OR OTHER DA	ATA			
	Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Production Fracture Treat Reclamation New Construction Recomplete Plug and Abandon Temporarily Plug Back Water Disp	Other			
13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days Following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) EIM Ridge Exploration Co., LLC requests permission to plug and abandon the following well according to the							
	Elm Ridge Exploration Co. attached procedure.	ng well according to the OIL CONS. DIV.					
	_		DV MEIG ADDO	DIST. 3			

SEE ATTACHED FOR SEE AT

Notify NMOCD 24 hrs prior to beginning operations

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS

AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS

14. I hereby certify that the foregoing is true and correct	
Name (Printed/Typed)	itle
Arthy Ardhuletta	Sr. Regulatory Supervisor
Signature D	August 18, 2014
THIS SPACE FOR F	EDERAL OR STATE USE
Approved by Trey Salvers	Title Petroleum Eng. Date 8 28 2014
Conditions of approval, if any, are attached. Approval of this notice does not warrant of certify that the applicant holds legal or equitable title to those rights in the subject least which would entitle the applicant to conduct operations thereon.	Office U

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)



Elm Ridge Resources

Pertinent Data Sheet

Well Name:

Buena Suerte 28M #1

Footage:

790' FSL and 1210' FWL

Location:

SWSW Section 28, T26N, R11W

County:

San Juan County, NM

API#:

30-045-28950

Field: Basin Fruitland Coal

Elevation: 6155' KB

TD: 1364' KB

Completed: 6/16/1993

Casing Record:

Hole Size	Casing Size	Wt.	Grade	Depth Set	Cement
8-3/4"	7"	20#	J-55	130'	94.4 cu. ft. (Circ. to surface)
6-1/4"	4-1/2"	9.5#	J-55	1359'	243 cu. ft. (Circ. to surface)

Tubing: 1-1/2" tubing set at 1239'

Formation Tops:

Nacimiento

Surface

Fruitland

1120'

Pictured Cliffs

1258'

Perforations:

Fruitland perforations: 1236'-1252'

Notes:

Wellbore Diagram Buena Suerte 28M #1 SWSW Sec. 28, T26N, R11W San Juan County, NM API #30-045-28950

Before

8-3/4" OH 7" 20# J-55 set @ 130' Circulated cmt to surface Nacimiento - surface Fruitland - 1120' 1-1/2" tbg set at 1239' Fruitland perforations: 1236'-1252' Pictured Cliffs - 1258' 6-1/4" OH 4-1/2" 9.5# J-55 set @ 1359' Circulated cmt to surface TD: 1364'

Wellbore Diagram Buena Suerte 28M #1 SWSW Sec. 28, T26N, R11W San Juan County, NM API #30-045-28950

After

Nacimiento - surface

8-3/4" OH 7" 20# J-55 set @ 130' Circulated cmt to surface

Fruitland - 1120'

Pictured Cliffs - 1258'

1-1/2" tbg set at 1239' Fruitland perforations: 1236'-1252'

6-1/4" OH 4-1/2" 9.5# J-55 set @ 1359' Circulated cmt to surface TD: 1364'

Buena Suerte Plugging Program for Bisti 28M #1

- 1) MOL RU. TOOH with 1-1/2" tubing.
- 2) PU and TIH with 4-1/2" retainer to 1235'. Squeeze below retainer with 10 sx cmt.
- 3) Sting out, mix and pump 100 sx, or sufficient volume, to bring cement to surface inside 4-1/2" casing.
- 4) Cut off well head 4 feet below surface and remediate location in accordance with regulatory agencies' conditions of approval.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of	
Intention to Abandon:	

Re: Permanent Abandonment Well: Buena Suerte 28M #1

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

Note: H2S has not been reported in this section; however, low concentrations of H2S (11-16 ppm GSV) have been reported in the NE/NE of section 27-26N-11W

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.