Form 3160-5 (November 19%)

#### UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

CASA	$\Lambda$	
PIAR	UJ	2915

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or reenter an-

5. Lease Serial No. **BIA #11** 6- If Indian Allottee or Tribe Name

abandoned well.	Jicarilla Apache Tribe					
SUBMIT IN TRIPL	ICATE – Other instru	ctions on reverse	side	7. If Unit or CA/Agreement, Name and/or No.		
1.  X Oil Well X Gas Well  2. Name of Operator Elm Ridge Exploration Compa	□ Other			8. Well Name and No. Jicarilla Apache B #15 9. API Well No.		
<ul> <li>3a. Address</li> <li>P.O. Box 156 Bloomfield, NM</li> <li>4. Location of Well (Footage, Sec., T.,</li> </ul>		3b. Phone No. (include a (505) 632-3476 ext.	,	30-039-21231 10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., Unit K, Section 30, T24N, R5V		Basin Mancos/Basin Dakota  11. County or Parish, State  Rio Arriba County, NM				
12. CHECK APPROPRIATE BOX(E	S) TO INDICATE NATURE	OF NOTICE, REPORT,	OR OTHER DA	ATA		
TYPE OF SUBMISSION	TYPE OF ACTION					
<ul> <li>Notice of Intent</li> <li>Subsequent Report</li> <li>Final Abandonment Notice</li> </ul>	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production () Reclamation Recomplete Temporarily Water Dispo	Abandon Other		
Atlach the Bond under which the work Following completion of the involved opportesting has been completed. Final Abdetermined that the site is ready for final inspection. Final Fin	or recomplete horizontally, give swill be performed or provide the first ations. If the operation results in indonment Notices shall be filed oction.)  C Plugged and Abandon Grandon Powell with the	ubsurface locations and measurements on file with BLM/E a multiple completion or recently after all requirements, included this well as follow DCD to run CBL from	red and true vertica BIA. Required subsompletion in a new cluding reclamation,  VS: 2-20-15: We not op of comp	Il depths of all pertinent markers and zones interval, a Form 3160-4 shall be filed once have been completed, and the operator has   IIRU. 2-24-15: Spoke with Bryce osite bridge plug @ 6250'		
to surface. They argreed this v						

150 sks of class G cement. Pumped a total of 134 sks below retainer and 13 sks on top of retainer. Plug one covered the Gallup and Dakota perforations from 6578' to 5261'. 2-27-15: PLUG #2 Set balanced plug from 4554' to 4454'. Pumped 25 sks of Class G cement. <u>3-2-15:</u> Tagged balance plug top at 4358'.**PLUG #3** Mixed 25 sks of cement and pumped a plug from 3764' to 3474'. Tagged top of cement at 3486' **PLUG #4** Pumped 30 sks of cement to cover Chacra from 3020' to 2860'. 3-4-15: Top of cement at 2780'. PLUG #5 Pumped 80 sks of cement to cover 2151' to 1522'. PLUG #6 Pumped 65 sks of cement from 420' to surface. Circulated cement to surface. Rig down and move off location. NOTE: All plugs were approved and inspected by Bryce Hammond with the Jicarilla BLM.√

	<u> </u>			
14. I hereby certify that the	foregoing is true and correct			
Name (Printed/Typed)	1 N N	Title		
	Amy Archuleta\	S	r. Regulatory Supervisor	
Signature	$\Lambda M \sim$	Date	March 9, 2015	
	/ \ / \ THIS S	PACE FOR FEDERAL OR STATE US	E	
Approved by	<i>()</i>	Title	Date	
certify that the applicant hold	, are attached. Approval of this notice do s legal or equitable title to those rights in cant to conduct operations thereon.			
Title 18 U.S.C. Section 1001	, makes it a crime for any person know	ingly and willfully to make to any departm	ent or agency of the United States any false, fictitious	or

fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

OIL CONS. DIV DIST. 3

MAR 3.0 2015

Approved as to plugging of the well bore. Liability under bond is retained until surface restoration is completed.

MMOCDA

ACCEPTED FOR RECORD

FARMINGTON FIELD OFFICE

### HALLIBURTON

# Cementing Job Summary

Sold To #: 3	302056		Rh!	ישו מו	2852551		KOUA	te #:		59	les Ume	#: N9N	2171565
Customer:		GE FY							p: MONTY				
Vell Name:				<del></del>		#: 1		tomor ita		API/UWI #		-21231-	<u></u>
ield:	JIOAN				ARILLA			ish: RIO			te: NEW		
				HE NATI			Juntymai	isii. NO			106. (41.7)	IVILATO	
egal Desc		•				-							
ontractor:						Rig/F	'latform I	Name/Nun	n: Workove	er			
ob BOM: 7													
Vell Type:													
ales Perso						Srve	Supervis	or: Rickey	/ Johnson				
	· Sim a		<u> </u>	. <u> </u>	to a market when the		Job	م مادا م	endo per vives metidos e discu		ير والمستقورين	. t. Substitute e sur e	and the same same same
ormation N	ame		<u> </u>										
ormation D	epth (ME	))	Тор	<del></del>			Bottom						
orm Type							BHST						
ob depth M	D		4700ft				Job Depti	1 TVD			****		
Vater Depth							Wk Ht Ab						
erforation i		D)	From				То	· · · · · · · · · · · · · · · · · · ·					
· · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·				·	Well Dat						
Descripti	lon	New / L	lead	Size	ID 1	Weight		a hread	Grade	Top MC	Botton	Тор	Bottor
Descripti		14044 / (	Deca	in	in	ibm/ft	`  '`	illeau	Grade	ft	MD	TVD	TVD
				1							ft	ft	l ft
				-	0.000								
				7 2.375	6.366 1.995	23 4.6 Tools	and Acce	essories		0 0	4700 4700		4 4
ubing	Siz	æ	Qty		1.995 Depth	4.6 Tools	and Acce	essories	Туре	Siz	4700 ze	Qty	Make
ubing Type	Siz	<b>2e</b>		2.375	1.995 Depth	4.6 Tools	and Acce		Туре	Siz in	4700	Qty	
Type	<b>Siz</b> in 2.3	75		2.375	1.995 Depth	4.6 Tools	and Acce		Type op Plug	9iz	4700	Qty	HES
Type ulde Shoe	Siz in 2.3 2.3	75 75		2.375	1.995 Depth	4.6 Tools	and Acce	T	Type op Plug ottom Plug	Siz in 2.3 2.3	4700 2 <b>e</b>   75   75	Qty	HES HES
Type ulde Shoe loat Shoe loat Collar	Siz in 2.3 2.3 2.3	75 75 75		2.375	1.995 Depth	4.6 Tools	and Acce	T	Type op Plug ottom Plug SR plug se	Siz in 2.3 2.3 t 2.3	4700 26 75 75 75	Qty	HES HES HES
Type ulde Shoe loat Shoe loat Collar sert Float	Siz in 2.3 2.3	75 75 75 75		2.375	1.995 Depth	4.6 Tools	and Acce	T B S S	Type op Plug ottom Plug	Siz in 2.3 2.3 t 2.3	4700 26 75 75 75 75 75	Qty	HES HES
Type ulde Shoe loat Shoe loat Collar sert Float	Siz in 2.3 2.3 2.3 2.3	75 75 75 75		2.375	1.995 Depth ft 4700	4.6		I B	Type op Plug ottom Plug SR plug.se lug Contair	Siz in 2.3 2.3 t 2.3 te 2.3	4700 26 75 75 75 75 75	Qty	HES HES HES
Type juide Shoe loat Shoe loat Collar asert Float tage Tool	Siz in 2.3 2.3 2.3 2.3	75 75 75 75	Qty	Make	1.995 Depth ft 4700	4.6 Toolš	aneous A	I I B S S C C C	Type op Plug ottom Plug SR plug se lug Contair entralizers	Siz in 2.3 2.3 t 2.3 2.3 2.3	75 75 75 75 75 75 75 75 75 75 75 75 75 7	3	HES HES HES HES
Type suide Shoe loat Shoe loat Collar sert Float tage Tool	Siz in 2.3 2.3 2.3 2.3 2.3	75 75 75 75	Qty	Make	1.995   Depth   ft   4700	4.6 Tools	aneous A	II B S P C Materials Conc	Type op Plug ottom Plug SR plug ser lug Contair entralizers	Siz in 2.3 2.3 t 2.3 2.3 2.3 2.3	4700 26 75 75 75 75 75	ty	HES HES HES HES
Type Sulde Shoe loat Shoe loat Collar nsert Float tage Tool	Siz in 2.3 2.3 2.3 2.3 2.3	75 75 75 75	Qty	Make	1.995 Depth ft 4700	4.6 Tools	aneous A	I I B S S C C C	Type op Plug ottom Plug SR plug ser lug Contair entralizers	Siz in 2.3 2.3 t 2.3 2.3 2.3	4700 26 75 75 75 75 75	3	HES HES HES HES
Type suide Shoe loat Shoe loat Collar sert Float tage Tool	Siz in 2.3 2.3 2.3 2.3 2.3	75 75 75 75	Qty	Make	1.995   Depth   ft   4700	Tools	aneous A	Aaterials Conc	Type op Plug ottom Plug SR plug ser lug Contair entralizers	Siz in 2.3 2.3 t 2.3 2.3 2.3 2.3	4700 26 75 75 75 75 75	ty	HES HES HES HES
78.4.	Siz in 2.3 2.3 2.3 2.3 2.3	75 75 75 75	Qty	Make	1.995   Depth   ft   4700	Tools	aneous A	Aaterials Conc	Type op Plug ottom Plug SR plug ser lug Contair entralizers	Siz in 2.3 2.3 t 2.3 2.3 2.3 2.3	4700 26 75 75 75 75 75	ty	HES HES HES HES
Type Juide Shoe Joat Shoe Joat Collar Insert Float Itage Tool Jelling Agt Treatment Float Treatment Float	Siz in 2.3 2.3 2.3 2.3 2.3	75 75 75 75 75 75	Qty	Make	Depth ft 4700	Tools	aneous A	Aaterials Conc Conc	Type op Plug ottom Plug SR plug se lug Contair entralizers Acid	Siz in 2.3 2.3 t 2.3 t 2.3 Type	75 75 75 75 75 8 8 8 8	ty	HES HES HES HES Cone
Type Juide Shoe Joat Shoe Joat Collar Sert Float tage Tool Jelling Agt	Siz in 2.3 2.3 2.3 2.3 2.3	75 75 75 75 75 75	Qty	Make	Depth ft 4700	Tools	aneous A	Aaterials Conc	Type  op Plug  ottom Plug  SR plug se  lug Contair  entralizers  Acid  Sand	0	75 75 75 75 75 75 8 8	ty	HES HES HES HES
Type ulde Shoe loat Shoe loat Collar isert Float tage Tool elling Agt reatment Float	Siz in 2.3 2.3 2.3 2.3 2.3	75 75 75 75 75 75	Qty	Make	Depth ft 4700	Tools	aneous A	Aaterials Conc Conc	Type op Plug ottom Plug SR plug se lug Contair entralizers Acid	0	75 75 75 75 75 75 8 8	ty	HES HES HES HES Conc Qty
Type uide Shoe loat Shoe loat Collar isert Float tage Tool eilling Agt reatment Fi	Siz in 2.3 2.3 2.3 2.3 2.3	75 75 75 75 75 75 75	Con	Make  C C Fluid N	Depth ft 4700	Tools, Miscell actant oltor	aneous A	Aaterials Conc Conc	Type  op Plug ottom Plug SR plug ser lug Contair entralizers Acid Sanc	0	75 75 75 75 75 75 75 75 75 75 8	ty	HES HES HES HES Conc Qty
Type Juide Shoe Joat Shoe Joat Collar Sert Float Joage Tool Joannelling Agt Teatment Float  Tage/Plug  Fluid #	Siz   in   2.3   2.3   2.3   2.3   2.3	75 75 75 75 75 75 75	Con	Make  C C Fluid N	Depth ft 4700	Tools, Miscell actant oltor	aneous A	Aaterials Conc Conc	Type  op Plug  ottom Plug SR plug ser  lug Contair entralizers  Acid Sand  Mixing Density Ibm/gal	0	75	ty   ze   Rate   bl/mi   n	HES HES HES HES Cone Qty Total Mix Fluid Gal
Type Juide Shoe Joat Shoe Joat Collar Sert Float Joage Tool Joannelling Agt Teatment Float  Tage/Plug  Fluid #	#: 1 Stage	75 75 75 75 75 75 75 1	Con	Make  C C C Fluid N	Depth ft 4700	Tools, Miscell actant oltor	aneous A	Aaterials Conc Conc	Type  op Plug  ottom Plug SR plug se  lug Contair entralizers  Acid Sand  Mixing Density   lbm/gal   15.8	0	### 4700  ### 47	ty   ze   Rate   bl/mi   n	HES HES HES HES Cone Qty Total Mix Fluid Gal
Type uide Shoe loat Shoe loat Collar sert Float tage Tool eiling Agt reatment Fl	#: 1 Stage	75 75 75 75 75 75 75 1	Con	Make  C C C Fluid N	Depth ft 4700	Alscell actant bitor	aneous A Fluid Dat  Qty  80	Aaterials Conc Conc a Qty UoM sack	Type  op Plug  ottom Plug SR plug se  lug Contair entralizers  Acid Sand  Mixing Density   lbm/gal   15.8	0	### 4700  ### 47	Rate bl/mi n 1.5	HES HES HES HES Cone Qty Total Mix Fluid Gal
Type  uide Shoe loat Shoe loat Collar sert Float tage Tool  elling Agt reatment Fl  tage/Plug  Fluid #	Siz   in   2.3   2.3   2.3   2.3   2.3	75 75 75 75 75 75 75 1	Con	Make  C C C Fluid N	Depth ft 4700	Alscell actant bitor	aneous A	Aaterials Conc Conc a Qty UoM sack	Type  op Plug  ottom Plug SR plug se  lug Contair entralizers  Acid Sand  Mixing Density   lbm/gal   15.8	0	### 4700  ### 47	ty   ze   Rate   bl/mi   n   1.5   oe Joint	HES HES HES HES Cone Qty Total Mix Fluid Gal

### HALLIBURTON

## Cementing Job Summary

Fluid #	Stage Type		Fluid Name	Qty	Qty UoM	Mixing Density Ibm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/mi n	Total Mix Fluid Gal	
1	Plug 2	PLUG	CEM (TM) SYSTEM	63	sack	15.8	1.16	5.11	1.5	7.6	
4	.99 Gal				FRESH W	ATER					
	Left In Pipe	Amount	A		Reason	·- · · · · · · · · · · · · · · · · · ·			Shoe Join		
Cement	Lett in Pipe	Amount	<u>  π                                   </u>		Reason			<del></del>	Silve Join	<u> </u>	
·		·		Fluid Dat	a						
Stage/Plu	g #: 3				<del></del>				<del>alangan ji neg</del>	<del></del>	
Cement	Left in Pipe	Amount	ft.	<u></u>	Reason	- ***			Shoe Join	t	
				Fluid Dat	'a						
Stage/Plu	g #: 4				····						
Fluid#	Stage Type		Fluid Name		Qty UoM	Mixing Density Ibm/gai	Yield ft3/sack	Mix Fluid Gal	Rate bbl/mi n	Total Mix Fluid Gai	
1	Plugcem	PLUG	CEM (TM) SYSTEM	30	sack	15.8	1.16	5.11	2		
5	.07 Gal				FRESH W	ATER			<u> </u>		
Fluid #	Stage Type	•	Fluid Name	Qty	Qty UoM	Mixing Density ibm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/mi n	Total Mix Fluid Gal	
2	Squeeze	Р	remium Cement	143	sack	15.8	1.16	5.11	2		
4	.97 Gal			FRESH WATER							
	94 lbm		CMT - PREM					<b>(1000</b>	03685)		
	0.20 %			HALAC	(R)-9, 50 L	B (10000	1617)	,			
Cement	Left In Pipe	Amount	lft.	<u>*                                    </u>	Reason		<del></del>	<u> </u>	Shoe Join	<u> </u>	
	Mix Water:		Mix Water Chloride:		1.000011	Mix W	ater Temp			•	
Cement Temperature:## °F °C		## °F °C	Plug Displaced by:		g/m3 XXXX	D	isp. Temp	erature:	## °F °C		
Cemen	Plug Bumped?Yes/No			Bump Pressure:#### psi MPa			Floats Held?Yes/No				
	Plug Bumped? ment Returns:		Bump Pressure: Returns Density:				Float Irns Temp				

#### HALLIBURTON



### Summary Report

	•		Sales Order #:	0902171565
Crew:			WO #:	0902171565
	2/48045		PO/AFE #:	NA
Job Start Date:	3/4/2015			

**Customer:** 

**ELM RIDGE EXPLORATION CO** 

LLC - EBUS

The Information Stated Herein Is Correct

UWI / API Number: 30-039-21231-00

Well Name:

Remarks:

JICARILLA APACHE B

Well No:

15

Field:

County/Parish:

**RIO ARRIBA** 

State:

**NEW MEXICO** 

Latitude:

36.281002

Longitude:

-107.405281

Sect / Twn / Rng: //

Customer Representative Signature

**Customer Representative Printed Name** 

Job Type:

Cust Rep Name:

Cust Rep Phone #:

**CMT PLUG TO** 

**ABANDON BOM** 

Service Supervisor: Rickey Johnson

5053301916

MONTY STRIEGEL

Date