

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED  
OMB No. 1004-0137  
Expires: October 31, 2014**SUNDRY NOTICES AND REPORTS ON WELLS**  
**Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.**5. Lease Serial No.  
See Attached - Exhibit 'A'  
6. Indian, Allottee or Tribe Name  
N/A

SUBMIT IN TRIPLICATE - Other instructions on page 2.

## 1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other2. Name of Operator  
Encana Oil & Gas (USA) Inc.3a. Address  
370 17th Street, Suite 1700 Denver, CO 802023b. Phone No. (include area code)  
720-876-59944. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
See Attached - Exhibit A7. If Unit of CA/Agreement, Name and/or No.  
See Attached - Exhibit 'A'8. Well Name and No.  
See Attached - Exhibit 'A'9. API Well No.  
See Attached - Exhibit 'A' 30-045-3563810. Field and Pool or Exploratory Area  
See Attached - Exhibit 'A'11. County or Parish, State  
See Attached - Exhibit 'A'

## 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

| TYPE OF SUBMISSION                                    | TYPE OF ACTION                                   |                                           |                                                    |                                                            |
|-------------------------------------------------------|--------------------------------------------------|-------------------------------------------|----------------------------------------------------|------------------------------------------------------------|
| <input type="checkbox"/> Notice of Intent             | <input type="checkbox"/> Acidize                 | <input type="checkbox"/> Deepen           | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off                    |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Alter Casing            | <input type="checkbox"/> Fracture Treat   | <input type="checkbox"/> Reclamation               | <input type="checkbox"/> Well Integrity                    |
| <input type="checkbox"/> Final Abandonment Notice     | <input type="checkbox"/> Casing Repair           | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete                | <input checked="" type="checkbox"/> Other Well Name Change |
|                                                       | <input checked="" type="checkbox"/> Change Plans | <input type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon       | on C-102                                                   |
|                                                       | <input type="checkbox"/> Convert to Injection    | <input type="checkbox"/> Plug Back        | <input type="checkbox"/> Water Disposal            |                                                            |

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Encana Oil & Gas (USA) Inc. submits revised C-102s for the wells detailed on the attached Exhibit 'A' to reflect revised well naming for proposed unit wells. Encana has developed a new naming convention for unit wells to reflect current OCD requirements. The attached Exhibit 'A' provides the prior well name, along with the new well name based on current OCD standards.

OIL CONS. DIV DIST. 3

JUN 04 2015

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Shawn Turk

Title Regulatory Analyst

Signature

Date 05/21/2015

## THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by


Title

Office

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any Department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)



AV

3

Exhibit 'A'

| Well Name                      | New Name for OCD Naming Conventions | API Well No. | Status of Permit         | SHL Location                              | BHL Location                               | Pool                     | Lease Serial No. | Unit No.     | County     |
|--------------------------------|-------------------------------------|--------------|--------------------------|-------------------------------------------|--------------------------------------------|--------------------------|------------------|--------------|------------|
| Gallo Canyon Unit P14-2306-01H | Gallo Canyon Unit 001H              | 30-039-31264 | Approved But Not Drilled | 49' FSL, 690' FEL<br>Sec. 14, T23N, R6W   | 1700' FNL, 330' FEL<br>Sec. 25, T23N, R6W  | Counselors Gallup-Dakota | NMNM 17009       | NMNM 131017X | Rio Arriba |
| Gallo Canyon Unit P14-2306-02H | Gallo Canyon Unit 002H              | 30-039-31265 | Approved But Not Drilled | 49' FSL, 660' FEL<br>Sec. 14, T23N, R6W   | 40' FNL, 330' FEL<br>Sec. 25, T23N, R6W    | Counselors Gallup-Dakota | NMNM 17009       | NMNM 131017X | Rio Arriba |
| Gallo Canyon Unit P14-2306-03H | Gallo Canyon Unit 003H              | 30-039-31266 | Approved But Not Drilled | 50' FSL, 630' FEL<br>Sec. 14, T23N, R6W   | 2250' FSL, 330' FEL<br>Sec. 24, T23N, R6W  | Counselors Gallup-Dakota | NMNM 17009       | NMNM 131017X | Rio Arriba |
| Gallo Canyon Unit M14-2306-01H | Gallo Canyon Unit 004H              | 30-039-31306 | Approved But Not Drilled | 51' FSL, 1279' FWL<br>Sec. 14, T23N, R6W  | 515' FSL, 990' FWL<br>Sec. 24, T23N, R6W   | Counselors Gallup-Dakota | NMNM 17009       | NMNM 131017X | Rio Arriba |
| Gallo Canyon Unit O15-2306-01H | Gallo Canyon Unit 005H              | 30-039-31271 | Approved But Not Drilled | 496' FSL, 2008' FEL<br>Sec. 15, T23N, R6W | 1050' FSL, 2320' FWL<br>Sec. 23, T23N, R6W | Counselors Gallup-Dakota | NMNM 17009       | NMNM 131017X | Rio Arriba |
| Gallo Canyon Unit O15-2306-02H | Gallo Canyon Unit 006H              | 30-039-31269 | Approved But Not Drilled | 516' FSL, 2029' FEL<br>Sec. 15, T23N, R6W | 345' FNL, 115' FWL<br>Sec. 25, T23N, R6W   | Counselors Gallup-Dakota | NMNM 17009       | NMNM 131017X | Rio Arriba |
| Gallo Canyon Unit M15-2306-01H | Gallo Canyon Unit 007H              | 30-039-31270 | Approved But Not Drilled | 231' FSL, 555' FWL<br>Sec. 15, T23N, R6W  | 330' FSL, 450' FEL<br>Sec. 22, T23N, R6W   | Counselors Gallup-Dakota | NMNM 17009       | NMNM 131017X | Rio Arriba |
| Gallo Canyon Unit M15-2306-02H | Gallo Canyon Unit 008H              | 30-039-31276 | Approved But Not Drilled | 210' FSL, 576' FWL<br>Sec. 15, T23N, R6W  | 175' FSL, 1420' FWL<br>Sec. 23, T23N, R6W  | Counselors Gallup-Dakota | NMNM 17009       | NMNM 131017X | Rio Arriba |
| Gallo Canyon Unit M24-2306-01H | Gallo Canyon Unit 101H              | TBD          | In Permitting Queue      | 140' FSL, 305' FWL<br>Sec. 24, T23N, R6W  | 180' FSL, 330' FEL<br>Sec. 25, T23N, R6W   | Counselors Gallup-Dakota | NMNM 17009       | NMNM 131017X | Sandoval   |
| Gallo Canyon Unit M24-2306-02H | Gallo Canyon Unit 102H              | TBD          | In Permitting Queue      | 113' FSL, 320' FWL<br>Sec. 24, T23N, R6W  | 1885' FSL, 330' FEL<br>Sec. 25, T23N, R6W  | Counselors Gallup-Dakota | NMNM 17009       | NMNM 131017X | Sandoval   |
| Gallo Canyon Unit N23-2306-01H | Gallo Canyon Unit 103H              | TBD          | In Permitting Queue      | 913' FSL, 1861' FWL<br>Sec. 23, T23N, R6W | 1000' FSL, 610' FWL<br>Sec. 25, T23N, R6W  | Counselors Gallup-Dakota | NMNM 17009       | NMNM 131017X | Sandoval   |
| Gallo Canyon Unit N23-2306-02H | Gallo Canyon Unit 104H              | TBD          | In Permitting Queue      | 927' FSL, 1887' FWL<br>Sec. 23, T23N, R6W | 1875' FSL, 1500' FWL<br>Sec. 25, T23N, R6W | Counselors Gallup-Dakota | NMNM 17009       | NMNM 131017X | Sandoval   |
| Gallo Canyon Unit M23-2306-02H | Gallo Canyon Unit 105H              | TBD          | In Permitting Queue      | 656' FSL, 547' FWL<br>Sec. 23, T23N, R6W  | 310' FSL, 480' FEL<br>Sec. 26, T23N, R6W   | Counselors Gallup-Dakota | NMNM 117564      | NMNM 131017X | Sandoval   |
| Gallo Canyon Unit D22-2306-03H | Gallo Canyon Unit 106H              | TBD          | In Permitting Queue      | 1045' FNL, 649' FWL<br>Sec. 22, T23N, R6W | 330' FSL, 2380' FEL<br>Sec. 22, T23N, R6W  | Counselors Gallup-Dakota | NMNM 17009       | NMNM 131017X | Sandoval   |
| Gallo Canyon Unit L25-2306-01H | Gallo Canyon Unit 201H              | TBD          | In Permitting Queue      | 1427' FSL, 655' FWL<br>Sec. 25, T23N, R6W | 2040' FSL, 330' FEL<br>Sec. 36, T23N, R6W  | Counselors Gallup-Dakota | V09212           | NMNM 131017X | Sandoval   |
| Gallo Canyon Unit L25-2306-02H | Gallo Canyon Unit 202H              | TBD          | In Permitting Queue      | 1457' FSL, 650' FWL<br>Sec. 25, T23N, R6W | 1550' FNL, 330' FEL<br>Sec. 36, T23N, R6W  | Counselors Gallup-Dakota | V09212           | NMNM 131017X | Sandoval   |
| Gallo Canyon Unit P26-2306-01H | Gallo Canyon Unit 203H              | 30-043-21207 | Active                   | 249' FSL, 969' FEL<br>Sec. 26, T23N, R6W  | 279' FSL, 2537' FEL<br>Sec. 36, T23N, R6W  | Counselors Gallup-Dakota | V0 9212          | NMNM 131017X | Sandoval   |
| Gallo Canyon Unit P26-2306-02H | Gallo Canyon Unit 204H              | 30-043-21209 | Active                   | 253' FSL, 939' FEL<br>Sec. 26, T23N, R6W  | 339' FSL, 384' FEL<br>Sec. 36, T23N, R6W   | Counselors Gallup-Dakota | NMNM 17009       | NMNM 131017X | Sandoval   |
| Gallo Canyon Unit E26-2306-03H | Gallo Canyon Unit 205H              | TBD          | In Permitting Queue      | 1991' FNL, 850' FWL<br>Sec. 26, T23N, R6W | 680' FNL, 1570' FEL<br>Sec. 35, T23N, R6W  | Counselors Gallup-Dakota | NMNM 118128      | NMNM 131017X | Sandoval   |
| Gallo Canyon Unit M26-2306-01H | Gallo Canyon Unit 206H              | 30-043-21205 | Active                   | 75' FSL, 200' FWL<br>Sec. 26, T23N, 6W    | 328' FSL, 691' FWL<br>Sec. 36, T23N, R6W   | Counselors Gallup-Dakota | V0 9212          | NMNM 131017X | Sandoval   |
| Gallo Canyon Unit O27-2306-01H | Gallo Canyon Unit 207H              | 30-043-21206 | Active                   | 24' FSL, 2042' FEL<br>Sec. 27, T23N, R6W  | 346' FSL, 2520' FWL<br>Sec. 35, T23N, R6W  | Counselors Gallup-Dakota | NMNM 118128      | NMNM 131017X | Sandoval   |
| Gallo Canyon Unit O27-2306-02H | Gallo Canyon Unit 208H              | 30-043-21208 | Active                   | 29' FSL, 2012' FEL<br>Sec. 27, T23N, R6W  | 307' FSL, 1054' FEL<br>Sec. 35, T23N, R6W  | Counselors Gallup-Dakota | NMNM 118128      | NMNM 131017X | Sandoval   |
| Gallo Canyon Unit M27-2306-01H | Gallo Canyon Unit 209H              | 30-043-21179 | Active                   | 990' FSL, 186' FWL<br>Sec. 27, T23N, R6W  | 359' FSL, 324' FWL<br>Sec. 35, T23N, R6W   | Counselors Gallup-Dakota | NMNM 118128      | NMNM 131017X | Sandoval   |
| Gallo Canyon Unit H33-2306-01H | Gallo Canyon Unit 301H              | 30-043-21233 | Active                   | 1466' FNL, 60' FEL<br>Sec. 33, T23N, R6W  | 349' FSL, 2252' FEL<br>Sec. 34, T23N, R6W  | Counselors Gallup-Dakota | NMNM 118128      | NMNM 131017X | Sandoval   |
| Nageezi Unit L27-2409-01H      | Nageezi Unit 219H                   | 30-045-35478 | Active                   | 2399' FSL, 333' FWL<br>Sec. 27, T24N, R9W | 2395' FNL, 349' FWL<br>Sec. 28, T24N, R9W  | Nageezi Unit HZ (Oil)    | NMNM 12374       | NMNM 132918X | San Juan   |
| Nageezi Unit L27-2409-02H      | Nageezi Unit 220H                   | 30-045-35481 | Active                   | 2369' FSL, 332' FWL<br>Sec. 27, T24N, R9W | 2404' FSL, 344' FWL<br>Sec. 28, T24N, R9W  | Nageezi Unit HZ (Oil)    | NMNM 12374       | NMNM 132918X | San Juan   |

Exhibit 'A'

| Well Name                           | New Name for OCD Naming Conventions | API Well No. | Status of Permit         | SHL Location                               | BHL Location                               | Pool                  | Lease Serial No.         | Unit No.     | County   |
|-------------------------------------|-------------------------------------|--------------|--------------------------|--------------------------------------------|--------------------------------------------|-----------------------|--------------------------|--------------|----------|
| Nageezi Unit M27-2409-01H           | Nageezi Unit 222H                   | 30-045-35480 | Active                   | 1282' FSL, 383' FWL<br>Sec. 27, T24N, R9W  | 1809' FSL, 345' FWL<br>Sec. 28, T24N, R9W  | Nageezi Unit HZ (Oil) | NMNM 12374               | NMNM 132918X | San Juan |
| Nageezi Unit M27-2409-02H           | Nageezi Unit 223H                   | 30-045-35479 | Active                   | 1255' FSL, 371' FWL<br>Sec. 27, T24N, R9W  | 852' FSL, 345' FWL<br>Sec. 28, T24N, R9W   | Nageezi Unit HZ (Oil) | NMNM 12374               | NMNM 132918X | San Juan |
| Nageezi Unit A28-2409-01H           | Nageezi Unit 226H                   | 30-045-35558 | Approved But Not Drilled | 1223' FNL, 346' FEL<br>Sec. 28, T24N, R9W  | 1360' FNL, 330' FWL<br>Sec. 28, T24N, R9W  | Nageezi Unit HZ (Oil) | NMNM 12374               | NMNM 132918X | San Juan |
| Nageezi Unit A28-2409-02H           | Nageezi Unit 227H                   | 30-045-35557 | Approved But Not Drilled | 1234' FNL, 318' FEL<br>Sec. 28, T24N, R9W  | 1860' FNL, 330' FWL<br>Sec. 28, T24N, R9W  | Nageezi Unit HZ (Oil) | NMNM 12374               | NMNM 132918X | San Juan |
| Nageezi Unit D34-2409-01H           | Nageezi Unit 320H                   | 30-045-35440 | Active                   | 1109' FNL, 509' FWL<br>Sec. 34, T24N, R9W  | 585' FNL, 349' FWL<br>Sec. 33, T24N, R9W   | Nageezi Unit HZ (Oil) | NMNM 12374<br>NMNM 90843 | NMNM 132918X | San Juan |
| Nageezi Unit D34-2409Y-03H          | Nageezi Unit 321H                   | 30-045-35583 | Active                   | 1136' FNL, 523' FWL<br>Sec. 34, T24N, R9W  | 1895' FNL, 345' FWL<br>Sec. 33, T24N, R9W  | Nageezi Unit HZ (Oil) | NMNM 90843               | NMNM 132918X | San Juan |
| Nageezi Unit L10-2309-01H           | Nageezi Unit 503H                   | TBD          | In Permitting Queue      | 1455' FSL, 288' FWL<br>Sec. 10, T23N, R9W  | 1750' FSL, 330' FWL<br>Sec. 9, T23N, R9W   | Nageezi Unit HZ (Oil) | NMNM 8005                | NMNM 132918X | San Juan |
| Nageezi Unit L10-2309-02H (FKA 03H) | Nageezi Unit 504H                   | TBD          | In Permitting Queue      | 1426' FSL, 296' FWL<br>Sec. 10, T23N, R9W  | 430' FSL, 330' FWL<br>Sec. 9, T23N, R9W    | Nageezi Unit HZ (Oil) | NMNM 8005                | NMNM 132918X | San Juan |
| Pinon Unit M03-2410-01H             | Pinon Unit 101H                     | 30-045-35560 | Approved But Not Drilled | 235' FSL, 1232' FWL<br>Sec. 3, T24N, R10W  | 410' FSL, 485' FEL<br>Sec. 10, T24N, R10W  | Pinon Unit HZ (Oil)   | NMNM 104606              | NMNM 133841X | San Juan |
| Pinon Unit M03-2410-02H             | Pinon Unit 102H                     | 30-045-36529 | Approved But Not Drilled | 226' FSL, 1261' FWL<br>Sec. 3, T24N, R10W  | 2360' FNL, 330' FEL<br>Sec. 10, T24N, R10W | Pinon Unit HZ (Oil)   | NMNM 104606              | NMNM 133841X | San Juan |
| Pinon Unit D14-2410-01H             | Pinon Unit 301H                     | 30-045-35493 | Active                   | 1321' FNL, 449' FWL<br>Sec. 14, T24N, R10W | 928' FNL, 1576' FEL<br>Sec. 16, T24N, R10W | Pinon Unit HZ (Oil)   | NMNM 100807              | NMNM 133841X | San Juan |
| Pinon Unit D14-2410-02H             | Pinon Unit 302H                     | 30-045-35530 | Active                   | 1348' FNL, 436' FWL<br>Sec. 14, T24N, R10W | 2228' FNL, 292' FEL<br>Sec. 16, T24N, R10W | Pinon Unit HZ (Oil)   | NMNM 100807              | NMNM 133841X | San Juan |
| Pinon Unit M16-2410-01H             | Pinon Unit 303H                     | 30-045-35635 | Approved But Not Drilled | 1278' FSL, 228' FWL<br>Sec. 16, T24N, R10W | 260' FSL, 120' FWL<br>Sec. 8, T24N, R10W   | Pinon Unit HZ (Oil)   | NOG 99111367             | NMNM 133841X | San Juan |
| Pinon Unit M16-2410-02H             | Pinon Unit 304H                     | 30-045-35636 | Approved But Not Drilled | 1278' FSL, 258' FWL<br>Sec. 16, T24N, R10W | 1730' FSL, 1210' FWL<br>Sec. 8, T24N, R10W | Pinon Unit HZ (Oil)   | NOG 99111367             | NMNM 133841X | San Juan |
| Pinon Unit M16-2410-03H             | Pinon Unit 305H                     | 30-045-35637 | Approved But Not Drilled | 1277' FSL, 288' FWL<br>Sec. 16, T24N, R10W | 705' FSL, 320' FEL<br>Sec. 21, T24N, R10W  | Pinon Unit HZ (Oil)   | NOG 01011426             | NMNM 133841X | San Juan |
| Pinon Unit M16-2410-04H             | Pinon Unit 306H                     | 30-045-35638 | Approved But Not Drilled | 1277' FSL, 318' FWL<br>Sec. 16, T24N, R10W | 2225' FNL, 325' FEL<br>Sec. 21, T24N, R9W  | Pinon Unit HZ (Oil)   | NOG 01011426             | NMNM 133841X | San Juan |